MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. _____
T.C. NO. 15098
MAP DATE po 215-092-08
DATE June 19, 1979

NAME OF OWNER Mr. Paul A. Vogler

ADDRESS OF OWNER 2238 Waverly Drive, Monroe, NC

LOCATION OF LOT Highway 74, East Lot 3

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive
Perched Water Table
Soil Permeability Unsuitable
Site Classification Unsuitable

Inadequate area available for installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

Stephen J. Wood, Environmentalist

EHD 398
7/77

Date Received 2/2/79

1

APT No. 15098

T. C. No. 215-092-08

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER VOGLER (LAST) PAUL (FIRST) A (MIDDLE)

2) ADDRESS OF OWNER 2228 Whitney Dr. ZIP 28210

3) PHONE NO. Home 537-7056 Office 821-9437


4) LOCATION OF PROPERTY Independence Blvd. at County Line
STREET OR COUNTY ROAD

5) SUBDIVISION _____ LOT NO 2 BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Paul A. Vogler
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

S.I.R. No. 15098

(Ground Absorption Sewage Disposal)

OWNER: Paul A. Wrigley
ADDRESS: 2238 Waverly Dr.
COUNTY: Rowan, N. C. 28110
LOCATION OF SITE: Highway 29E.

DATE REQUESTED:
PLAT NO.: PC 215-092-08 Lot 42
LOT SIZE: 75,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 2-6% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS 2:1 Clay (U)	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils) ✓	(S) Massive PS U	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 40" U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	(S) None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal) ✓	S Seasonal PS Perched (U) water Table	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate) ✓	S PS (U) Slow	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION ✓	Unsuitable			
SOIL SERIES	Helena			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns)

Recommendations/Comments: _____

Described By: William A. Mullen

Title: Soil Scientist Date: 2-16-79 ✓

dhs form 2601 (1/79)
Sanitation


165'
Hotone
500'
500'
Highway 14

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15098
T.C. NO. po 215-092-08
MAP DATE
DATE Feb. 21, 1979

NAME OF OWNER Paul A. Vogler

ADDRESS OF OWNER 2238 Waverly Drive

LOCATION OF LOT Highway 74, East (Independence Blvd.) Lot #2

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Stfucture Massive

Perched Water Table

Soil Permeability Unsuitable

Site Classification Unsuitable

Stephen J. Wood, Environmentalist

EHD 398
7/77

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

APT 15C96

(Ground Absorption Sewage Disposal)

OWNER: Paul A. Wigler
ADDRESS: 2234 Waverly Dr.
COUNTY: Wayne Co. 27534
LOCATION OF SITE: Highway 74

DATE REQUESTED:
PLAT NO.: PC 215-C42-C4 Lot #4
LOT SIZE: 36,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) 2-6% PS U	(S) PS 2-6% U	S rolling PS slopes U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S (PS) clay U	S 2:1 PS clay U	S (PS) clay U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S (PS) Blocky U	S PS Massive U	S (PS) Blocky U	S PS U
4. SOIL DEPTH (In.)	(S) 40" PS U	(S) 40" PS U	S 12-20" PS Variable U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	(S) None PS U	(S) None PS U	S None PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 24-36" PS Grand U Water	S Seasonal PS Perched U Water Table	S Limited PS Areas, Channel U Water	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) Moderate U	S PS Slow U	S (PS) Moderate U	S PS U
8. OTHER (Specify)	S (PS) Limited Area U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Provisionally Suitable	Unsuitable	Prov. Suitable	
SOIL SERIES	Coxville	Johnston	Exum/Mixed Alluvial	

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)


Recommendations/Comments:

Described By: William H. Martin

Title: Soil Scientist Date: 6-14-79

DHS Form 2601 (2/77)
Sanitation

3


200'
200'
150'
Highway

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. _____
T.C. NO. _____
MAP DATE 15098
DATE po 215-092-08

June 19, 1979

NAME OF OWNER _____

ADDRESS OF OWNER Paul A. Vogler

LOCATION OF LOT 2238 Waverly Drive Lot 2
Highway 74 East, Lots 2 and 6

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive
Perched Water Table
Soil Permeability Unsuitable
Site Classification Unsuitable

Inadequate area available for installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

John R. Adkisson

John R. Adkisson, Environmentalist

EHD 398
7/77