Date Received 3-28-84

RECEIVED
MAR 28 1984
ENVIRONMENTAL HEALTH

SIR No 20849 ✓
T. P. No 001-121-06

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Hampton Builders, Inc
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P.O. Box 984 Davidson, NC ZIP 28036

3) PHONE NO. Home 563-5795 Office same 379-4989 Roger

4) LOCATION OF PROPERTY Corner of Bethel Church Rd & Walter Henderson Rd.
(STREET OR COUNTY ROAD)

5) SUBDIVISION For Donald Hampton LOT NO 5 BLOCK NO _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Donald W. Hampton Pres.
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT COPY

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20849

T.C. NO. PO 001-12106

(Ground Absorption Sewage Disposal)

OWNER: Hampton Builders, Inc.
ADDRESS: PO Box 924
Davidson, N.C. 28036
LOCATION OF SITE: Whitten Henderson Rd

PLAT NO: Lot #5
LOT SIZE: 24,700

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 2-10% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS 30-48" U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS >36" U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S >48" PS to ground water U	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	WP			
9. SITE CLASSIFICATION	Provisionally suitable			
10. SOIL SERIES	Cerit Lite			

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: Dirt piled on lot to be removed by developer

Described by: William R. Martin
Title: Soil Scientist

Date: 4-26-84


105'
339'
cent. line
344'
118'
Walter Henderson Rd

Serial No. 5617

SIR No. 20849

Date Issued 4-27-84

T. C. No. PO 001-121-06

Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
SOIL INVESTIGATION REPORT

NAME OF OWNER Hampton Builders, Inc.
LAST FIRST MIDDLE

ADDRESS OF OWNER P. O. Box 924, Davidson, NC ZIP 28036

LOCATION OF PROPERTY Walter Henderson Road
STREET OR COUNTY ROAD

SUBDIVISION LOT NO 5 BLOCK NO



PLOT PLAN

This is to certify that a soil investigation and on-site investigation was made by the Mecklenburg County Department of Environmental Health [illegible] The said investigation was conducted on that portion of the lot as indicated on the above plot PROVISIONALLY SUITABLE

The permeability rate determined by the investigation was [illegible] The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install [illegible] from the Mecklenburg County Department of Environmental Health [illegible] treatment system on the said lot.
2. The size of the septic tank [illegible] the Mecklenburg County Department [illegible] the size and type of [illegible]
3. [illegible] installation on the above plot.
4. The approval [illegible] on the lot which in the [illegible] as acceptable for system installation [illegible]

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina Department of Human Resources, Division of Health Services and the Mecklenburg County Health Commission which were in effect on the date of issuance and is void if at any time in the future, prior to completion of the system, these laws, rules and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

William R. Marlin
Soil Scientist

Bill D. Harbuter Jr.
Environmental Health Director or Authorized Section Head

EHD-5-76

Environmental Health Department's Copy

SEE INSTRUCTIONS ON BACK

Date Received 5-2-84 — ICAR(S) Application No. 26849

T. P. No. 001-121-06

Map Date _____

MECKLENBURG, COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Department of Environmental Health for a permit to

1) X Install or Construct 2) _____ Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption effluent discharge



3) PLOT PLAN (ACCURATELY DIMENSIONED)

Mobile Home ____ Yes ✓ No
Residence ✓ Yes ____ No
4) No. of Bedrooms 3
5) Business Use — Max No. Employees N/A
6) Washing Machine ✓ Yes ____ No
7) Garbage Disposal ____ Yes ✓ No
8) Dishwasher ✓ Yes ____ No
9) Water Supply
A) Individual Well ✓
B) Governmental System ____
C) Community System
1 Well source ____
2 Governmental source ____
10) Sewage System
House located within 200 feet of public sewer ____ Yes ✓ No
House located within 200 feet of community sewer ____ Yes ✓ No
11 FHA Case No ____
12 VA Case No ____

13) NAME OF OWNER Hampton Builders, Inc. (LAST / FIRST / MIDDLE)

14) ADDRESS OF OWNER P.O. Box 924 Davidson, NC 28036

15) PHONE NO. Home 563-5795 Office 379-4989 pager

16) LOCATION OF SYSTEM 19931 Walter Henderson Road (STREET OR COUNTY ROAD)

17) SUBDIVISION for Donald Hampton Lot No. 5 Block No. n/a

Map Book No. _____ Page No. _____

18) DEED REFERENCE — DEED BOOK 4815 AT PAGE 790

19) HAS A SOIL INVESTIGATION BEEN RUN? X YES ____ NO DATE RUN 4-26-84

20) PTR NUMBER (See Instructions) _____

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

5-1-84
DATE OF APPLICATION

Donald M. Hampton Pres.
OWNER

EHD-5-76

Environmental Health Department's Copy

Date Issued 5-2-84

Serial No. 7463

SIR No. 20849

T. C. No. PO 001-121-06

Map Date L CRT

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Hampton Builders, Inc. (LAST / FIRST / MIDDLE)

ADDRESS OF OWNER P.O. Box 924, Davidson, NC ZIP 28036

LOCATION OF LOT 19931 Walter Henderson Road (STREET OR COUNTY ROAD)

SUBDIVISION ____ LOT NO. 5 BLOCK NO. ____

MAP BOOK NO. ____ PAGE NO. ____

The above specified lot is approved by the Mecklenburg County Department of Environmental Health for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the soil investigation, on an on-site inspection of the said lot, and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 20849 This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered and/or repaired in the same area where the soil investigation was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altered, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit.

Ralph R. Ellis
Environmentalist

Environmental Health Director, or Authorized Section Head

EHD-5-74

Environmental Health Department's Copy