MECK COUNTY DEPARTMENT OF
RECEIVED
JUL 15 1993
ENVIRONMENTAL HEALTH

Date Received 7-15-93

SIR No. 19882

Part of T. C. No. 139-182-10

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Flowe (LAST) Fannie (FIRST) G. (MIDDLE)

2) ADDRESS OF OWNER % Haney Const. P.O. Box 25311 Charlotte, N.C. ZIP 28212

3) PHONE NO. Home _____ Office 536-2100


4) LOCATION OF PROPERTY Cabarrus Rd. & Ferguson Rd. (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Fannie G. Flowe
OWNER

EHD-5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 19882
T.C. NO. PO 139-182-10
DATE: 8-30-83

Ms. Fannie G. Flowe
% Haney Construction Company
P. O. Box 25311
Charlotte, NC 28212

Re: Property located at Cabarrus Road & Ferguson Road

Dear Ms. Flowe:

At your request, a field investigation was conducted on the property designated above. The soils on the property were found to contain a limited area of provisionally suitable soil for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit plot plans for the proposed construction, well, and ground absorption sewage disposal system to this office. They will be reviewed and if it is found that there is an adequate area of provisionally suitable soil to accommodate the proposed installation, an Improvements Permit will be issued by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19882

T.C. NO. P8 139-182-10

(Ground Absorption Sewage Disposal)

OWNER: Fannie Flowe
ADDRESS: % Haney Const. Co Box 25311 28212
PLAT NO:
LOT SIZE: 1.21
LOCATION OF SITE: Cabarrus Rd At Ferguson Rd LOT I

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(PS) 2-10	(PS) 2-10	(PS) 2-6	PS
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	(PS) Clayey	(PS) Clayey	(PS) Clayey	PS
3. SOIL STRUCTURE (12-36 inches)	(PS) Blocky	(PS) Blocky	(PS) Blocky	PS
4. SOIL DEPTH (inches)	(U) 30 >	(PS) 36-40	(PS) 45	PS
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	(PS) None	(PS) None	(PS) None	PS
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	(PS) Adequate	(PS) Adequate	(PS) Adequate	PS
7. OTHER (Specify)	PS	PS	PS	PS
8. SOIL GROUP	IVa	IVa	IVa	
9. SITE CLASSIFICATION	Unsuitable	PS Suitable	PS Suitable	
10. SOIL SERIES	Cecil	Cecil	Cecil	

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments:

Described by: W. B. Ramsey
Title: Soil Scientist

Date: 2-25-83

EHD 539 (Revised: 6/82)

1
11


30
316
Cecil
2-6
P.stubble
Depth 45"
Low Area
300
90
Cecil 36-40"
2-10 P.stubble
Eroded Cecil 2-10
60'
Depth 30" unsuitable
Fairview Rd
201
Cabarrus Rd