Date Received 3-28-83

MECK. COUNTY DEPARTMENT OF
RECEIVED
MAR 28 1983
ENVIRONMENTAL HEALTH

SIR No. 19501

T. Pin No. 037-211-03

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Dancy Homess Inc.,
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 443 South Boulevard, _____ ZIP _____
Charlotte, N. C., 28203

3) PHONE NO. Home _____ Office 332-6310


4) LOCATION OF PROPERTY ~~Henderson Circle~~
(STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. 10 E BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT
Dancy Homes, Inc.,

OWNER A.F. Dancy Sr., Pres.

A. F. Dancy

EHD-5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
[illegible]
CHARLOTTE [illegible] NA 28203

SIR. NO. 19501
T. C. NO. PO 037-212-04
DATE: 4-25-83

Dancy Homes, Inc.
1443 South Boulevard
Charlotte, NC 28203

Re: Property located at Henderson Circle South, Lot 10-E

Dear Sir:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, please submit your proposals, in the form of plans and specifications, to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of a "Septic Tank Agreement Form" provided by this office.

If I may be of assistance, please feel free to call at any time.

Sincerely,

Mike Sexton

Michael A. Sexton
Environmentalist
On Premises Waste Disposal Section

Enclosure

EHD #37 (11-82)

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19501

T.C. NO. PO 037-2120

(Ground Absorption Sewage Disposal)

OWNER: Laney Homes Inc.
ADDRESS: 1443 S. Boulevard Charlotte, N.C. 28203
PLAT NO: 10-E
LOT SIZE: 14,320
LOCATION OF SITE: Henderson Circle

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U — 8-15%	(S) PS U — 8-15%	(S) PS U — 36%	S (PS) U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) U — clay	S PS (U) — 2-1 clay	S (PS) U — clay loam	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U — Blocky	S (PS) U — Weak Blocky	S (PS) U — Blocky	S PS U
4. SOIL DEPTH (inches)	S (PS) U — 36-48"	S PS (U) — 24-36"	S (PS) U — 36-40"	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) U — Saprolite 36"+	S PS (U) — Saprolite ± 36"	S (PS) U — 36"+	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) U — 36"+ to ground water	S PS (U) — Perched water table 24-36"	S PS (U) — Drainage way	S PS U
7. OTHER (Specify)	S PS (U) — Restrictive Area	S PS U	S PS U	S PS U
8. SOIL GROUP	IVA	IVB	IVA	
9. SITE CLASSIFICATION	unsuitable	unsuitable	unsuitable	
10. SOIL SERIES	Cecil-like	Herndon-like	Drainageway	

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: inadequate lot size

Described by: William A. Merlin
Title: Soil Scientist
Date: 4-22-83

EHD 539 (Revised: 6/82)

2/


60' Ended Arms
225'
Proposed Road
Cecil Line
320'
Helena Line
Henderson Circle

Date Received 11-10-83

MECK COUNTY DEPARTMENT OF
RECEIVED
NOV 10 1983
ENVIRONMENTAL HEALTH

SIR No. 19501
P.C. No. 037-212-04
Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Dancy Homes Inc
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER 1443 South Blvd ZIP 28203

3) PHONE NO. Home —— Office 332-6310


4) LOCATION OF PROPERTY 5200 Henderson Circle - (Hy 115)
(STREET OR COUNTY ROAD)

5) SUBDIVISION Trexler Heights LOT NO. 70-71-81-82 BLOCK NO.

MAP BOOK NO 4 PAGE NO. 64-1 #7

6) DEED REFERENCE: DEED BOOK 4567 PAGE NO. 0549

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Robert E. Dancy
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 19501
T.C. NO. PO 037-212-04
DATE: 12-6-83

Dancy Homes, Inc.
1443 South Boulevard
Charlotte, NC 28203

Re: Property located at Henderson Circle, Lot 7

Dear Sirs:

At your request, a field investigation was conducted on the property designated above. The soils on the property were found to contain a limited area of provisionally suitable soil for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit plot plans for the proposed construction, well, and ground absorption sewage disposal system to this office. They will be reviewed and if it is found that there is an adequate area of provisionally suitable soil to accommodate the proposed installation, an Improvements Permit will be issued by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19501

T.C. NO. PO 137-21224

(Ground Absorption Sewage Disposal)

OWNER: Davis Homes, Inc.
ADDRESS: 1443 Scuth Blvd Charlotte, N.C. 28203
PLAT NO: #7
LOT SIZE: Acres 24,000
LOCATION OF SITE: off Henderson Circle

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U — 6-12%	S (PS) U — 2-12%	S PS (U) — complex slopes	S PS U —
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) U — clay	S PS (U) — 2:1 clay	S PS U —	S PS U —
3. SOIL STRUCTURE (12-36 inches)	S (PS) U — blocky	S (PS) U — blocky	S PS U —	S PS U —
4. SOIL DEPTH (inches)	S (PS) U — 36-40"	S (PS) U — 24-36"	S PS U —	S PS U —
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) U — 36"	S PS (U) — 36"	S PS U —	S PS U —
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) U — 36" to ground water	S PS (U) — perched water table 24-30"	S PS (U) — eroded areas channel	S PS (U) — driveway
7. OTHER (Specify)	S (PS) U — restricted areal	S PS U	S PS U — no soil	S PS U
8. SOIL GROUP	IVA	IVB	—	—
9. SITE CLASSIFICATION	unsuitable	unsuitable	unsuitable	unsuitable
10. SOIL SERIES	Cecil-Pacolet	Helena-Pacolet	complex slopes	Drainageway

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments: _____

Described by: William G. Martin
Title: Soil Scientist

Date: 12-2-83

EHD 539 (Revised: 6/82)

14


Drainageway
cervi-
800'
100
Proposed
Drive
60'
200'
complex slopes
Henderson Circle

Date Received 5-3-84 4-24-84

SEE INSTRUCTIONS ON BACK

RECEIVED
APR 24 1984
MECKLENBURG COUNTY DEPARTMENT OF HEALTH

(CAR S) Application No. 19501

T. C. No. PO 039-212-04


Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Department of Environmental Health for a permit to:

1) ✓ Install or Construct 2) _____ Alter or Repair an individual septic tank wastewater treatment system with a subsurface, soil absorption, effluent discharge.



3) PLOT PLAN (ACCURATELY DIMENSIONED)

Mobile Home ✓ Yes ___ No
Residence ___ Yes ___ No

4) No of Bedrooms 2
5) Business Use — Max No Employees _____
6) Washing Machine ___ Yes ✓ No
7) Garbage Disposal ___ Yes ✓ No
8) Dishwasher ___ Yes ✓ No
9) Water Supply:
   A) Individual Well _____
   B) Governmental System _____
   C) Community System:
      1. Well source ✓
      2. Governmental source _____
10) Sewage System:
   House located within 200 feet of public sewer ___ Yes ✓ No
   House located within 200 feet of community sewer ___ Yes ✓ No
11) FHA Case No _____
12) VA Case No. _____

13) NAME OF OWNER Danny (LAST) Homes (FIRST) Inc. (MIDDLE)

14) ADDRESS OF OWNER 1443 S. Bush, Charlotte, N.C. 28203

15) PHONE NO. Home 392-4662 Office 334-2706

16) LOCATION OF SYSTEM 7143 Tide St. (STREET OR COUNTY ROAD)

17) SUBDIVISION _____ Lot No. _____ Block No. _____

Map Book No. _____ Page No. _____

18) DEED REFERENCE — DEED BOOK _____ AT PAGE _____

19) HAS A SOIL INVESTIGATION BEEN RUN? ___ YES ___ NO DATE RUN _____

20) PTR NUMBER (See Instructions) _____

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

4/24/84
DATE OF APPLICATION

Robert E. Gainey
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY