Kemp R. Dunaway
1607 E Morehead St, Charlotte
333-2113

Date Received 10 24 84

MECK [illegible] DEPARTMENT OF
RECEIVED
[illegible] 1984
ENVIRONMENTAL HEALTH

SIR No. 21571
T. C. No. 139-261-31
Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER FARR (LAST) DAVID (FIRST) K (MIDDLE)

2) ADDRESS OF OWNER 1559 FAIRWAY Dr. Charleston, SC ZIP 29412

3) PHONE NO. Home 803 795 4581 Office

4) LOCATION OF PROPERTY IRA Flow Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION THREE SPRINGS LOT NO. 4 BLOCK NO.

MAP BOOK NO. PAGE NO.

6) DEED REFERENCE DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

David K. Farr
By Kemp R. Dunaway, Agent
OWNER

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 21571

T.C. NO. 139 261-31

(Ground Absorption Sewage Disposal)

OWNER: DAVID FARR
ADDRESS: 3559 FAIRWAY DR.
Charleston, S.C. 29412
LOCATION OF SITE: To Flow Rd

PLAT NO:
LOT SIZE: 45,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S / PS 2-15 / U	S / PS 15-15 / U	S / PS 2-[illegible] / U	S / PS / U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S / PS Clayey / U	S / PS Clayey / U	S / PS Mixed Clay / U	S / PS / U
3. SOIL STRUCTURE (12-36 inches)	S / PS Blocky / U	S / PS Blocky / U	S / PS Weak Blocky / U	S / PS / U
4. SOIL DEPTH (inches)	S / PS [illegible] / U	S / PS 12-15 / U	S / PS 12-35 / U	S / PS / U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S / PS None / U	S / PS None / U	S / PS None / U	S / PS / U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S / PS Adequate / U	S / PS Adequate / U	S / PS Slow / U	S / PS / U
7. OTHER (Specify)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
8. SOIL GROUP	IVa	IVa	IVa	
9. SITE CLASSIFICATION	Unsuitable	Unsuitable	Unsuitable	
10. SOIL SERIES	Cecil	Sewed [illegible]	Poorly Hollow soils	

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: Pump [illegible] Required To Use The F.S. Area

Described by: W. B. Ramsey
Title: Soil Scientist

Date: 11-11-84

1#


150
Lake
Helena
2-6
300
Cecil
10-12" Depth
301
Cecil
2-15%
50
150
Flow Road

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

L

SIR. NO. 21571
T.C. NO. 139-261-31
DATE: 11-9-84

David K. Farr
1559 Fairway Drive
Charleston, SC 29412

RE: Property located at Ira Flow Road, Lot 4

Dear Mr. Farr:

At your request, a field investigation was conducted on the property designated above. The soils on the property were found to contain a limited area of provisionally suitable soil for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit plot plans for the proposed construction, well, and ground absorption sewage disposal system to this office. They will be reviewed and if it is found that there is an adequate area of provisionally suitable soil to accommodate the proposed installation, an Improvements Permit will be issued by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure