Date Received 5-25-83

MECK COUNTY DEPARTMENT OF
RECEIVED
MAY 25 1983
ENVIRONMENTAL HEALTH

SIR No. 19710
T. C. No. 111-041-08
Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNERS Brawley, Columbus & Wife Wilma
3 Brawley (LAST) Hugh (FIRST) Frank (MIDDLE)

2) ADDRESS OF OWNER 9600 Brawley Lane ZIP 28215

3) PHONE NO. Home 537-1654 Office


4) LOCATION OF PROPERTY At END of Teeter Dr. (STREET OR COUNTY ROAD) Turn Right Go Nearly to Dead End See Perk sign on Right

5) ~~SUBDIVISION~~ FARM LOT NO. BLOCK NO.

TAX MAP BOOK NO III PAGE NO. 04

6) DEED REFERENCE DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Columbus Brawley et al
OWNER

EHD-5-76

Environmental Health Department's Copy

Serial No. 5097

SIR No. 19710

T. C. No. P0 111-041-08

Date Issued 7-6-83

Map Date


MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
SOIL INVESTIGATION REPORT

NAME OF OWNER Brawley, (LAST) Columbus & wife Wilma brawley, hugh (FIRST) Frank (MIDDLE)

ADDRESS OF OWNER 9600 Brawley Lane, Charlotte, NC ZIP 28215

LOCATION OF PROPERTY Teeter Drive (STREET OR COUNTY ROAD)

SUBDIVISION LOT NO BLOCK NO.



PLOT PLAN

This is to certify that a soil investigation and on-site investigation was made by the Mecklenburg County Department of Environmental Health on the lot described above. The said investigation was conducted on that portion of the lot as indicated on the above plot. Provisionally Suitable
The permeability rate determined by the investigation was The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install, construct, alter or repair the specific system shall be obtained from the Mecklenburg County Department of Environmental Health prior to the beginning of any construction of buildings or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater treatment system which must be installed will be determined by the Mecklenburg County Department of Environmental Health prior to installation based on the permeability rate obtained above, and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area indicated as acceptable for system installation on the above plot.
4. This approval is void if any grading, filling or construction including the drilling of a well is performed on the lot which, in the opinion of the Mecklenburg County Department of Environmental Health renders the area indicated as acceptable for system installation unsuitable for installation, construction, alteration, and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina Department of Human Resources, Division of Health Services and the Mecklenburg County Health Commission which were in effect on the date of issuance and is void if at any time in the future, prior to completion of the system, these laws, rules and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

W. B. Ramsey
EHD-S-76 Soil Scientist

Bill D. Henderson
Environmental Health Director or Authorized Section Head

Environmental Health Department's Copy

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19710

T.C. NO. PO 111-041-08

(Ground Absorption Sewage Disposal)

OWNER: Columbus Brawley
ADDRESS: 9600 Brawley Lane

PLAT NO:
LOT SIZE: 2+A

LOCATION OF SITE: End of Teeter Dr. Turn Rt.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U — 2-10	S (PS) U — 2-15	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) U — Clayey	S PS (U) — Mixed Clay	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U — Blocky	S PS (U) — Weak Blocky	S PS U	S PS U
4. SOIL DEPTH (inches)	S (PS) U — 36-45"	S PS (U) — 10-15"	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) U — None	S PS (U) — Saprolite	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) U — Adequate	S PS (U) — Slow	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IIa	IIIa		
9. SITE CLASSIFICATION	Suitable	Unsuitable		
10. SOIL SERIES	Cecil	Wilkes		

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:

Described by: W. B. Ramsey
Title: Soil Scientist

Date: 7-5-83

EHD 539 (Revised: 6/82)


Lot 2
Lot 1
160'
230'±
Wilkes
2-B
Coyl
160
2-10
Wilkes
2-B
Wilkes
2-15
Bank
200
200