Date Received 5-23-73

APT No 6349
P.O.
T C No 139-22-15
Map Date 2-14-73

# MECKLENBURG COUNTY HEALTH DEPARTMENT

## ENVIRONMENTAL HEALTH DIVISION

### APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER [redacted] Brief Road Development Company
LAST FIRST MIDDLE

2) ADDRESS OF OWNER 1240 E. INDEPENDENCE BLVD. ZIP 28205

3) PHONE NO. Home _____ Office 333-5492


4) LOCATION OF PROPERTY LOT 6, Barley Lane
STREET OR COUNTY ROAD

5) SUBDIVISION HILLANDALE Acres Addition LOT NO. 6 BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.




7) ACCURATELY DIAGRAM & DIMENSION LOT

[redacted] Brief Road Development Company

MAY 14, 1973

OWNER [redacted] VICE PRESIDENT

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

# MECKLENBURG COUNTY HEALTH DEPARTMENT
## INTER-OFFICE COMMUNICATION

**DATE:** November 5, 1973

**TO:** John Adkisson
Environmentalist

**FROM:** W. Everette Lynn, Jr. WEL
Soil Scientist

**SUBJECT:** APT #6349 (Brief Road Development Co.)
Lot No. 6, Baxley Lane
11-2-73

Soils were found to be fill material on the front of the lot (adjacent to Baxley Lane) to a depth of 18 to 36 inches. This fill material overlies an area of alluvial soils. These alluvial soils have a seasonal high water table. This factor results in inadequately slow permeability and percolation rate. The rear portion of the lot is also subject to flooding.

Based on this investigation, the lot is unsuitable for installation of a septic tank system.

WEL:jdg

# MECKLENBURG COUNTY
## Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. November 6, 1973
2. _____
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 6349
T.C. No. P.O. 139-275-15
2-14-73

NAME OF OWNER Brief Road Development Company

ADDRESS OF OWNER 1740 E. Independence Blvd. ZIP 28205

LOCATION OF LOT Baxley Lane, Lot 6

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

| | Test No. | Date of Test | Percolation Rate |
|---|---|---|---|
| ____ | 1. | _____ | _____ min/in |
| ____ | 2. | _____ | _____ min/in |
| ____ | 3. | _____ | _____ min/in |

__X__ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) 11-2-73 - Soils were found to be fill material on the front of the lot (adjacent to Baxley Lane) to a depth of 18 to 36 inches. This fill material overlies an area of alluvial soils. These alluvial soils have a seasonal high water table. This factor results in inadequately slow permeability and percolation rate. The rear portion of the lot is also subject to flooding.

W. Emmette Lynn, Jr. — Soil Scientist
John R. Atkisson — Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70