Date Received 3/22/99

MECK COUNTY DEPARTMENT OF
RECEIVED
MAR 22 1999
ENVIRONMENTAL HEALTH

APT No. 15276

T. C. No. 193-311-09

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Davant Realty Inc. (one of the owners)
LAST FIRST MIDDLE

2) ADDRESS OF OWNER 216 N. Church St. Charlotte ZIP 28202

3) PHONE NO. Home _____ Office 376-3591


4) LOCATION OF PROPERTY US Hwy 74 (E. Ind. Blvd.) Between 84 Lumber Co. (Right hand side)
STREET OR COUNTY ROAD

5) SUBDIVISION Monroe LOT NO. Tax Code 193-311-9 BLOCK NO. _____

MAP BOOK NO See tax map Atlas PAGE NO _____

6) DEED REFERENCE DEED BOOK 3646 PAGE NO 193

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Eugene M Davant
OWNER

EHD-5-74

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

S.I.R. No. 15276
193-311-09

(Ground Absorption Sewage Disposal)

OWNER: DAVANT Realty INC
ADDRESS: 216 N Church St.
COUNTY: Meck
LOCATION OF SITE: U.S. Hwy 74 E at BH Lumber

DATE REQUESTED: 3-22-79
PLAT NO.:
LOT SIZE: 92,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10 U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S mostly PS Saprolite (U)	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S mostly PS massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS <48" (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S Saprolite PS (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S PS slow (U)	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	~~S~~ ~~PS~~ (U) slow	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	~~UNSUITABLE~~			
SOIL SERIES	Cullasaja C Horizon			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns)

Recommendations/Comments:

Described By: Willard B. Lamay

Title: Soil Scientist Date: 3-28-79

dhs form 2601 (1/79)
Sanitation


Cut 30
200
3 Feet
Cut Area
To Saprolite
2-1a
522
397
Furniture store
Lumber 84
Proposed Area
slight Fill
were in swale
area
200
U.S. 74

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15276
T.C.NO. 193-311-09
MAP DATE
DATE March 29, 1979

NAME OF OWNER Davant Realty Inc.

ADDRESS OF OWNER 216 N. Church St.

LOCATION OF LOT U.S. Highway 74

At your request and pursuant to Section .1900 of the North Carolina Administrative Code, Title 10, Department of Human Resources, Chapter 10, Health Services, Subchapter 10A, a site evaluation has been made for an on premises ground absorption sewage disposal system on the property designated above and the following conditions were found:

Soil Permeability Unsuitable

Site Classification Unsuitable

Sites classified as Unsuitable are not acceptable for soil absorption of sewage effluent. However, if engineering, geologic, soil, and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be expected to function satisfactorily, such sites may be re-classified as Provisionally Suitable. (Section 10 of the North Carolina Administrative Code 10 A,.1910)

If you desire to file for permission to install an "alternate or modified" system, you should present this office with your proposals in the form of plans and specifications. These would be reviewed and if it is found that the system may reasonably be expected to function satisfactorily, approval may be given on the execution by you of a "Septic Tank Agreement Form" available in this office.

John R Adkisson

John R. Adkisson, Environmentalist

EHD 999 (1/79)

R