5

Date Received 1-29-73

APT No. 5487

T C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER HENDERSON (LAST) PAUL (FIRST) FLETCHER (MIDDLE)

2) ADDRESS OF OWNER 3117 CAROL AVE ZIP 28208

3) PHONE NO. Home 392 2455 Office 333 0165


4) LOCATION OF PROPERTY Owen Blvd - Dougherty Dr. (STREET OR COUNTY ROAD)

5) SUBDIVISION Dougherty Acres LOT NO 1 & 2 BLOCK NO A

MAP BOOK NO 12 PAGE NO 463

6) DEED REFERENCE DEED BOOK 2725 PAGE NO 598

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on on site inspection of the lot here nabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



ACCURATELY DIAGRAM & DIMENSION LOT

Paul F Henderson
OWNER

FORM NO. 6-1-11-1-70

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
INTER-OFFICE COMMUNICATION

DATE: August 7, 1973

TO: Randy Reynolds, Environmentalist

FROM: W. Everette Lynn, Jr.
Soil Scientist

SUBJECT: Soil investigation on Lots 1 & 2-A, Owen Boulevard & Doughtry Drive
APT. 5487

On August 7, 1973, a soil investigation was made on Lot 1 & 2-A on Owen Boulevard and Doughtry Drive to determine site suitability for a septic tank absorption field. The soils were found to be of the Iredell and Wilkes series. These soils have very plastic and sticky clay subsoils which contain a high percentage of swelling clay minerals. The Iredell soils also have a perched high water table during periods of high rainfall. The Wilkes soils are shallow to impervious weathered rock material. These factors result in inadequately slow percolation rate and permeability.

Based on these observations, it is recommended that the lots be disapproved for installation of a septic tank system.

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. _____
2. _____
3. _____

SDR No. _____
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER _____

ADDRESS OF OWNER _____ ZIP _____

LOCATION OF LOT _____

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
____	1.	_____	_____ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

_____

_____

_____

R.M. Reynolds
Environmentalist

(Stencil No.)
MED 390

FORM MD. -70

Date Received 9-18-74

MECK COUNTY HEALTH DE ..
RECEIVED
1974

APT No. 5487
T. C No 049-171-06
-05
Map Date -04
-03

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Henderson (LAST) Paul (FIRST) Fletcher (MIDDLE)

2) ADDRESS OF OWNER 3117 Oakcrest Drive ZIP 28208

3) PHONE NO Home 394-2455 Office


4) LOCATION OF PROPERTY Allens Blvd + Daughtry (STREET OR COUNTY ROAD)

5) SUBDIVISION Daughtry Acres LOT NO 23-4-5 BLOCK NO A

MAP BOOK NO 12 PAGE NO 463

6) DEED REFERENCE DEED BOOK 2725 PAGE NO 548

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Paul Henderson
OWNER

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT

INTER-OFFICE COMMUNICATION

DATE: September 18, 1974

TO: John R. Adkisson

FROM: W. Everette Lynn, Jr.
Soil Scientist

SUBJECT: Apt. 5487 (P. F. Henderson)
Lot No. 2, 3, 4 and 5, Block A, Daughtry Drive
9-18-74

The property consists of soils of the Enon and Wilkes series. These soils have plastic and sticky clay subsoils which contain expanding clay minerals. In addition, the Wilkes soils are shallow to weathered rock material. These soil characteristics generally result in inadequately slow permeability and percolation rate. Potential also exists for contamination of the water table.

WEL:dsb

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

DATE ISSUED
1. 9-19-74
2.
3.

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 5487
T.C. NO. 049-171-06
MAP DATE -05
-04
-03

NAME OF OWNER Henderson, Paul Fletcher

ADDRESS OF OWNER 3117 Carol Avenue, Charlotte 28208

LOCATION OF LOT Owens Boulevard & Daughtry

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Unsuitable soil - slow permeability and percolation rate.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Unit
Environmental Health Division

JRA:dsb

(Stencil No.)
EHD 388
8/74

FORM NO.
[illegible]-8-21-74

Date Received 9-16-74 | RECEIVED 1974 | ICAR (S) Application No. 5487

T C No. 049-171-04-25

Map Date -04-03


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

1 Install or Construct 2 ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



3 PLOT PLAN (ACCURATELY DIMENSIONED)

4 No. of Bedrooms ___

5 Business Use Max. No. Employees ___

6 Washing Machine ✓ Yes ___ No

7 Garbage Disposal ___ Yes ✓ No

8 Dishwasher ✓ Yes ___ No

9 Water Supply
A Individual Well ___
B Governmental System ___
C Community System
1 Well source ___
2 Governmental source ___

10 Sewage System
House located within 200 feet of public sewer ___ Yes ___ No
House located within 200 feet of community sewer ___ Yes ___ No

11 FHA Case No. ___

12 VA Case No. ___

13 NAME OF OWNER [illegible] (LAST) Paul (FIRST) Fletcher (MIDDLE)

14 ADDRESS OF OWNER [illegible] Creek Rise

15 PHONE NO. Home [illegible] Office ___

16 LOCATION OF SYSTEM [illegible] (STREET OR COUNTY ROAD)

17 SUBDIVISION Dogwood Lakes Lot No. 2-34-5 Block No. H

Map Book No. 14 Page No. 463

18 DEED REFERENCE — DEED BOOK 3125 AT PAGE 595

19 HAS A PERCOLATION TEST BEEN RUN? ___ YES ___ NO DATE RUN ___

20 PTR NUMBER (See Instructions) ___

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

9-16-74
DATE OF APPLICATION

Paul Henderson
OWNER

FORM NO. E-4-4-[illegible]

HEALTH DEPARTMENT'S COPY