Date Received 3-28-83

LOCK COUNTY DEPARTMENT OF
RECEIVED
MAR 28 1983
ENVIRONMENTAL HEALTH

SIR No. 19495

T. Rng. 037-262-03

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Dancy Homes, Inc.,
(LAST)

2) ADDRESS OF OWNER 1443 South Boulevard (FIRST) (MIDDLE)
Charlotte, N. C., [redacted] 28204 ZIP

3) PHONE NO. Home Office 332-6310

4) LOCATION OF PROPERTY Henderson Circle
(STREET OR COUNTY ROAD)

5) SUBDIVISION LOT NO. 4 E BLOCK NO.

MAP BOOK NO. PAGE NO.

6) DEED REFERENCE. DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.

Metrolina North Mobile Home Park,
Lot No. 4 E

7) ACCURATELY DIAGRAM & DIMENSION LOT

Dancy Homes, Inc.,
A. F. Dancy
OWNER A. F. Dancy Sr., Pres.

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19495

T.C. NO. PO 037-21204

(Ground Absorption Sewage Disposal)

OWNER: Danny Homes Inc.
ADDRESS: 1143 South Blvd. Charlotte, NC. 28203

PLAT NO: 4-E
LOT SIZE: 8,500

LOCATION OF SITE:

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 2-6% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S 2-1 Clay PS U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS 36-40" U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S saprolite PS 36"+ U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S perched PS water U Table 12-24"	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U

8. SOIL GROUP: 1 B

9. SITE CLASSIFICATION: unsuitable

10. SOIL SERIES: Helena-Liff

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: lot size inadequate

Described by: William A. Mullins
Title: Soil Scientist

Date: 4-21-83

EHD 539 (Revised: 6/82)


50
Helen's Little
170'
170'
Proposed Road
50'
Henderson Circle

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SIR. NO. 19495
T. C. NO. PO 037-212-04
DATE: 4-25-83

Dancy Homes, Inc.
1443 South Boulevard
Charlotte, NC 28203

Re: Property located at Henderson Circle North, Lot 4-E

Dear Sir:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, please submit your proposals, in the form of plans and specifications, to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of a "Septic Tank Agreement Form" provided by this office.

If I may be of assistance, please feel free to call at any time.

Sincerely,

Mike Sexton

Michael A. Sexton
Environmentalist
On Premises Waste Disposal Section

Enclosure

EHD #37 (11-82)