Date Received 4/24/77

APT No. 12749

T. C. No. 137-071-61

Map Date 1-30-76

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Batey (LAST) Elmer (FIRST) R. (MIDDLE)

2) ADDRESS OF OWNER 3411 Boulevard Colonial Heights, Virginia ZIP 23834

3) PHONE NO Home 526-2710 Office 526-4333


4) LOCATION OF PROPERTY Willhill Road (STREET OR COUNTY ROAD)

5) SUBDIVISION Wilson Woods LOT NO 7 BLOCK NO. C

MAP BOOK NO 9 PAGE NO 281

6) DEED REFERENCE DEED BOOK 2446 PAGE NO. 146

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Elmer R. Batey

OWNER

EHD-5-76

Agent for Elmer R. Batey

Environmental Health Department's Copy

Apt. 12749

DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES

APPENDIX H
SITE EVALUATION
(Ground Absorption Sewage Disposal)

APP'D: E. R. Batey DATE REQUESTED: June 14, 1977
ADDRESS: 3411 Block Colonial Heights, Va. LOT NO.: ——
COUNTY: Dinwiddie Co. LOT SIZE: 1693 Acres 28,000 sq. ft.
LOCATION OF SITE: Walthall Rd. lot no. 7 Block C Tax Ld. No.: 137-071-61

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 3-16%	S PS U ——	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, mixed clay)	S (PS) U clay	S PS U ——	S PS U	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey soils)	S (PS) U Blocky	S PS U ——	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS U >48"	S PS U ——	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, rock)	S PS U ——	S PS U ——	S PS U	S PS U
6. SOIL DRAINAGE, GROUNDWATER (External & Internal)	(S) PS U water table >36"	S PS (U) poorly drained	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) U moderate 60 min/in	S PS U seasonal high water table <18"	S PS U	S PS U
8. OTHER (Specify)	S PS U ——	S PS (U) floods from surface	S PS U	S PS U
9. SITE CLASSIFICATION*	provisionally suitable	unsuitable		
SOIL SERIES	Cecil	Chewacla		

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments: Based on this investigation, the lot was found to have an adequate area of provisionally suitable soils for installation of a septic tank system. System design should be based on a percolation rate of 60 min/in and should be placed in the area of Cecil soils.

Described By: W. Edward Casement

Title: Soil Scientist Date: July 6, 1977

DHS Form 2601 (2/77)
Sanitation


35'
preferrable septic system location
① Cecil
346'
314'
Chewacla
②
130'
Willhill Rd

Serial No. 1072

PTR No. 12749

T C No. 137-071-61

Map Date 1-30-76

Date Issued July 6, 1977


MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
SOIL INVESTIGATION REPORT

NAME OF OWNER Batey (LAST) Elmer (FIRST) R. (MIDDLE)

ADDRESS OF OWNER 3411 BOulevard, Colonial Heights, Virginia ZIP 23834

LOCATION OF PROPERTY WillHill Road (STREET OR COUNTY ROAD)

SUBDIVISION Wilson Woods LOT NO 7 BLOCK NO C



PLOT PLAN

This is to certify that a soil investigation and percolation test was made by the Mecklenburg County Department of Environmental Health on the lot described above. The soil investigation was conducted on the date noted and dated on the above plat. **Provisionally Suitable**

The permeability rate determined by this investigation was **60 min/in.** The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge subject to the following terms and conditions:

1. A system of a design approved by the Mecklenburg County Department of Environmental Health as specified in the application for the wastewater treatment system on this lot.
2. The absorption area shall be determined by the Mecklenburg County Department of Environmental Health in accordance with the permeability rate obtained above, and on the size of the building it will serve.
3. The absorption area shall be limited to the area indicated as acceptable for system installation on the above plat.
4. The issuance of a permit for the construction of a building on the lot will be performed on the lot which the Mecklenburg County Department of Environmental Health has indicated as acceptable for system installation and that the location of the building will not impair the use of the system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina Department of Human Resources, Division of Health Services and the Mecklenburg County Health Commission which were in effect on the date of issuance and is void if at any time in the future prior to completion of the system these laws, rules and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

W. Edward Casement
Soil Scientist

EHD-5-76

John A. Wesson
Environmental Health Director or Authorized Section Head

Environmental Health Department's Copy

Date Received 11/5/79

APT No. 12749

T. C. No. 137-071-61

Map Date 9/4/79

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Batey (LAST) Elmer (FIRST) R (MIDDLE)

2) ADDRESS OF OWNER Rt 1 Box 144-D-7 Prince George, Va. ZIP 23875

3) PHONE NO Home 804-541-3343 Office 804-732-6613


4) LOCATION OF PROPERTY Wilcox Road # 3248 (STREET OR COUNTY ROAD)

5) SUBDIVISION Wilcox Woods LOT NO 61 BLOCK NO 71

MAP BOOK NO 137 PAGE NO 7

6) DEED REFERENCE DEED BOOK 2446 PAGE NO 146

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinafter described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Elmer R. Batey
OWNER

EHD-5-76

Environmental Health Department's Copy

S. I. R. NO. 12749

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

T. C. # 137-071-61

(Ground Absorption Sewage Disposal)

OWNER: ELMER R. BATEY
ADDRESS: R-1 Box 164-D7
COUNTY: PRINCE GEORGE VA 23875
LOCATION OF SITE: WILL HILL ROAD Lot #7

DATE REQUESTED: 11 5 79
PLAT NO.:
LOT SIZE: 23,690

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U — 2 - 10	S PS (U) — 0 - 2	S (PS) U — 2 - 10	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy clayey, Note 2:1 Clay)	S PS (U) — CLAYEY 2-1	S PS (U) — Clayey 2-1	S PS (U) — Clays 2-1	S PS U
3. SOIL STRUCTURE (12-36 in.) (Clayey Soils)	S PS (U) — Massive	S PS (U) — TEND TO BE Massive	S PS (U) — Blocky To Massive	S PS U
4. SOIL DEPTH (In.)	S PS (U) — <48	S PS (U) — <48	S PS (U) — <48	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S PS (U) — Clay	S PS (U) — Clays	S PS (U) — Clays	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & internal)	S PS (U) — Slow	S PS (U) — Slow	S PS (U) — Slow	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S ~~PS~~ (U) — Slow	S PS (U) — SLOW	S PS (U) — Slow	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION:	UNSUITABLE	Unsuitable	Unsuitable	
SOIL SERIES	HELENA	MONACAN Cecil over Helena		

S - Suitable PS - Provisionally Suitable U Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies wet areas, fill areas, wells, water bodies, slope patterns, etc

Recommendations/Comments:

Described By: W.B. RAMSEY

Title: SOIL SCIENTIST Date: 11-20-79

DHS Form 2601
Sanitation
EHD 539 (2/79)

2

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # ~~12749~~

T.C. # ~~127-871-61~~

DATE ~~11-21-79~~

NAME OF OWNER Batey, Elmer R.

ADDRESS OF OWNER RFD 1, Box 164 D 7, Prince George, Va. 23875

LOCATION OF LOT Willhill Road, Lot 7, Block C

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section