W

Date Received 9-20-73

APT No. 7023

T C No. 137-109-15

Map Date Sept 73

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Gladden (LAST) Hubert (FIRST) James (MIDDLE)

2) ADDRESS OF OWNER 7310 Wilson Grove Rd ZIP 28212

3) PHONE NO Home 545-6523 Office 537-9831


4) LOCATION OF PROPERTY Wilson Grove Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO _____ BLOCK NO _____

MAP BOOK NO 5 PAGE NO 345

6) DEED REFERENCE DEED BOOK 3531 PAGE NO 456

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Hubert James Gladden
OWNER

FORM NO. E-1-11-1-70

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY

Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. October 4, 1973
2. October 8, 1973
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 7023
T.C. No. 137-109-15
9-5-73

NAME OF OWNER Gladden, Hubert James

ADDRESS OF OWNER 7310 Wilson Grove Road ZIP 28212

LOCATION OF LOT Wilson Grove Road

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	10-2-73	300 min/in
X	2.	10-4-73	160 min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

Thomas R. Ward
Environmentalist

(Stencil No.)
HD 398
8/70

FORM NO.
E-19-8-14-70

Serial No.

PTR No. 7023

T C No 137-109-15

Date Issued October 12, 1973

Map Date 9-5-73

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER Gladden (LAST) Hubert (FIRST) James (MIDDLE)

ADDRESS OF OWNER 7310 Wilson Grove Road ZIP 28212

LOCATION OF PROPERTY Wilson Grove Road (STREET OR COUNTY ROAD)

SUBDIVISION LOT NO BLOCK NO



PLOT PLAN

This is to certify that a percolation test has been run and an on-site inspection made by the Mecklenburg County Health Department on the lot described above. The said test was conducted on that portion of the lot as indicated on above plot

The percolation rate determined by the test was 60 min/in The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install, construct, alter, or repair the specific system shall be obtained from the Mecklenburg County Health Department prior to the beginning of any construction of buildings, or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater teratment system which must be installed will be determined by the Health Department prior to installation based on the percolation rate obtained above, and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area where the percolation test was run
4. This approval is void if any grading, filling, or construction (including the drilling of a well) is performed on the lot which, in the opinion of the Health Department, renders the area where the percolation test was run unsuitable for the installation, construction, alteration, and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina State Board of Health and the Mecklenburg County Board of Health which were in effect on the date of issuance and is void if at any time in the future, prior to the completion of the system, these laws, rules, and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

John R. Robinson

Director, Environmental Health Division or Authorized Section Head

FORM NO. E-2-4-1-71

HEALTH DEPARTMENT'S COPY

SEE INSTRUCTIONS ON BACK

Date Received 9-20-73

ICAR(S) Application No 7023

T C No


Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

(1) Install or Construct (2) Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



4 No of Bedrooms 3

5 Business Use Water for Employees

6 Washing Machine (a) Yes (b) No

7 Garbage Disp (a) Yes X (b) No

8 Dishwasher (a) Yes (b) No

9 Water Supply
A Individual Well X
B Government
C Community
(a) Well
(b) Government
Sewage System
Have (a) public sewer (b) No
Have (a) community sewer (b) Yes (c) No

11 FHA Case No

12 VA Case No

(3) PLOT PLAN (ACCURATELY DIMENSIONED)

(13) NAME OF OWNER Gladden (LAST) Hubert (FIRST) James (MIDDLE)

(14) ADDRESS OF OWNER 734 Wilson Grove Rd

(15) PHONE NO Home 545-6533 Office 537-9831

(16) LOCATION OF SYSTEM Wilson Grove Rd (STREET OR COUNTY ROAD)

(17) SUBDIVISION _____ Lot No _____ Block No. _____

Map Book No 5 Page No. 345

(18) DEED REFERENCE — DEED BOOK 3531 AT PAGE 456

(19) HAS A PERCOLATION TEST BEEN RUN? (a) YES (b) NO DATE RUN _____

(20) PTR NUMBER (See Instructions) 7023

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

9-20-73
DATE OF APPLICATION

Hubert J Gladden
OWNER

FORM NO E-4-8-1-72

HEALTH DEPARTMENT'S COPY

Serial No. 3512

LA No. 7023

Date Issued October 12, 1973

T. C No. 137-109-15

Map Date 9-5-71

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Gladden (LAST) Hubert (FIRST) James (MIDDLE)

ADDRESS OF OWNER 7310 Wilson Grove Road ZIP 28212

LOCATION OF LOT Wilson Grove Road (STREET OR COUNTY ROAD)

SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

The above specified lot is approved by the Mecklenburg County Health Department for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the percolation test results which yielded a percolation rate of 60 min/inch on an on-site inspection of the said lot, and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 7023. This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered, and/or repaired in the same area where the percolation test was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed altered and/or repaired in accordance with a valid Installation, Construction Alteration, and/or Repair Permit

John R Robinson

Environmentalist

Director, Environmental Health Division or Authorized Section Head

FORM NO E-3-4-1-71

HEALTH DEPARTMENT'S COPY

Date Issued 11 JAN 74 **Serial No. 4695** ICAR(S) Permit No. 7023

T. C No

Map Date


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

INSTALLATION, CONSTRUCTION, ALTERATION, AND OR REPAIR PERMIT

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Permission is hereby given to ✓ Install or Construct, Alter or Repair the individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in application 7023, dated 9-20-73 and this permit shall be void and of no effect if the information provided in the application is not true or is erroneous. All work shall be completed on or before 11 Feb 74 after which date this permit shall be null and void.



PLOT OF SYSTEM

Percolation Rate 6-C

Liquid Capacity of Tank 1500 gal

Tank Construction Precast Concrete

Absorption and/or Nitrification Lines.

Total Line Lenght 600' & 150'

Number of Lines 5 12½' x 120'

Distance from House 10'+

Distance from Property Line 10'

Distance from Well 100'

NAME OF OWNER Gladden, Hubert James

LOCATION OF PROPERTY 7310 Wilson Grove Rd

The system shall meet all of the construction requirements as set forth in the Regulations of the Mecklenburg County Board of Health which are in effect on the date of the granting of this permit. A certificate of approval must be issued by the Health Director before any system can be covered up or otherwise rendered uninspectable or can be used.

Comments: water 7½' x 50'

aeration pit 2½' x 7' x 4' stone

*insure 2ft cover on low side

Division or Section Head

R. M. Reynolds
Environmentalist

* If this permit is for the installation or construction of a new system, it must be signed by the division or a section head of the Environmental Health Division in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired.

FORM NO E-5-4-1-71

HEALTH DEPARTMENT'S COPY

Date Issued 18 Feb 74 Serial 4446

C of A (s) No. 7023

T C No

Map Date

CERTIFICATE OF COMPLETION

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

CERTIFICATE OF APPROVAL

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Name of Owner Gladden, Hubert J. (LAST, FIRST, MIDDLE)

Location of Property 7310 Wilson Grove Rd

Application Number 7023 Permit Number 7023

Inspection Data:

Liquid Capacity of Tank 1500 gal Tank Material Precast Concrete

Total Length of Drain Tile 600' & 150' Number of Lines (5) 12½' x 120'

Depth of Filter Material 17" Cover Depth 15"

Water Supply Source well Distance from Water Source 100'

Excavation Inspected 18 Feb 74 (DATE) Tank Inspected 18 Feb 74 (DATE)

Nitrification Field Inspected 18 Feb 74 (DATE)

Washing Machine Line Inspected, If Applicable 18 Feb 74 (DATE)

The undersigned has inspected the Individual Septic Tank System with subsurface, soil absorption, effluent discharge as described above and it has been ✓ installed or constructed, ____ altered or repaired in accordance with the permit issued and the regulations of the Mecklenburg County Board of Health in effect on the date of issuance of the permit. The issuance of this Certificate of Approval does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling, or using such system from any liability resulting from the failure of the system to operate properly. This Certificate of Approval is issued subject to those restrictions and conditions shown on the permit(s) in addition to those listed below under comments. This Certificate of Approval shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

Comments: aeration pit O.K.

B. W. Reynolds
Environmentalist

FORM NO. E-6-4-1-71

HEALTH DEPARTMENT'S COPY