RECEIVED

Date Received 4-8-83 APR 13 1983

ENVIR. MENTAL HEALTH

SIR No. 19556

T. C. No. 111-115-03

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Dillard (LAST) James (FIRST) L. (MIDDLE)

2) ADDRESS OF OWNER 9832 Robinson Church Road, Charlotte, N. C. ZIP 28212

3) PHONE NO Home 535-3301 Office 535-3301


4) LOCATION OF PROPERTY Lot 6 & 7 Block F. Glenmac Rd. (STREET OR COUNTY ROAD)

5) SUBDIVISION Cedarbrook acres LOT NO 6 & 7 BLOCK NO _____

MAP BOOK NO 111-115-3 PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

James L. Dillard
OWNER

EHD-5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

SIR NO. 19556
T. C. NO. 111-115-03
DATE: 5-3-83

Mr. James L. Dillard
9832 Robinson Church Road
Charlotte, NC 28212

Re: Property located at Glenmac Road, Lots 6 & 7, Blk. F

Dear Mr. Dillard:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, please submit your proposals, in the form of plans and specifications, to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of a "Septic Tank Agreement Form" provided by this office.

If I may be of assistance, please feel free to call at any time.

Sincerely,

Mike Sexton

Michael A. Sexton
Environmentalist
On Premises Waste Disposal Section

Enclosure

EHD #37 (11-82)

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19556

T.C. NO. 111-115-03

(Ground Absorption Sewage Disposal)

OWNER: James L. Dellaval
ADDRESS: 9832 Pleasant Church Rd Charlotte N.C. 28212
PLAT NO: Lot 6 PO Lot 7
LOT SIZE: 33,541
LOCATION OF SITE: Pleasant Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 2 8%	(S) PS U 6-10%	(S) PS U 2-8%	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS (U) 2-1 clay	S (PS) U clay	S (PS) U clay	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U weak blocky	S (PS) U Blocky	S (PS) U Blocky	S PS U
4. SOIL DEPTH (inches)	S (PS) U 36-40"	S PS (U) ~~24-36"~~ 18-24"	S (PS) U 36-40"	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) U saprolite 36"+	S PS (U) saprolite 18-24"	S (PS) U saprolite 36"+	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S PS (U) perched water 24-36"	(S) PS U >36" to ground water	S (PS) U >36" to ground water	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS (U) Restrictive Area	S PS U
8. SOIL GROUP	IIB	IIA	IIB	
9. SITE CLASSIFICATION	unsuitable	unsuitable	unsuitable	
10. SOIL SERIES	Helena-Lilla	Parelot Lilla	Cecil Lilla	

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments:

Described by: William B. Marlin
Title: Soil Scientist

Date: 4-28-83

EHD 539 (Revised: 6/82)

2


Cecil-Like
150'
Glenmar Rd
Pacolet-Like
225'
225'
Helena Like
150'