Date Received 10/24/79

APT No 16264

T C. No 108-082-02

Map Date 5/23/79

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Brumble (LAST) William (FIRST) Bruce (MIDDLE)

2) ADDRESS OF OWNER 2115 Ladurnum Ave ZIP 28205

3) PHONE NO Home 377-1456 Office


4) LOCATION OF PROPERTY Myra Way (STREET OR COUNTY ROAD)

5) SUBDIVISION White Street LOT NO 39 BLOCK NO

MAP BOOK NO 7 PAGE NO 695

6) DEED REFERENCE DEED BOOK 3111 PAGE NO 155

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on-site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

W. B. Brumble.
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

S. I. R. #16264
T. C. # 108-082-02

(Proposed Description Sewage Disposal)

OWNER William B. BRUMBLE DATE PROPOSED 10-24-79
ADDRESS 215 LABURNUM AVE PLAT NO.
COUNTY CHARLOTTE LOT SIZE 20,000
LOCATION OF SITE MYRA WAY LOT 39

FACTORS		AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S	2-10			
	PS				
	U				
2. SOIL TYPE (12-36 in.) (Sandy loamy clay/clay 2:1 Clay)	S				
	PS	clay			
	U	Saprolite			
3. SOIL STRUCTURE (12-36 in.) (Granular Soils)	S				
	PS	MASSIVE			
	U				
4. SOIL DEPTH (In.)	S				
	PS	48			
	U				
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S				
	PS	Saprolite			
	U				
6. SOIL WETNESS/GROUNDWATER (External & Internal)	S				
	PS	SLOW			
	U				
7. SOIL PERMEABILITY (Percolation Rate)	S				
	PS	SLOW			
	U				
8. OTHER (Specify)	S				
	PS				
	U				
9. SITE CLASSIFICATION		Unsuitable			
SOIL SERIES		WILKES			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* Site Plan on Back (Include Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc.)

Recommendations/Comments

Described By: W. B. Ramsey
Title: Soil Scientist Date: 10-31-79

DHS Form 2691
Sanitation
Rev. 530 (7/79)

2



LOT # 39

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16264

T.C. # 108-082-02

DATE November 2, 1979

NAME OF OWNER Brumble, William B.

ADDRESS OF OWNER 2115 Laburnum Avenue, Charlotte, NC 28205

LOCATION OF LOT Myra Way, Lot 39

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Atkisson

John R. Adkisson, Environmentalist