Date Received 5/ /72

APT No. 2416

T C No. [illegible] 03

Map Date [illegible]

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER GRIFFIN (LAST) STEVEN (FIRST) A. (MIDDLE)

2) ADDRESS OF OWNER RT 9 BOX 216E CHARLOTTE ZIP 28208

3) PHONE NO Home 399-[illegible] Office [illegible]


4) LOCATION OF PROPERTY SIMPSON RD. (STREET OR COUNTY ROAD)

5) SUBDIVISION LAKE ACRES LOT NO 10 BLOCK NO. E

MAP BOOK NO. E PAGE NO 273

6) DEED REFERENCE DEED BOOK 2[illegible] PAGE NO 401

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on-site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



OWNER

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 23 1973 APT NO. 1244

Owner [illegible] T.C. 433-1257

Location of Property [illegible]

Soil Suitability Ratings

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	[illegible]	[illegible]		
2. Soil Slope	[illegible]	[illegible]		
3. Soil Depth	[illegible]	[illegible]		
4. Soil Texture	[illegible]	[illegible]		
5. Soil Structure	[illegible]	[illegible]		
6. Restrictive Horizons				
7. Soil Drainage	[illegible]	[illegible]		
8. Soil Permeability (Percolation Rate)	[illegible]	[illegible]		
9. Other	[illegible]	[illegible]		
10. Overall Rating	[illegible]	[illegible]		

Recommendations [illegible]


Soil Engineer [illegible]

William R. Marsh

WEC

3/12/73

DIAGRAM OF PROPERTY



3/18/75

EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 5-27-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12416
T.C. NO. 033-075-03
MAP DATE _____

NAME OF OWNER Griffin, Steven A.

ADDRESS OF OWNER Rt.9, Box 217 E, Charlotte, NC 28208

LOCATION OF LOT Simpson Road, Lot 10, Block E

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Permeability Unsuitable.

Percolation rate in excess of 200 min/in.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
END 398
8/74

FORM NO.
E-11-8-21-74

WELL RECORD

Atkinson [redacted]

Well Permit No. _____

MAIL COMPLETED FORM TO: WELL WATER SUPPLIES

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

1200 BLYTHE BOULEVARD, CHARLOTTE, N. C. 28203

Drilling Contractor LASSITER WELL DRILLING CO.

1. Location of property Rhyne Rd.
2. Name of owner ~~Jerry Barefoot~~ Mattick, M.J.

   Address 5532 Wilkinson Blvd., Charlotte, N. C. ~~28208~~
3. Does this well replace an existing well? _____
4. Topography (circle one): draw slope, hilltop, valley, flat
5. Use of well res. Date completed 6-21-77
6. Rig type or method air Total depth 126
7. Casing:

	Depth		Inside Diam.	Wall thick. or Wt. ft.	Type
From	0	to 63 ft	2	in.	

8. Grout:

	Depth		Material	Method
From	0	to 20 ft.	cement	poured

9. Other Uses: Depth _____ Diameter _____

   No. holes drilled and abandoned _____
10. Water zones (depth and gpm) _____

    Static water level 20 ft. above / below top of casing

    which is _____ ft. above land surface. Elev. _____

    Date _____
12. Yield (gpm) 6 Method of testing air
13. Pumping water level: _____ ft. after _____ hrs.

    at _____ gpm.
14. Water quality clear Temperature (°F) _____
15. Well sterilization method HTH
16. Permanent pump: _____ Type _____ Make _____

    Installed - Date _____ By _____

    Capacity _____ gpm. Hp _____ TDH _____

    Intake depth _____ Airline depth _____
17. Remarks: _____

DRILLING LOG

Depth From	To	Formation
0	63	red & white dirt
63	126	Grey granite

MECK COUNTY DEPARTMENT OF RECEIVED ENVIRONMENTAL HEALTH

I do hereby certify that this well record is true and exact.

VL/bps

SIGNATURE OF CONTRACTOR OR AGENT

EHD-5-76