b

Date Received 6-12-73 APT No. 6425

T. C. No. _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

NAME OF OWNER CAMPBELL (LAST) LEROY (FIRST) (NMI) (MIDDLE)

ADDRESS OF OWNER 277 W. LAPORTE DR. CHARLOTTE N.C. ZIP 28216

PHONE NO. Home 399-0624 Office _____


LOCATION OF PROPERTY 2822 HART ROAD (STREET OR COUNTY ROAD)

SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

DEED REFERENCE: DEED BOOK 3339 PAGE NO. 202

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



ACCURATELY DIAGRAM & DIMENSION LOT

Leroy Campbell
OWNER

FORM NO. E-1-7-1-70

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health

1200 Blythe Boulevard
Charlotte, North Carolina 28203
Telephone 374-2113

Date Issued
1. 7-9-73
2. _____
3. _____

SDR No. 6475
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Leroy Campbell

ADDRESS OF OWNER 277 W. LaPorte Drive, Charlotte ZIP 28216

LOCATION OF LOT 2822 Hart Road

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	7-6-73	300+ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

X ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) The soils are high in content of very firm and plastic clay (presence of swelling clay minerals indicated). The soil series is Lnon. The soils are slowly permeable and have slow percolation rate. No suitable area was located for installation of a system.

W. Cecil Lyon, Jr.
Soil Scientist

_____
Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70