Date Received 7-13-83

RECEIVED
JUL 12 1983
ENVIRONMENTAL HEALTH

SIR No. 19890
T.C. No. 033-111-07

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Hough (LAST) Ronald (FIRST) Duane (MIDDLE)

2) ADDRESS OF OWNER Rt 9, Box 213, Charlotte, N.C. ZIP 28214

3) PHONE NO. Home 393-1903 Office 332-7162

4) LOCATION OF PROPERTY Mt Holly-Huntersville Road (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO 3558 PAGE NO ~~167~~ 549 6669 6671

6) DEED REFERENCE DEED BOOK 4281 PAGE NO 6671

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge

(See attached map)

7) ACCURATELY DIAGRAM & DIMENSION LOT

Ronald E. Hough
OWNER

EHD-5-76

Environmental Health Department's Copy

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 19890
T.C. NO. PO 033-111-07
DATE: 7-26-83

Mr. Ronald D. Hough
Route 9, Box 213
Charlotte, NC 28214

RE: Property located at Mount Holly - Huntersville Road

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, please submit your proposals, in the form of plans and specifications, to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreement Form" provided by this office.

If I may be assistance, please feel free to call.

Sincerely,

for John R Adkisson
Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19840

T.C. NO. P0033-111207

(Ground Absorption Sewage Disposal)

OWNER: Ronald D. Haigh
ADDRESS: Rt. 2, Box 213 Charlotte NC 28214

PLAT NO:
LOT SIZE: 22,500

LOCATION OF SITE: Mr. Holly Huntersville Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S 2 6% PS U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S 12-36" PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S Saprolite PS 12-36" U Rock Stones	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S PS 7-36" Perched water U	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	III A			
9. SITE CLASSIFICATION	Unsuitable			
10. SOIL SERIES	Cat Area			

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments:

Described by: William A. Martin
Title: Soil Scientist

Date: 7-25-83

EHD 539 (Revised: 6/82)

2H


Mt. Holly - Huntersville Road
150'
150'
Existing Building