Date Received 9/8/77

APT No. 14522

T. C. No. 105-222-09

Map Date 3-1-77

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Keen (LAST) J. (FIRST) Donald (MIDDLE)

2) ADDRESS OF OWNER 321 Hillside Ave ZIP 28209

3) PHONE NO Home 372-9292 Office 559-2287


4) LOCATION OF PROPERTY 9001 Fairview Rd. Off Plaza Rd Ext.
(STREET OR COUNTY ROAD)

5) SUBDIVISION Northeast Mobile Home City LOT NO 30 BLOCK NO
See attached

MAP BOOK NO Print PAGE NO

6) DEED REFERENCE DEED BOOK PAGE NO

Applicant must notify the Mecklenburg County Department of Environmental Health for the construction of [illegible] for the purpose of [illegible] and for the installation of [illegible] sewage treatment [illegible] from [illegible]



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER J. D. Keen

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

(Ground Absorption Sewage Disposal)

APT 14522
PO 105-222-04
Lot #30

OWNER: Donald A. Keen
ADDRESS: 221 Hillcrest Dr.
COUNTY: Charlotte, N.C.
LOCATION OF SITE: Northwest Mobile Home Park - Off Freires Rd.

DATE REQUESTED:
PLAT NO.:
LOT SIZE: 5,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U — 2-10%	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS — 2-1 (U) — Clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S PS — Massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) — 48" PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	(S) PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) — 36" to ground PS — water U	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S — slow → PS — & slow (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS — See Note (U)	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable			
SOIL SERIES	Enon			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: *Drainfield from existing system runs across lot.

Described By: William B. Marlin

Title: Soil Scientist Date: 9-25-96

DHS Form 2601 (2/77)
Sanitation

#2

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1700 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 14522
T.C. NO. P.O. 105-222-09
MAP DATE 3-1-77
DATE 10-2-78

NAME OF OWNER Keen, J. Donald

ADDRESS OF OWNER 221 Hillside Avenue, Charlotte, NC 28209

LOCATION OF LOT 9001 Faires Road, Lot 30, Northeast Mobile Home Park

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil Structure Massive.
Soil Permeability Unsuitable.
Site Classification Unsuitable - Drainfield from existing system crosses lot.

John R. Adkisson

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

EHD 3'9
7/.7

R