Date Received 7-10-84

RECEIVED
JUL 10 1984
ENVIRONMENTAL HEALTH

SIR No. 212145
T. C. No. 001-281-27
Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Alten (LAST) Charles (FIRST) Raymond (MIDDLE)

2) ADDRESS OF OWNER 307 Caulwood DR - Charlotte, NC, ZIP 28214

3) PHONE NO. Home 399-3565 Office 825-3628

4) LOCATION OF PROPERTY Claiborne DR - Near Corner (STREET OR COUNTY ROAD) Balmoral DR.

5) SUBDIVISION Lake Norman - Meck - Neck. LOT NO 234 A BLOCK NO. Section E

MAP BOOK NO 17 PAGE NO 625

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

[signature]
OWNER

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 2 13 15

T.C. NO. PC 001-362-49A

(Ground Absorption Sewage Disposal)

OWNER: Charles R. Austin
ADDRESS: 301 Coulwood Dr.
Charlotte, N.C. 28214
LOCATION OF SITE: Clairvaux Dr. & Balmoral

PLAT NO: 234A Sect. 6
LOT SIZE: 30,100 .69

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S [illegible] / PS / U	S Complex / PS Slopes / U Stream	S / PS / U	S / PS / U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S / PS Clay / U	S / PS Clay / U	S / PS / U	S / PS / U
3. SOIL STRUCTURE (12-36 inches)	S / PS Blocky / U	S / PS Blocky / U	S / PS / U	S / PS / U
4. SOIL DEPTH (inches)	S / PS [illegible] / U	S / PS [illegible] / U	S / PS / U	S / PS / U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S / PS 730" / U	S / PS 230" / U	S / PS / U	S / PS / U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S 730" / PS To ground water / U	S Eroded / PS Areas / U Channel Runoff	S / PS / U	S / PS / U
7. OTHER (Specify)	S Somewhat / PS [illegible] / U Area	S / PS / U	S / PS / U	S / PS / U
8. SOIL GROUP	10A	10A		
9. SITE CLASSIFICATION	Provisionally Suitable	Unsuitable		
10. SOIL SERIES	Cecil Like	Complex Slopes		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: Consistent limited area - recommend plans for house system & well locations be submitted

Described by: William C. Martin
Title: Soil Specialist

Date: [illegible]

1+



Balmoral Dr.
100'
83
temples
slopes
218'
Terrace
Head
148'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 21215
T.C. NO. PO 001-382-49A
DATE: 8-28-84

Charles R. Auten
307 Coulwood Drive
Charlotte, NC 28214

RE: Property located at Claiborne Dr. & Balmoral Dr.

Dear Mr. Auten:

At your request, a field investigation was conducted on the property designated above. The soils on the property were found to contain a limited area of provisionally suitable soil for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit plot plans for the proposed construction, well, and ground absorption sewage disposal system to this office. They will be reviewed and if it is found that there is an adequate area of provisionally suitable soil to accommodate the proposed installation, an Improvements Permit will be issued by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure