Date Received 10/5/94 Apt No (S) Application No (W) 8199

T C No. 053-015-19

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
APPLICATION FOR WELL WATER SUPPLY PERMIT

NAME OF OWNER Shepherd, Jerry C.
LAST FIRST MIDDLE

ADDRESS OF OWNER Rt. 14, Box 305, Chas. ZIP 28214

PHONE NO Home 399-7765 Office


LOCATION OF PROPERTY Rhyne Rd.
STREET OR NEAREST ROAD

WELL CONTRACTOR Unknown LICENSE NO

Application is made to the Mecklenburg County Department of Environmental Health for a permit to drill a water well on the property described below to be used as a source of X individual semi-public public water supply

10-3-94
DATE OF APPLICATION

Jerry C Shepherd
OWNER



ACCURATELY DRAWN TO SCALE OR DIMENSIONED

Application approved and permit hereby granted

Permit No

ENVIRONMENTALIST

Environmental Health Department's Copy

Date Received 7-5-74

APT No 8199

T C No

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

NAME OF OWNER Barefoot (LAST) Jerry (FIRST) C. (MIDDLE)

ADDRESS OF OWNER Route 14, Box 325, Charlotte, N. C. ZIP 28208

PHONE NO Home 394-2259 Office 399-7765


LOCATION OF PROPERTY Southwest cornor of Rhyne Rd, and Chapelton Drive (city #1833)
(STREET OR COUNTY ROAD)

SUBDIVISION LOT NO BLOCK NO

MAP BOOK NO 053 PAGE NO 015 14 (Tax Maps)

DEED REFERENCE DEED BOOK 3497 PAGE NO 445

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Jerry C. Barefoot

FORM NO. E-1-7-1-70

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. 7-18-74
2. _____
3. _____

SDR No. 8199
T.C. No. 055-015-19

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER barefoot, Jerr[illegible]

ADDRESS OF OWNER [illegible] ZIP 28208

LOCATION OF LOT Rhyne Road and Chapelton Drive

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	7-	24 1+ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

_____

_____

_____

_____
Environmentalist

(Stencil No.)
EHD 398
8/70

FORM NO.
E-19-8-14-70

MECKLENBURG COUNTY HEALTH DEPARTMENT

INTER-OFFICE COMMUNICATION

DATE July 22, 1974

TO J. R. Adkisson
Environmentalist

FROM W. Everette Lynn, Jr. WEL
Soil Scientist

SUBJECT APT #8199 (J. C. Barefoot
Rhyne Road
7-19-74

The lot consists of soils of the Enon series and soils intergradient between the Cecil and Mecklenburg series.

The Enon soils occur on the rear portion of the property (away from Rhyne Road). These soils have plastic and sticky clay subsoils which contain expanding clay minerals. These soil characteristics result in inadequately slow permeability and percolation rate.

The intergradient soils occur on the front portion of the property (adjacent to Rhyne Road). These soils show indications of containing a small amount of expanding clay minerals. This soil characteristic results in limited permeability and percolation rate (true mean perc. rate of 120 min./in.).

Based on this investigation, it is recommended that the lot be granted conditional approval for installation of a septic tank system. The system should be located in the area of intergradient soils as indicated on the "Percolation Test Report". System design should be based on a 120 min./in. perc. rate.

WEL:lar

Serial No. 4555

PTR No 8199

Date Issued [illegible]

T C No 053-015-19

Map Date

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER Barefoot (LAST) Jerry (FIRST) C. (MIDDLE)

ADDRESS OF OWNER Route 14, Box 325 ZIP 28208

LOCATION OF PROPERTY Mayne Rd. and Chapelton Dr.

SUBDIVISION LOT NO. BLOCK NO.



[illegible] in/hr*

[illegible] for the [illegible]

[illegible] and regulations [illegible] completion of the [illegible] have been given [illegible] the [illegible] and regulations governing [illegible] date

*Results determined by soil analysis.

Director Environmental Health Division or Authorized Section Head

FORM NO E-2 [illegible] Soil Scientist

HEALTH DEPARTMENT, S. C.

Date Received [illegible]

ICARUS Application No 8199


TCN 053-015-19

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge

[illegible] applies to the Mecklenburg County Health Department for a permit to [illegible] Alter or Repair an individual [illegible] treatment [illegible] effluent discharge



3 PLOT PLAN AS DRAWN BY OWNER

1. NAME OF OWNER [illegible]
2. ADDRESS OF OWNER R. 14, Box 325, Chas. S C
3. PHONE NO. Home 399 7165T Office
4. LOCATION OF SYSTEM Johnie Rd At Charleston Dr
5. SUBDIVISION [illegible] Block No
   Map Book No Page No
6. DEED REFERENCE DEED BOOK AT PAGE 5057 122
7. HAS A PERCOLATION TEST BEEN RUN? YES NO DATE RUN
8. [illegible] NUMBER [illegible] 5 [illegible]

[illegible] the above facts are true

DATE OF APPLICATION 9-27-76

OWNER [illegible]

E-4-9-1-72

HEALTH DEPARTMENT'S COPY

Date Issued 9/29/76

Serial No. 0195

IMPROVEMENTS PERMIT

LA No. 8199

T C No 053-015-19

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Barefoot Tappy
LAST FIRST MIDDLE

ADDRESS OF OWNER Route 14, Box 325, Charlotte, N. C. ZIP

LOCATION OF LOT Rhyne Road
STREET OR COUNTY ROAD

SUBDIVISION Woodland Park LOT NO BLOCK NO

MAP BOOK NO PAGE NO

This property is approved by the Mecklenburg County Department of Environmental Health for the installation of an individual septic tank system with subsurface soil absorption effluent discharge. This approval is based upon an on-site investigation of the soil and upon the information supplied in the Application for Installation Construction, Alteration and/or Repair Permit" number 8199 and is subject to the following terms and conditions:

1. The septic tank system shall be installed in the soil and at the location and approximate depth as were found suitable when the soil investigation was run.

2. The Installation Construction, Alteration and/or Repair Permit issued by the Building Inspection Department shall specify that the septic tank system is installed in accordance with these terms and conditions and in accordance with the Mecklenburg County Sanitary Code.

The owner is responsible for and the building inspection department is prohibited from issuing any permit which would result in authorizing the construction of this subdivision, time of application, for a permit in the area covered by this approval unless the septic tank system can be installed, operated and repaired in accordance with a valid Installation Construction, Alteration, and/or Repair Permit.

Environmentalist

Date

John R. Atkinson
Section Head

Environmental Health Department's Copy

Serial No. 6 ICAR(S) Permit No 8199

Date Issued

T C No 053-015-14


Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

INSTALLATION, CONSTUCTION, ALTERATION, AND/OR REPAIR PERMIT

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Permission is hereby given to Install or Construct Alter or Repair the individual septic tank waste-water treatment system with subsurface soil absorption effluent discharge at the de- ... This permit is granted based upon the information supplied in application 8199 ... in effect if the information provided in the ap- ... completed on or before after which ...



... must be signed by the division ... of the Department of Environmental Health in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired.

Department's Copy

Date Issued 22 Nov 76

Serial No. 0334

C of A (s) No 8199

T C No C 5 3 015-19

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
ENVIRONMENTAL HEALTH DIVISION

John R Adkinson

CERTIFICATE OF COMPLETION **CERTIFICATE OF APPROVAL**

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Name of Owner [illegible] (LAST) [illegible] (FIRST) C (MIDDLE)

Location of Property [illegible]

Application Number S 19[illegible] Permit Number S [illegible]

Inspection Data:

Liquid Capacity of Tank 1250 Tank Material [illegible]

Total Length of Drain Tile 60' x 3 = 180' Number of Lines 3 (2 x 60' & 1 x 30')

Depth of Filter Material 24" Cover Depth 18" - 24"

Water Supply Source Well Distance from Water Source 75'

Septic Tank Inspected 22 Nov 76 (DATE) Tank Inspected 22 Nov 76 (DATE)

Distribution Box Inspected 22 Nov 76 (DATE)

Washing Machine Inspected If Applicable 22 Nov 76 (DATE)

This is to certify that the Individual Septic Tank System with Subsurface Soil Absorption and Effluent Discharge installed at this premises [illegible] in accordance with the permit issued by the Mecklenburg County Health Department. This certificate is issued for the purpose of [illegible] and is not to be construed as a guarantee of the system's performance. The Certificate of Approval shall be void if any alterations are made to the system which would affect the requirements for which it was issued.

Comments Final Insp (Carter)

Environmentalist

EHD-5-76

Environmental Health Department's Copy

THE END OF

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH

DIVISION

"INDIVIDUAL SEPTIC TANK SYSTEMS"

RECORDED IN NUMERICAL ORDER

BY FILES