Date Received 9-7-72

APT No. 6080

T. C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Dellinger, Madison & Associates, Incorporated
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER 121 Greenwich Road, Room 207, Charlotte, NC ZIP 28211

3) PHONE NO. Home --- Office 364-7155


4) LOCATION OF PROPERTY Windwood Circle
(STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle LOT NO. 24 BLOCK NO. 1

MAP BOOK NO. PAGE NO.

6) DEED REFERENCE: DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Douglas Madison
OWNER

FORM NO. E-1-11-1-70

HEALTH DEPARTMENT'S COPY

Date Received 4.2013

APT No. 6080

T C No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Henkel (LAST) Charles (FIRST) L. (MIDDLE)

2) ADDRESS OF OWNER 1011 White Plains Road, Charlotte,N.C. ZIP 28213

3) PHONE NO Home 596-3373 Office 377-6656


4) LOCATION OF PROPERTY Windwood Circle off Carmel Road (STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle LOT NO. 24 BLOCK NO.

MAP BOOK NO 1698 PAGE NO 511

6) DEED REFERENCE DEED BOOK 1783 PAGE NO 96

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Charles L Henkel
OWNER

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

SEE INSTRUCTIONS ON BACK

Date Received 4-20-73

ICAR(S) Application No 6080

T C No

Map Date


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge

The owner of the property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

1) X Install or Construct 2) ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No of Bedroom 3

5) Business Use Max No Employees

6) Washing Machine X Yes No

7) Garbage Disposal Yes X No

8) Dishwasher X Yes No

9) Water Supply
A) Individual Well
B) Government
C) Community System
1) Well source
2) Government
Sewage System
If not located within 2 years of public sewer Yes X No
If not located within 2 years of community sewer Yes X No

11) FHA Case No

12) VA Case No

13) NAME OF OWNER Henkel (LAST) Charles (FIRST) L. (MIDDLE)

14) ADDRESS OF OWNER 1011 White Plains Road, Charlotte, N.C. 28213

15) PHONE NO Home 596-3373 Office 333-8475

16) LOCATION OF SYSTEM Windwood Circle off Carmel Road (STREET OR COUNTY ROAD)

17) SUBDIVISION Windwood Circle Lot No 24 Block No

Map Book No 1698 Page No. 511

18) DEED REFERENCE — DEED BOOK 1783 AT PAGE 96

19) HAS A PERCOLATION TEST BEEN RUN? YES X NO DATE RUN

20) PTR NUMBER (See Instructions)

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

4/20/73
DATE OF APPLICATION

Charles L. Henkel
OWNER

FORM NO E-4-8-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. April 26, 1973
2. _____
3. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

SDR No. 6080
T.C. No. 209-253-51
2-23-72

NAME OF OWNER Henkel, Charles L.

ADDRESS OF OWNER 1011 White Plains Road ZIP 28213

LOCATION OF LOT Windwood Circle, Lot 24

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	[illegible]	222 min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

John R Atkisson
Environmentalist

(Stencil No.)
MHD 398
8/70

FORM NO.
E-19-8-14-70

Date Received 9-10-13

APT No 6080

T C No 209-253-51

Map Date 2-23-72

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Woodruff (LAST) John (FIRST) G. (MIDDLE)

2) ADDRESS OF OWNER 4225 Windwood Circle ZIP 28211.

3) PHONE NO Home 366-4257 Office None Retired.


4) LOCATION OF PROPERTY Windwood Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle LOT NO 84 BLOCK NO

MAP BOOK NO 1783 PAGE NO. 96

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER John G. Woodruff
John G. Woodruff.

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT

INTER-OFFICE COMMUNICATION

DATE: September 11, 1973

TO: Luther Bridgeman
Environmentalist

FROM: W. Everette Lynn, Jr. W. E. L.
Soil Scientist

SUBJECT: APT # 6080 (John Woodruff)
Windwood Circle, Lot No. 24
7/25/73

Soils were found to be of the Iredell and Wilkes series. These soils have very plastic and sticky clay subsoils which contain swelling clay minerals. The Iredell soils have a perched high water table during periods of high rainfall. The Wilkes soils are shallow to impervious weathered rock material. These factors result in inadequately slow percolation rate and permeability.

Based on these observations, it is recommended that the lot be disapproved for installation of a septic tank system.

WEL:dcr

Date Received 10-2-73

APT No 6080

T. C. No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

RECEIVED
OCT 02 1973
ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Woodruff (LAST) John (FIRST) G. (MIDDLE)

2) ADDRESS OF OWNER 4225 Windwood Circle ZIP 28211.

3) PHONE NO Home 366-4257 Office None retired.


4) LOCATION OF PROPERTY Windwood Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Windwood Circle LOT NO 24 BLOCK NO

MAP BOOK NO 1783 PAGE NO 96

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER John G. Woodruff
John G. Woodruff.

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

(Ground Absorption Sewage Disposal)

APT 6080
TC 209-253-51
LOT #24

OWNER: John D. Wedrick
ADDRESS: 516 Twinsham Ct.
COUNTY: Columbia, S.C. 29206
LOCATION OF SITE: Windwood Circle

DATE REQUESTED:
PLAT NO.:
LOT SIZE: 24,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS 4-15% U	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S 2-1 PS Loamy (U) clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S PS massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S variable PS 18-36" (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S saprolite PS @ 18-31" (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 48" PS To U ground water	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S V. slow PS (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable			
SOIL SERIES	Enoch ville. Wilkes Intergrade			

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: Lot evaluated at request of John D. Wedrick

Described By: William A. Martin

Title: Soil Scientist Date: 1-27-78

DHS Form 2601 (2/77)
Sanitation


125'
Irodell-
W. Mas
Intergrade
200'
200'
125'
Windwood Circle