

Old Statesville Rd.

1/29/08

thomatc

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

Date Received 2-1-84

MECK COUNTY DEPARTMENT OF
RECEIVED
FEB 1 1984
ENVIRONMENTAL HEALTH

APT No. 20586

T. C. No. PO 019-111-12

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Norris (LAST) Gary (FIRST) Lane (MIDDLE)

2) ADDRESS OF OWNER Route 1 Box 477 ZIP 28078

3) PHONE NO. Home 875-6214 Office 399-8352


4) LOCATION OF PROPERTY ~~Hwy. 115~~ or old Statesville Rd, (STREET OR COUNTY ROAD)

5) SUBDIVISION Huntersville LOT NO. BLOCK NO.

MAP BOOK NO. PAGE NO.

6) DEED REFERENCE: DEED BOOK 4552 PAGE NO. 0918

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Gary L. Norris
OWNER


EHD-5-76

Environmental Health Department's Copy

THIS IS TO CERTIFY THAT ON THE _____ DAY OF _____ 19____ I SURVEYED THE PROPERTY SHOWN ON THIS PLAT AND THAT THE TITLE LINES AND THE WALLS OF THE BUILDING ARE AS SHOWN HEREON; THAT THERE ARE NEITHER ANY ENCROACHMENTS BY THE WALLS OR PROJECTIONS OF THE BUILDINGS THEREON, ON THE STREETS OR ON THE ADJACENT PROPERTY; NOR ANY ENCROACHMENTS OF THE WALLS OR PROJECTIONS OF THE ADJACENT BUILDINGS UPON THE MORTGAGED PROPERTY.

SIGNED _____
Reg. Surveyor, State of North Carolina

Note: boundary surveyed Feb. 1958; division line surveyed April 14, 1982. E. R. Strain - N.C.R.S.



PD 614-111-12

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20586

T.C. NO. PO 014-111-12

(Ground Absorption Sewage Disposal)

OWNER: Gary L Norris
ADDRESS: Rt. 1 Box 477 Huntersville, N.C. 28078
LOCATION OF SITE: Highway 115

PLAT NO:
LOT SIZE: 52,500

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS 2-1 Clay (U)	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S 18-30" PS (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) 36" to saprolite (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) 36" to ground water U	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	HUB			
9. SITE CLASSIFICATION	unsuitable			
10. SOIL SERIES	Vance-like			

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments:

Described by: William B. Marlin
Title: Soil Scientist

Date: 2-13-84

EHD 539 (Revised: 6/82)

28


Vance-
Like
250'
210'
Railroad
Highway 115

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 20586
T.C. NO. PO 019-111-12
DATE: 2-14-84

Gary L. Norris
Route 1, Box 477
Huntersville, NC 28078

RE: Property located at Old Statesville Road

Dear Mr. Norris:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure