Date Received 5-21-84

SIR No. 2084

T.C. No. 97-141-01

Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER McDougle (LAST) Ronald (FIRST) H. (MIDDLE)

2) ADDRESS OF OWNER 3220 Sherwin Rd ZIP 28269

3) PHONE NO. Home 542-3520 Office 375-6611


4) LOCATION OF PROPERTY Indian Trail Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO 7 BLOCK NO _____

MAP BOOK NO 127 PAGE NO 14 Tract 01

6) DEED REFERENCE DEED BOOK 1861 PAGE NO 172

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Carson Realty Co. Inc.
Charles M. Carson Agent

OWNER Ronald H. McDougle

EHD-5-76

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 21494

T.C. NO. 21-0000-01

(Ground Absorption Sewage Disposal)

OWNER: Donald W. Pierce
ADDRESS: 1515 Cameron Dr
Charlotte, NC 28211
PLAT NO:
LOT SIZE: .52

LOCATION OF SITE: Indian Lake Road

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 2-7% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS Sandy Loam U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S 30"+ PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S 30"+ PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S Well drained PS U	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	2/6			
9. SITE CLASSIFICATION	Approved			
10. SOIL SERIES	Cecil			

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: 1 Bedroom min. 4" Gravel

Described by: William J. Martin
Title: Soil Scientist

Date: 4-17-84

2H


150'
150'
Indian Trail
Rd

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 21084
T.C. NO. PO 197-141-01
DATE: 7-20-84

Anabel H. McDougle
2220 Inverness Road
Charlotte, NC 28208

RE: Property located at Indian Trail Road, Lot 9

Dear Ms. McDougle:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure