Date Received 5-6-83

MECK COUNTY DEPARTMENT OF
RECEIVED
MAY 6 1983
ENVIRONMENTAL HEALTH

SIR No. 19641

P.C. No. 049-083-20,21

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER JARRETT & ASSOCIATES
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 6535 OLDE SAVANNAH ZIP 28212

3) PHONE NO. Home 568-3303 Office SAME


4) LOCATION OF PROPERTY BLANCHARD CIR
(STREET OR COUNTY ROAD)

5) SUBDIVISION GLEN ECHO PARK LOT NO. PART OFF BLOCK NO. 2

MAP BOOK NO. B PAGE NO. 439 849

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER Jarrett & Assoc. by James C. Jarrett

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19641

T.C. NO. PO049-093-2021

(Ground Absorption Sewage Disposal)

OWNER: Jarrett & Associates
ADDRESS: 6575 Olde Savannah (Charlotte, 28212

PLAT NO: Part of Lots 9 & 9
LOT SIZE: 15,624

LOCATION OF SITE: Brandywine Circle

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-6% U	S (PS) 2-6% 6-20% U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS mixed Sandy loam clay U	(S) PS Sandy loam U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Massive (U)	S PS Massive (U)	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS Fill 24"-36" (U)	S PS saprolite @ soil surface (U)	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS compacted Fill (U)	S PS saprolite @ soil surface (U)	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) >36" to ground water U	S (PS) >36" to ground water U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IUA	IUA		
9. SITE CLASSIFICATION	unsuitable	unsuitable		
10. SOIL SERIES	Fill	cut		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: _____

Described by: William A. Taylor
Title: Soil Scientist

Date: 5-16-93

EHD 539 (Revised: 6/82)

2

80'
Tar
191'
Fill
Brandhill
80'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
[illegible]
CHARLOTTE, [illegible]

SIR. NO. 19641
T. C. NO. PO 049-093-20,21
DATE. 5-17-83

Jarrett & Associates
6535 Olde Savannah Road
Charlotte, NC 28212

Re: Property located at Branchhill Circle, Lots 8 & 9

Dear Mr. Jarrett:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, please submit your proposals, in the form of plans and specifications, to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of a "Septic Tank Agreement Form" provided by this office.

If I may be of assistance, please feel free to call at any time.

Sincerely,

for John A. Jackson
Michael A. Sexton
Environmentalist
On Premises Waste Disposal Section

Enclosure

EHD #37 (11-82)