Date Received 28 Feb 1972

APT No 5675

P.O.T C No 209-253-25

Map Date 2-23-72

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Blanchard, (LAST) Andrew (FIRST) James (MIDDLE)

2) ADDRESS OF OWNER 5705 Carmel Rd., Charlotte, N.C. ZIP 28211

3) PHONE NO Home 366-1473 Office ____


4) LOCATION OF PROPERTY Glen Forest Dr. (STREET OR COUNTY ROAD)

5) SUBDIVISION ____ LOT NO ____ BLOCK NO. ____

MAP BOOK NO ____ PAGE NO ____

6) DEED REFERENCE DEED BOOK 209 PAGE NO 253 LOT - 25

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and on on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

OWNER A. J. Blanchard

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

Serial No. 4

PTR No. 5675
P.O.
T C No. 209-253-25
Map Date 2-23-72

Date Issued March 16, 1973

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER Reynolds (LAST) Elaine (FIRST) Blanchard (MIDDLE)

ADDRESS OF OWNER 5625 Carmel Road ZIP 28211

LOCATION OF PROPERTY Glen Forest Drive (STREET OR COUNTY ROAD)

SUBDIVISION LOT NO BLOCK NO.



PLOT PLAN

This is to certify that a percolation test has been run and an on site inspection made by the Mecklenburg County Health Department on the lot described above. The said test was conducted on that portion of the lot as indicated on above plat.

The percolation rate determined by the test was 56 min/in. The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install, construct, alter, or repair the specific system shall be obtained from the Mecklenburg County Health Department prior to the beginning of any construction of buildings, or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater treatment system which must be installed will be determined by the Health Department prior to installation based on the percolation rate obtained above and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area where the percolation test was run.
4. This approval is void if any grading, filling, or construction (including the driving of a well) is performed on the lot which, in the opinion of the Health Department, renders the area where the percolation test was run unsuitable for the installation, construction, alteration, and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina State Board of Health and the Mecklenburg County Board of Health which were in effect on the date of issuance and is void if at any time in the future, prior to the completion of the system, these laws, rules, and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

John R. Johnson

Director, Environmental Health Division or Authorized Section Head

FORM NO. E-2-4-1-71

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203 Telephone 374-2113

Date Issued
1. March 5, 1973 SITE DISAPPROVAL REPORT SDR No. 5675
2. _____ INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE, T.C. No. P.O. 209-253-25
3. _____ SOIL ABSORPTION, EFFLUENT DISCHARGE 2-23-72

NAME OF OWNER [illegible], Andrew James

ADDRESS OF OWNER 5725 Carmel Road ZIP 28211

LOCATION OF LOT Glen Forest Drive

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
X	1.	3-2-73	240 min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) _____

John R Atkisson
Environmentalist

(Stencil No.)
END 398
8/70

FORM NO.
E-19-8-1A-70

Date Received 2 28 73

ICAR(S) Application No. 5625

P.O. T C No 209-253-25

Map Date 2-23-72


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to

1) X Install or Construct 2) ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No. Bedrooms 4

5) Business Use Max No Employees ___

6) Washing Machine X Yes ___ No

7) Garbage Disposal ___ Yes X No

8) Dishwasher X Yes ___ No

9) Water Supply
- A Individual Well X
- B Governmental System ___
- C Community System
  - 1 Well source ___
  - 2 Governmental source ___

10) Sewage System
House located within 200 feet of public sewer ___ Yes X No
House located within 200 feet of community sewer ___ Yes ___ No

11) FHA Case No ___

12) VA Case No ___

13) NAME OF OWNER Reynolds (LAST) Elaine (FIRST) Blanchard (MIDDLE)

14) ADDRESS OF OWNER 5625 Clearmont Dr, Char N.C. 28211

15) PHONE NO Home 366-9177 Office 399-6211

16) LOCATION OF SYSTEM Glen Forest Dr (STREET OR COUNTY ROAD)

17) SUBDIVISION ___ Lot No. ___ Block No. ___

Map Book No ___ Page No. ___

18) DEED REFERENCE — DEED BOOK ___ AT PAGE ___

19) HAS A PERCOLATION TEST BEEN RUN? ___ YES ___ NO DATE RUN ___

20) PTR NUMBER (See Instructions) 5675

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

28 Feb 1973
DATE OF APPLICATION

Elaine Blanchard Reynolds
OWNER

FORM NO E-4-4-[illegible]

HEALTH DEPARTMENT'S COPY

Date Issued March 16, 1973

Serial No. 2618

LA No. 5675
P.O.
T C No. 209-253-25

Map Date 2-23-72

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Reynolds (LAST) Elaine (FIRST) Blanchard (MIDDLE)

ADDRESS OF OWNER 5625 Carmel Road ZIP 28211

LOCATION OF LOT Glen Forest Drive (STREET OR COUNTY ROAD)

SUBDIVISION _____ LOT NO. _____ BLOCK NO _____

MAP BOOK NO _____ PAGE NO _____

The above specified lot is approved by the Mecklenburg County Health Department for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the percolation test results which yielded a percolation rate of 56 min/in on an on-site inspection of the said lot, and upon the information supplied in the "Application for an Installation Construction, Alteration, and/or Repair Permit" number 5675. This approval is subject to the following terms and conditions.

1. That the nitrification field be installed, constructed, altered, and/or repaired in the same area where the percolation test was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction Alteration, and/or Repair Permit.

John R Adkisson
Environmentalist

Director, Environmental Health Division or Authorized Section Head

FORM NO E-3-4-1-71

HEALTH DEPARTMENT'S COPY

Date Issued 5/30/73

Serial No. 3783

ICAR(S) Permit No. 5675

T C No ________

Map Date ________


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

INSTALLATION, CONSTRUCTION, ALTERATION, AND OR REPAIR PERMIT

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Permission is hereby given to X Install or Construct, * Alter or Repair the individual septic tank waste-water treatment system with subsurface soil absorption effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in application ________, dated 2/28/73 and this permit shall be void and of no effect if the information provided in the application is not true or is erroneous. All work shall be completed on or before ________ after which date this permit shall be null and void.



PLOT OF SYSTEM

Percolation Rate 56 mp.

Liquid Capacity of Tank 1500

Tank Construction PC

Absorption and/or Nitrification Lines:

	ST	WM
Total Line Lenght	795'	150
Number of Lines	10	3
Distance from House	10	10
Distance from Property Line	10' min	
Distance from Well	100'	

NAME OF OWNER Elaine Reynolds

LOCATION OF PROPERTY 5500 Blk Glen Forest Dr.

The system shall meet all of the construction requirements as set forth in the Regulations of the Mecklenburg County Board of Health which are in effect on the date of the granting of this permit. A certificate of approval must be issued by the Health Director before any system can be covered up or otherwise rendered uninspectable or can be used.

Comments: Washer-Pit 7½' x 25' x 3' stone

C. Morrison – 6/10/73

RLMc/LRB
Division or Section Head

[signature]
Environmentalist

* If this permit is for the installation or construction of a new system, it must be signed by the division or a section head of the Environmental Health Division in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired.

FORM NO. E-5-4-1-71

HEALTH DEPARTMENT'S COPY

Date Issued 6/3/[illegible]

Serial No. 3426

C of A (s) No. 5675

T C. No. _____

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

CERTIFICATE OF APPROVAL

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Name of Owner REYNOLDS (LAST) ELAINE (FIRST) _____ (MIDDLE)

Location of Property [illegible] GLEN FOREST DR.

Application Number 5675 Permit Number 5675

Inspection Date:

Liquid Capacity of Tank 1500 Tank Material PC

Total Length of Drain Tile 75'x10'x3'150 (7½x25'x3') Number of Lines 10 3

Depth of Filter Material 36" 3" Cover Depth _____

Water Supply Source WELL Distance from Water Source 200'

Excavation Inspected 6-7-73 (DATE) Tank Inspected 6-5-73 (DATE)

Nitrification Field Inspected 6-8-73 (DATE)

Washing Machine Line Inspected, If Applicable 6-7-73 (DATE)

The undersigned has inspected the Individual Septic Tank System with subsurface, soil absorption, effluent discharge as described above and it has been X installed or constructed, _____ altered or repaired in accordance with the permit issued and the regulations of the Mecklenburg County Board of Health in effect on the date of issuance of the permit. The issuance of this Certificate of Approval does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling, or using such system from any liability resulting from the failure of the system to operate properly. This Certificate of Approval is issued subject to those restrictions and conditions shown on the permit(s) in addition to those listed below under comments. This Certificate of Approval shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

Comments [illegible]

SOIL FAILURES TO IMPERMEABLE

[illegible] (Environmentalist)

FORM NO. E-6-4-1-71

HEALTH DEPARTMENT'S COPY