Date Received 1-10-84

MECK COUNTY DEPARTMENT OF
RECEIVED
JAN 10 '84
ENVIRONMENTAL HEALTH

SIR No. 20491

T.P. No. 019-191-14

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Locklear (LAST) John (FIRST) E (MIDDLE)

2) ADDRESS OF OWNER Rt #3 Box 218m Charlotte NC ZIP 28208

3) PHONE NO. Home 392-1137 Office _____


4) LOCATION OF PROPERTY OFF Holdbrook Rd. (STREET OR COUNTY ROAD) Huntersville NC

5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO. _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

John Locklear
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20491

T.C. NO. PO 019-191-14

(Ground Absorption Sewage Disposal)

OWNER: John F. Jacklin
ADDRESS: Rt. 9 Box 216 M
Charlotte, N.C. 28216
LOCATION OF SITE: off Hathaway Road

PLAT NO:
LOT SIZE: Approx 30,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U 2 8%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS (U) 2-1 Clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U Weak Blocky	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS (U) 6-20"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS (U) 6 30" To saprolite	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) U 7 36" To ground water	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IVB			
9. SITE CLASSIFICATION	unsuitable			
10. SOIL SERIES	Wilkes-Like			

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments: _____

Described by: William R. Moulin
Title: Soil Scientist

Date: 2-13-84

EHD 539 (Revised: 6/82)

2H


Holbrook Rd
Well
150'
90'
Existing Trailer

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 20491
T.C. NO. PO 019-191-14
DATE: 2-14-84

John F. Locklear
Route 9, Box 218-M
Charlotte, NC 28208

RE: Property located at Off Holdbrook Road

Dear Mr. Locklear:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreement Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure