

4702 MOUNTAIN POINT LN

02316214

5/29/2007

duponbj

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

N.C. Department of Environment and Natural Resources
Division of Environmental Health

Inspection of Engineered Subsurface Wastewater System

Mecklenburg County	Mowry Residence	4951A
Health Department	**Name of Establishment**	**Permit/Project No.**
4702 Mountain Point Lane	House	360
Location	**Type of Establishment**	**Design Flow**
Doug Mowry	4702 Mt. Point Lane	NA
Owner/Agent	**Address**	**Phone**
NA	NA	NA
Operator	**Address**	**Phone**
IIIb	9/15/09	September 2013
System Type	**Date of Inspection**	**Next Inspection Due**

	Yes	No	N/A	Comments:
1. ESTABLISHMENT:				
a. Type, size, and sewage flow in accordance with permit?	☒	☐	☐	
2. COLLECTION SYSTEM:				
a. No evidence of leaks into or out from sewer lines/manholes?	☒	☐	☐	
b. Free of blockages/solids buildup in lines or manholes?	☒	☐	☐	
3. TANKAGE: (Grease Traps/Lift Stations/Septic/Dosing Tanks)				
a. Tank risers accessible and surface water diverted?	☒	☐	☐	
b. Tanks and access manholes structurally sound, watertight?	☒	☐	☐	
c. Sanitary tee(s) in good working condition?.....	☐	☐	☒	3.c. Sanitary tee not inspected.
d. Tanks pumped, cleaned out as needed?.....	☒	☐	☐	
4. RAW SEWAGE LIFT STATION (if present):				
a. Required pumps present, operating, and cycling properly	☐	☐	☒	
b. High-water alarm present and operating properly?	☐	☐	☒	
c. Floats/pipe/valves/disconnects in good condition?	☐	☐	☒	
5. EFFLUENT DOSING SYSTEM:				
a. Effluent appears clear, free of excess solids?	☒	☐	☐	
A. PUMP SYSTEMS:				
a. Required pumps present, operating, and cycling properly?	☒	☐	☐	
b. High-water alarm present and operating properly?	☒	☐	☐	
c. Floats/pipe/valves/disconnects in good working condition?	☒	☐	☐	
d. Control panel enclosure/components in good condition?	☒	☐	☐	Recommend weather proof
e. Elapsed time readings: _____ _____ _____ _____				enclosure over electrical box.
B. SIPHON SYSTEMS:				
a. No evidence of overflow or siphon leakage?	☐	☐	☒	
b. Siphon(s) appear to be working/alternating properly?	☐	☐	☒	
c. Bells and vents free of debris and in good condition?	☐	☐	☒	

	Yes	No	N/A	Comments:
6. GROUND ABSORPTION FIELDS:				
a. No evidence of effluent surfacing/reaching surface waters?	☒	☐	☐	
b. Minimal ponding in subsurface trenches?	☒	☐	☐	
c. Surface water being effectively diverted away?	☒	☐	☐	
d. Diversions/ditches/swales/tiles drains properly maintained?	☒	☐	☐	
e. Line cover/vegetation adequate/maintained as needed?	☒	☐	☐	
f. Protected from traffic, destructive uses?	☒	☐	☐	
g. Distribution devices in good condition, working properly?	☒	☐	☐	
h. Repair area properly reserved, maintained?	☒	☐	☐	
A. LOW PRESSURE PIPE DRAIN FIELDS:				
a. Turnups/cleanouts/valves intact and accessible?	☐	☐	☒	
b. No effluent standing in lower laterals?	☐	☐	☒	
c. Laterals free of excess solids, cleaned out as needed?	☐	☐	☒	
d. Pressure head is properly adjusted?	☐	☐	☒	

OVERALL CONDITION AND OPERATION OF SYSTEM:

System appears to be functioning properly at time of inspection.

SUMMARY OF REPAIRS REQUIRED AT THIS TIME:

***REPAIR WITHIN DAYS.**

SYSTEM MAINTENANCE/IMPROVEMENTS REQUIRED:

*The MCHD recommends having the tanks (septic & dosing) pumped out every 3 to 5 years to remove excess solids.

*Please visit http://groundwater.charmeck.org for additional information.

DATE: 9/16/09

SIGNED: _____ AGENT
Division of Environmental Health

Printed Name:

Phone #:

N.C. Department of Environment and Natural Resources
Division of Environmental Health

Inspection of Engineered Subsurface Wastewater System

Mecklenburg County **Health Department**	Mowry Residence **Name of Establishment**	4951A **Permit/Project No.**
4702 Mountain Point Ln. Charlotte 28216 **Location**	3-Bedroom House **Type of Establishment**	360 GPD **Design Flow**
Doug Mowry **Owner/Agent**	Same as location address **Address**	(704) 393-3173 **Phone**
N/A **Operator**	N/A **Address**	N/A **Phone**
IIIb **System Type**	7/26/2005 **Date of Inspection**	July 2010 **Next Inspection Due**

	Yes	No	N/A	Comments:
1. ESTABLISHMENT:				
a. Type, size, and sewage flow in accordance with permit?	☒	☐	☐	
2. COLLECTION SYSTEM:				
a. No evidence of leaks into or out from sewer lines/manholes?	☒	☐	☐	
b. Free of blockages/solids buildup in lines or manholes?	☒	☐	☐	
3. TANKAGE: (Grease Traps/Lift Stations/Septic/Dosing Tanks)				
a. Tank risers accessible and surface water diverted?	☒	☐	☐	
b. Tanks and access manholes structurally sound, watertight?	☒	☐	☐	
c. Sanitary tee(s) in good working condition?.....	☐	☐	☒	3.c. Sanitary tee not inspected.
d. Tanks pumped, cleaned out as needed?.....	☒	☐	☐	
4. RAW SEWAGE LIFT STATION (if present):				
a. Required pumps present, operating, and cycling properly	☐	☐	☒	
b. High-water alarm present and operating properly?	☐	☐	☒	
c. Floats/pipe/valves/disconnects in good condition?	☐	☐	☒	
5. EFFLUENT DOSING SYSTEM:				
a. Effluent appears clear, free of excess solids?	☒	☐	☐	5.a. Measured <4" of solids in the dosing tank.
A. PUMP SYSTEMS:				
a. Required pumps present, operating, and cycling properly?	☒	☐	☐	
b. High-water alarm present and operating properly?	☒	☐	☐	
c. Floats/pipe/valves/disconnects in good working condition?	☒	☐	☐	
d. Control panel enclosure/components in good condition?	☒	☐	☐	
e. Elapsed time readings: _____ _____ _____ _____				
B. SIPHON SYSTEMS:				
a. No evidence of overflow or siphon leakage?	☐	☐	☒	
b. Siphon(s) appear to be working/alternating properly?	☐	☐	☒	
c. Bells and vents free of debris and in good condition?	☐	☐	☐	

6. GROUND ABSORPTION FIELDS:

a. No evidence of effluent surfacing/reaching surface waters?	☒	☐	☐	6. Drain field in good condition.
b. Minimal ponding in subsurface trenches?	☒	☐	☐	
c. Surface water being effectively diverted away?	☒	☐	☐	
d. Diversions/ditches/swales/tiles drains properly maintained?	☒	☐	☐	
e. Line cover/vegetation adequate/maintained as needed?	☒	☐	☐	
f. Protected from traffic, destructive uses?	☒	☐	☐	
g. Distribution devices in good condition, working properly?	☒	☐	☐	
h. Repair area properly reserved, maintained?	☒	☐	☐	

A. LOW PRESSURE PIPE DRAIN FIELDS:

a. Turnups/cleanouts/valves intact and accessible?	☐	☐	☒
b. No effluent standing in lower laterals?	☐	☐	☒
c. Laterals free of excess solids, cleaned out as needed?	☐	☐	☒
d. Pressure head is properly adjusted?	☐	☐	☒

OVERALL CONDITION AND OPERATION OF SYSTEM:

No problems detected with system operation at the time of inspection.

No sewage observed on the ground surface at the time of inspection.

SUMMARY OF REPAIRS REQUIRED AT THIS TIME:

None

***REPAIR WITHIN N/A DAYS.**

SYSTEM MAINTENANCE/IMPROVEMENTS REQUIRED:

*The MCHD recommends having the tanks (septic & dosing) pumped out every 3 to 5 years to remove excess solids.

1. Recommend installing a weather-proof enclosure over outdoor, electrical junction box.
2. Recommend raising pump control float so that a minimum of 12" of effluent is retained in the dosing tank at all times and the effluent pump remains submerged. Adjust level of alarm control float if necessary.

*Visit http://groundwater.charmeck.org for additional information.

DATE: 7/27/2005

SIGNED: _____ RSI _____ AGENT

Division of Environmental Health

MECKLENBURG COUNTY
LAND USE AND ENVIRONMENTAL SERVICES
Payment Receipt

COPY

Receipt Information

Date:	06/14/05	**Amount:**	85.00
Receipt #:	35143	**Tendered:**	85.00
Check / Auth #:	CHECK 2411	**Returned:**	0.00
Received By:	WALKEVA		

Account Information


Account #: 200000
Contractor: MOWRY DOUG
Attn:
Address: 4702 MOUNTAIN PT. LANE
Address:
City/State/Zip: CHARLOTTE, NC 28216

Item	Description	Permit#	Quantity	Unit Price	Total Price
0743	Hmeownr Maint Inspec-Type IIIB FILE #4951A 704-393-3173		1	85.00	85.00

7/28/04

----------Outstanding Balances----------

Month-To-Date	Prior Month	30 Days	60 Days	90 Days	Balance


CBA

MAINTENANCE INSPECTION STATEMENT

MECKLENBURG COUNTY HEALTH DEPARTMENT

Robert J. & Margaret T. Burns
4702 Mountain Point Lane
Charlotte, NC 28216

Please Make Check Payable To:

Mecklenburg County Health Department
700 N. Tryon Street, Ste 211
Charlotte, NC 28202

Note: THIS COMPLETED FORM MUST ACCOMPANY PAYMENT!

DESCRIPTION OF PROPERTY

Name	Site Address	Tax Parcel	File #	#Bedrooms	System Type
Robert J. & Margaret T. Burns	4702 Mountain Point Lane	023-162-14	4951A	3	IVA

Total Amount Due: $85.00

Please use the space below, to make any corrections to property information.

Name _____

Site Address _____

_____

Bedrooms _____

BILL INFORMATION

Billing Date	Payment Due Date
7/20/99	8/23/99

Direct Questions Concerning This Bill To ..... (704) 336-5102

☐ *Please check if you have a well.*

Make Check Payable To Mecklenburg County Health Department
Your Canceled Check Is Your Receipt

7-30-99
OSV

DO NOT SEND CASH

N. C. Department of Environment and Natural Resources
Division of Environmental Health

INSPECTION OF ENGINEERED SUBSURFACE WASTEWATER SYSTEM

Mecklenburg Co. — Health Department
Name of Establishment — Residence — Type of Establishment
4951A — Permit/Project No.
360 gpd — Design Flow
4702 Mountain Point Lane — Location
Robert + Margaret Burns, 4702 Mtn. Pt. Lane, Char. 28216 — Owner/Agent — Address — Phone
N/A — Operator — Address — Phone
Remarks IIIb

	Yes	No	REMARKS
1. ESTABLISHMENT:			
Type, size, and sewage flow in accordance with permit?	☑	☐	
2. COLLECTION SYSTEM:			
No evidence of leaks into or out from sewer lines/manholes?	☐	☐	
Free of blockages/solids buildup in lines or manholes?	☐	☐	
3. TANKAGE (Grease Traps/Lift Stations/Septic/Dosing Tanks):			
Tank risers accessible and surface water diverted?	☑	☐	Recommend pumping septic tank every 3-5 years.
Tanks and access manholes structurally sound, watertight?	☑	☐	
Sanitary tee(s) in good working condition?	☐	☐	
Tanks pumped, cleaned out as needed?	☐	☐	
4. RAW SEWAGE LIFT STATION (if present):			
Required pumps present, operating, and cycling properly?	☑	☐	Could not verify if alarm was working properly - Indoor Alarm
High-water alarm present and operating properly?	☐	☐	
Floats/pipe/valves/disconnects in good working condition?	☑	☐	
Control panel enclosure/components in good condition?	☑	☐	
5. EFFLUENT DOSING SYSTEM:			
Effluent appears clear, free of excess solids?	☐	☐	
PUMP SYSTEMS:			
Required pumps present, operating, and cycling properly?	☐	☐	
High-water alarm present and operating properly?	☐	☐	
Floats/pipe/valves/disconnects in good working condition?	☐	☐	
Control panel enclosure/components in good condition?	☐	☐	
Elapsed time readings: _____ _____ _____ _____			
SIPHON SYSTEMS:			
No evidence of overflow or siphon leakage?	☐	☐	
Siphon(s) appear to be working/alternating properly?	☐	☐	
Bells and vents free of debris and in good condition?	☐	☐	
6. GROUND ABSORPTION FIELDS:			
No evidence of effluent surfacing/reaching surface waters?	☑	☐	
Minimal ponding in subsurface trenches?	☑	☐	
Surface water being effectively diverted away?	☑	☐	
Diversions/ditches/swales/tile drains properly maintained?	☑	☐	
Line cover/vegetation adequate/maintained as needed?	☑	☐	
Protected from traffic, destructive uses?	☑	☐	
Distribution devices in good condition, working properly?	☑	☐	
Repair area properly reserved, maintained?	☑	☐	
LOW-PRESSURE PIPE DRAIN FIELDS:			
Turnups/cleanouts/valves intact and accessible?	☐	☐	
No effluent standing in lower laterals?	☐	☐	
Laterals free of excess solids, cleaned out as needed?	☐	☐	
Pressure head is properly adjusted?	☐	☐	

OVERALL CONDITION AND OPERATION OF SYSTEM: Looks good.

SUMMARY OF IMPROVEMENTS NEEDED:

Improvement	Repair Within (Day

DATE: 7-30-99 SIGNED: Larry B. Thompson, J. R. E.S. AGENT
Division of Environmental Health

– over –

SUMMARY OF IMPROVEMENTS NEEDED (cont.)

Improvement	Repair Within (Days)

INTENT TO SUSPEND OR REVOKE PERMIT

This is to notify you of intent to suspend/revoke your operation permit/certificate of completion 60 days from this date for the following
(circle one) *(circle one)*

violations: _____
[Law or Rule(s)]

If suspended, the operation permit or certificate of completion remains suspended until violations are corrected. A hearing will be held prior to suspension or revocation if you file a petition for a hearing with the Office of Administrative Hearings, P. O. Drawer 27447, Raleigh, NC 27611-7447, in writing within the number of days specified above of your intent to attend the hearing. If you do not petition the Office of Administrative Hearings, the operation permit or certificate of completion will be suspended or revoked.

IMMEDIATE SUSPENSION OR REVOCATION OF PERMIT

This is to notify you of immediate suspension/revocation of your operation permit/certificate of completion for the following violations:
(circle one) *(circle one)*

_____
[Law or Rule(s)]

If suspended, the permit or certificate remains suspended until the violations are corrected. You will be notified of the day and location of a hearing on this suspension or revocation by a hearing officer from the Office of Administrative Hearings.

This the _____ day of _____, 19 _____.

_____ Agent
DIVISION OF ENVIRONMENTAL HEALTH

INSTRUCTIONS

Purpose: Article 11 of Chapter 130A requires the Commission for Health Services to adopt rules governing the design, construction, and operation of on-site wastewater systems. 15A NCAC 18A .1937 specifies that the local health department shall determine whether systems with an Operation Permit are operating properly at a frequency specified in Rule .1961, Table V(a), and that systems which exceed 3,000 gallons per day and other systems which are required to be designed by a professional engineer shall be reinspected annually. This form is developed to be used in making inspections of engineered subsurface wastewater systems.

Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for:

1. Original to be left with the responsible person.
2. Copy for the local health department.
3. Copy for the On-Site Wastewater Section, Division of Environmental Health.

In the event the permit is suspended or revoked, complete the portion above.

Disposition: This form may be destroyed in accordance with Standard 7, Inspection Records, of the *Records Disposition Schedule* published by the N.C. Division of Archives and History.

Additional forms may be ordered from: On-Site Wastewater Section
Division of Environmental Health
P. O. Box 29594
Raleigh, NC 27626-0594
(Courier 52-01-00)

Mecklenburg County
Health Department

July 20, 1999

Robert J. and Margaret T. Burns
4702 Mountain Point Lane
Charlotte, NC 28216

Dear Mr. and Mrs. Burns:

This letter is being sent to all home/business owners in Mecklenburg County with septic tank systems that utilize pumps. In 1990 the North Carolina Administrative Code governing septic tank systems was amended to require routine maintenance and inspection of certain septic tank systems. Research conducted on septic tank systems has shown that properly maintained systems perform better and protect the home/business owner's investment. These State rule changes required local health departments to perform additional inspections without additional resources. During the 1998-99 budget hearings, the Mecklenburg County Board of County Commissioners (BOCC) approved user fees to offset costs and to allow the local health department to comply with mandatory enforcement requirements in the State regulations.

Since you have a pump system, these new rules and fee requirements affect you. The fee is $85.00 and is due upon receipt of this notice. We will visit your property and make assessments and recommendations for the continued efficient operation of your septic tank system. In addition, if you have a well, a bacterial sample will be collected to help assess the quality of your water supply source. The process, including fee assessment, will be repeated every five (5) years. The fee amount may change in the future.

We are excited about the interest and support demonstrated by the BOCC. Past performance in this area was more enforcement oriented rather than supportive. One of our goals is to establish our department as a resource to you to aid and assist you with this and related public health concerns. The inspection program and the water analysis are important to the health of you and your family. This is a very important initiative intended to protect the public's health while improving and preserving our groundwater resources.

Your prompt fee payment will activate our inspection process. Your comments and questions regarding this matter are encouraged and welcomed.

Sincerely,

Larry B. Thompson, Jr., R.S.

Larry B. Thompson, Jr., R.S., Coordinator
Managed Systems Program
Individual Water and Wastewater Systems

Enclosure

cc: Fiscal Services Manager, HMHCS

CERTIFICATE OF COMPLETION/OPERATION PERMIT

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

FILE: 4951 A DATE: 4/4/90

TC: 023 ~~[illegible]~~ PO ☐ L ☑ CRT

SERIAL 12-14 № 13057

Name of Owner Burns, Margaret Juris.:

Address of Property 4702 Mt. Point Ln.

Inspection Data:

Tank Material PCC

Total Length of Drainfield 400'

Number of Lines 4 @ 100'

Cover Depth 24"

Water Supply Source Well

Distance to Water Source 750

Excavation Inspected 4/4/90

Tank(s) Inspected 4/4/90

Wash Line Inspected

High Water Alarm Inspected

PLOT

Design: 1990 1500 ST 1000 DT PI Lin 1200SF 12"8 Fecl CTR# 48

The undersigned has inspected the Septic Tank System described above, and certifies it has been

☑ installed or constructed ☐ altered or repaired

☑ in accordance with the permit issued ☐ as detailed in the plot above

and meets the provisions of 10 NCAC 10A .1900, "Laws And Rules For Sanitary Sewage Collection, Treatment, And Disposal" in effect on the date of issuance of the permit. The issuance of this

☐ Certificate of Completion ☑ Operation Permit

does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling, or using such system from any liability resulting from the failure of the system to operate properly. This document is issued subject to those restrictions and conditions shown on the permit(s) and the provisions of 10 NCAC 10A .1900 in addition to those listed below under "COMMENTS." This document shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

COMMENTS: Would 1/3 HP

System designed for 3 bedroom home

[signature] R.S.
Environmentalist

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

INSTALLATION, CONSTRUCTION, ALTERATION, AND/OR REPAIR PERMIT


HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

FILE: 4951A DATE: 3/26/90

TC: 023-101-03 POOL

SERIAL Nº 13191

Permission is hereby given to ✓ Install or Construct, _____ Alter or Repair the individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in the application dated 4/2/89. All work shall be completed on or before 4/26/90, after which date this permit shall be null and void. The system shall meet all of the construction requirements of 10 NCAC 10A .1900 which are in effect on the date of the granting of this permit. A Certificate of Completion or an Operation Permit must be obtained from the Mecklenburg County Health Department before any system can be covered up or placed into service. The issuance of this permit does not in any way guarantee that the system anticipated to be constructed will operate properly, or relieve any person now or hereafter owning, controlling or using such system from any liability resulting from the failure of the system to operate properly.



PLOT OF SYSTEM

Liquid Capacity of Septic Tank 1500 gallons

Liquid Capacity of Dosing Tank 1000 gallons

Tank Construction PCC

Absorption and/or Nitrification Lines:

Trench Width 3 feet

Total Line Length 400 feet

Number of Lines 4

Depth of Stone 12 inches

Distance from House 15 feet

Distance from Property Line 710 feet

Distance from Well 750 feet

NAME OF OWNER Margaret Burns

LOCATION OF PROPERTY 4702 Mt Point LN

Comments: Lift station required, 4 Trenches x 100' long x 3' x 12" Gravel set 2 D-Boxes, Keep lines on contour of land, Stay 750 from existing well

Division or Section Head

Philo S. Walker
Environmentalist

* If this permit is for the installation or construction of a new system, it must be signed by the division or a section head of the Mecklenburg County Health Department in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired.

WHITE - HEALTH DEPARTMENT'S COPY • CANARY - ENVIRONMENTALIST'S COPY • PINK - OWNER OR AGENT'S COPY


PROPOSED PLOT PLAN

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

FILE: 4951 A

TC: _____

Draw in and name all roads adjoining the property. Draw in and accurately dimension the lot concerned. Accurately indicate property boundaries, proposed and/or existing structures and driveways, underground utilities, and wells and springs within 100 feet of the proposed building or drainfield.



Approved
8/19/99
PSW

PSW

Signed: _____

Date: 4702 Mountain Point Lane

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

CHARGE SLIP

Date 4/7/89

Name/Company B.E.W. Corp

Sanitation _____

Vector Control ✓

O.P.W.D. _____

Service: Imp/Inst #1195/A

ENVIRONMENTAL HEALTH DIVISION
PAID

APR 7 1989

Fee: $ 150 —

Rheinhardt

APPLICATION FOR AN IMPROVEMENT PERMIT

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

(OFFICE USE ONLY)
FILE: 4951A
TC: _____
SERIAL: No 17822
☐ L ☐ CRT

JOB LOCATION

① ADDRESS: 4702 MOUNTAIN POINT LANE (STREET NO. / STREET) ② FILE: _____
③ JURISDICTION: _____ ④ TAX PARCEL NO.: 023-101-03 PO
⑤ SUBDIVISION: _____ ⑥ LOT: _____ ⑦ BLOCK: _____

OWNER

⑧ NAME: Margaret (FIRST) T. (MIDDLE) Burns (LAST)
⑨ MAILING ADDRESS: 541 Kenlough Dr.
⑩ CITY: Charlotte ⑪ STATE: NC ⑫ ZIP: 28209
⑬ PHONE: (WORK) 376-0291 ⑭ (HOME) 704-523-6368

REQUEST

This request is for a(n):

⑮ ☒ New permit
⑯ ☐ Repair or alteration permit
⑰ ☐ Authorization for mobile home exchange
⑱ ☐ Other (specify) _____

DESIGN CRITERIA

System will serve:

⑲ ☒ Residence ⑳ ☐ Mobile home
㉑ ☐ Business or place of public assembly
㉒ Number of bedrooms? 3
㉕ Type? _____
㉓ Maximum occupancy? 2
㉖ Maximum number of employees? _____
㉔ Basement? ☑ yes ☐ no
㉗ Maximum number of seats? _____

WATER SUPPLY

㉘ Water supply from (present or proposed):

A ☐ Individual well
B ☐ Municipal system
C ☐ Community well
D ☑ Community system

㉙ The undersigned, owner of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY HEALTH DEPARTMENT to enter on the property for the purpose of processing this request.

Signed: Margaret T. Burns
Date: April 7, 1989

IMPROVEMENT PERMIT

The undersigned, an authorized agent of the MECKLENBURG COUNTY HEALTH DEPARTMENT, certifies that the Department has approved the Request for the Job Location contained in this document. This approval is granted in accordance with the provisions of Laws And Rules For Sanitary Sewage Collection, Treatment And Disposal in effect at the time of issuance of the permit and is subject to the following provisions:

... No work shall be conducted on the septic tank system until an Installation, Construction, Alteration and/or Repair permit is issued by this Department.

... This permit is not transferable, and shall become null and void 36 months from the date of issuance.

8/9/89 PSW
~~May require~~ lift pump shall be required Adding basement

Phyllis S. Walker, 8/9/89
Environmentalist Date

Director or Authorized Section Head 8-9-89 Date

*This permit must be signed by the Director of Mecklenburg County Health Department or an authorized section head in order to be valid.

DATE: 4/7/89

TO: HEALTH DEPARTMENT - ENVIRONMENTAL HEALTH

FROM: COUNTY ENGINEERING

EHD FILE 4951A JURISDICTION CODE Meck

PARCEL NUMBER 023-101-03po

ASSIGNED ADDRESS 4702 Mountain Point Ln.

EXISTING ADDRESS Lot 36

PROJECT NAME Mountain Point

THE ABOVE DESCRIBED LOCATION HAS BEEN CHECKED CONCERNING:

	APPROVED	NOT APPROVED
1. SUBDIVISION REGULATIONS	☐	☐ *
2. FLOODWAY REGULATIONS	☐	☐ *
3. EROSION CONTROL REGULATIONS	☐	☐ *
4. COMMERCIAL DRAINAGE PLAN	☐	☐ *
	PRESENT	NOT PRESENT
5. PUBLIC UTILITY EASEMENT	☐ *	☐
	YES	NO
6. PROPERTY FRONTS ON THOROUGHFARE	☐ *	☐
	YES	NO
7. DRIVEWAY PERMIT REQUIRED	☐ *	☐

* If checked, further investigation will be required to determine whether a building permit may be issued by Building Standards for the site.

REMARKS: Septic Tank

NOTE: THIS FORM MUST BE TURNED IN AT THE CASHIERS OFFICE AT BUILDING STANDARDS WHEN PAYING PERMIT FEES.
A CERTIFICATE OF OCCUPANCY WILL NOT BE GRANTED UNTIL THE TRANSPORTATION DIVISION GRANTS FINAL APPROVAL ON DRIVEWAY(S).

SIGNED: [signature]

OPWEAR 02/86

PROPOSED PLOT PLAN


MECKLENBURG COUNTY ENVIRONMENTAL HEALTH

1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

FILE: 4951A

TC: _____

Draw in and name all roads adjoining the property. Draw in and accurately dimension the lot concerned. Accurately indicate property boundaries, proposed and/or existing structures and driveways, underground utilities, and wells and springs within 100 feet of the proposed building or drainfield.



D/S approved 7/28/89 PSW
will submitted new plan

Signed: Margaret J. Burns

Date: April 7 1989

Mecklenburg County
Health Department

Basil G. Delta, M.D., M.P.H.
Health Director

September 9th, 1988

Landcraft Properties, Inc.
2305 Randolph Road
Charlotte, NC 28207

RE: Property located at Abernathy Road 36
FILE: 4951A
PARCEL: 02310103 PO

Dear Sir:

At your request, a field investigation was conducted on the property designated above for the purpose of determining site suitability for the installation of a ground absorption sewage disposal system. The property was found to contain a limited area of soils which were classified as provisionally suitable for such an installation. A copy of the Site Evaluation Report (Serial Number 15554) is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit an Application For An Improvement Permit with an ACCURATELY dimensioned plot plan detailing the location of current and/or proposed buildings, wells and sewage disposal systems to this office. The plan will be reviewed and if it is found that the area of provisionally suitable soils is adequate for the proposed construction, an Improvement Permit will be issued by this Department.

If I may be of assistance, please do not hesitate to contact me.

Very truly yours,

Sylvia D. Daniel

Sylvia D. Daniel, R.S., Supervisor
On Premises Waste Disposal & Water Supply

Enclosure

MECKLENBURG COUNTY ENVIRONMENTAL HEALTH
SITE EVALUATION REPORT
SERIAL NUMBER 15554

File: 4951A

Parcel: 02310103 PO

Action 1

☐ PC

Location: Abernathy Road

Subdivision:


Lot: 36 Block: Acres: 1.26

Owner: Landcraft Properties, Inc.
Address: 2305 Randolph Road
Charlotte, NC 28207

Comments: _____

Described by: William A. Merlin

Date: 9-9-95



***** EVALUATION KEY *****

S = Suitable U = Unsuitable
PS = Provisionally Suitable
The "Area Classification" below indicates the suitability of areas in the diagram.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4	AREA 5	AREA 6
Topography	(S) PS U 6-15%	S (PS) U 15-25%	S PS (U) complex slopes	S PS (U) slight Depression	S PS (U) Drainageway	S PS U
Texture	S (PS) U clay	S (PS) U clay	S PS U —	S PS U —	S PS U —	S PS U
Structure	S (PS) U Blocky	S (PS) U Blocky	S PS U —	S PS U —	S PS U —	S PS U
Drainage	S (PS) U 736" to water	S (PS) U 736" to water	S PS U —	S PS U —	S PS U —	S PS U
Depth	S (PS) U 736"	S (PS) U 36"+	S PS U —	S PS U —	S PS U —	S PS U
Restrictive Horizons	S (PS) U 736"	S (PS) U 736"	S PS U —	S PS U —	S PS U —	S PS U
Available Space	S (PS) U limited	S (PS) U limited	S PS U —	S PS U —	S PS U —	S PS U
Other (specify)	S PS U	S PS U	S PS U	S PS U	S PS U	S PS U
Soil Group/Series	IVA Cecil-Lilo	IVA Cecil-Lilo	complex slopes	Slight Depression	Drainageway	
Area Classification	S (PS) U	S (PS) U	S PS (U)	S PS (U)	S PS (U)	S PS U

APPLICATION FOR SOIL INVESTIGATION

1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

(OFFICE USE ONLY)

MECKLENBURG COUNTY
HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
PAID

FILE: 4951A AUG 29 1988 Rec

TC: Receipt #

☐ PC ☐ REPT

JOB LOCATION

① ADDRESS: 11956 Abernathy

② SUBDIVISION: Mountain Point ③ LOT: 36 ④ BLOCK:

⑤ PARCEL REFERENCE: BOOK NO.: 23 PAGE NO.: 101 PARCEL NO.: 03

⑥ DEED REFERENCE: BOOK NO.: 1119 PAGE NO.: 440

OWNER


⑦ NAME: C/O Jack (FIRST) LandCraft Properties (MIDDLE) Parker, Inc. (LAST)

⑧ MAILING ADDRESS: 2305 Randolph Rd.

⑨ CITY: Charlotte ⑩ STATE: NC ⑪ ZIP: 28207

⑫ PHONE: (WORK) 332-9340 (HOME)

⑬ Accurately diagram and dimension lot.



⑭ The undersigned, owner of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY DEPARTMENT OF ENVIRONMENTAL HEALTH to enter onto the property for the purpose of processing this request.

Signed: Harriette H Parker

Date: Aug 26, 1988

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

WHITE - ENVIRONMENTAL HEALTH DEPARTMENT'S COPY ● CANARY - ENVIRONMENTALIST'S COPY ● PINK - OWNER'S COPY