Date Received 6/9/77

APT No. 12561

R.O.
T.C. No. 135-361-01

Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & CO, INC.
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P.O. BOX 25746 CHAR. ZIP 28212

3) PHONE NO. Home _____ Office 545-6111


4) LOCATION OF PROPERTY APPLE CREEK DR.
(STREET OR COUNTY ROAD)

5) SUBDIVISION APPLE CREEK LOT NO. 8 BLOCK NO. A

MAP BOOK NO. _____ PAGE NO. _____

6) DEED REFERENCE: DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L. Gobel
OWNER

FORM NO. E-1-9-1-72

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation June 17, 1977 APT NO. 12561

Owner Bob McLorace & Co., Inc.

Location of Property Apple Creek Dr. Lot No. 8 Block AA

Soil Suitability Ratings Tax Code No. P.6.135 — 361-01

Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Cou.1 — ENON	Intergrad	Mt Holly	Chewacla
2. Soil Slope	Suitable 3-6%		Suitable 2-6%	—
3. Soil Depth	Suitable 48"+	w	suitable <30"	—
4. Soil Texture	provisionally suitable some 2:1 clays		unsuitable 2:1 clays	—
5. Soil Structure	provisionally suitable blocky		unsuitable massive	—
6. Restrictive Horizons	—		—	—
7. Soil Drainage	Suitable water table 36"+		unsuitable perched high water table	unsuitable poorly drained
8. Soil Permeability (Percolation Rate)	provisionally suitable moderate (less than 90 min. /in.		unsuitable very slow >200 min/in	unsuitable seasonal high water table 6"-18" from surface
9. Other	—		—	unsuitable floods
10. Overall Rating	provisionally suitable		unsuitable	unsuitable


Recommendations Based on this investigation, the lot was found to have an acceptable area of provisionally suitable soils for installation of a septic tank system. System design should be based on a percolation rate of 90 min/in. and should be placed in the area of intergradient soils.

See diagram on back

G. Edward Casemt
Soil Scientist

3/18/75
EHD 539

DIAGRAM OF PROPERTY



3/18/75
EHD 539

Serial No. 0952

PTR No. 12561

Date Issued June 22, 1977

T. C. No. P.O.135-361-01

Map Date


MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
SOIL INVESTIGATION REPORT

NAME OF OWNER Bob McLemore & Company, Inc.
LAST FIRST MIDDLE

ADDRESS OF OWNER P. O. Box 25746, Charlotte, NC ZIP 28212

LOCATION OF PROPERTY Apple Creek Drive
STREET OR COUNTY ROAD

SUBDIVISION Apple Creek LOT NO 8 BLOCK NO. A



PLOT PLAN

This is to certify that a soil investigation and on-site investigation was made by the Mecklenburg County Department of Environmental Health on the lot described above and that said investigation was conducted on that portion of the lot indicated on the above plot. **Provisionally Suitable**

The percolation rate determined by the investigation was **90 min/in.** The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge subject to the following terms and conditions:

1. Any improvements or alterations made to the property which would impair the Mecklenburg County Department of Environmental Health's ability to repair or replace the wastewater treatment system on this lot.
2. The approved system is a septic tank wastewater treatment system which must be installed with the determined by the Mecklenburg County Department of Environmental Health to be the minimum allowable for the soil and site conditions as they exist at the time of installation as based on the soil/site rate obtained above and on the proposed use of the building to be located thereon.
3. The approval is based on the system as noted on the attached and indicated as acceptable for system installation on the above plot.
4. This approval is void after ninety days from the date of issuance unless the drilling of a well has been performed on the lot which in the opinion of the Mecklenburg County Department of Environmental Health renders the area indicated as acceptable for system installation unsuitable for the installation, construction, alteration, or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina Department of Human Resources, Division of Health Services and the Mecklenburg County Health Commission which were in effect on the date of issuance and is void if at any time in the future, prior to completion of the system, these laws, rules and regulations are changed such that this approval would not have been granted had the new or revised laws, rules and regulations been in effect on the issue date.

W. Edward Leonard
Soil Scientist

John R. Robinson
Environmental Health Director or Authorized Section Head

EHD-5 76

Environmental Health Department's Copy

Date Received 10/16/79

SEE INSTRUCTIONS ON BACK

ICAR(S) Application No. 12561

T. C. No. 135-361-01


Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Department of Environmental Health for a permit to:

1) X Install or Construct 2) Alter or Repair an individual septic tank wastewater treatment system with a subsurface, soil absorption, effluent discharge.



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No of Bedrooms 4

5) Business Use Max No Employees

6) Washing Machine X Yes ___ No

7) Garbage Disposal ___ Yes X No

8) Dishwasher X Yes ___ No

9) Water Supply
- A Individual Well ___
- B Governmental System ___
- C Community System
  - 1 Well source X
  - 2 Governmental source ___

10) Sewage System
House located within 200 feet of public sewer ___ Yes X No
House located within 200 feet of community sewer ___ Yes X No

11) FHA Case No ___

12) VA Case No ___

13) NAME OF OWNER Bob McLemore & Co., Inc. (LAST / FIRST / MIDDLE)

14) ADDRESS OF OWNER P. O. Box 25746

15) PHONE NO. Home ___ Office 545-9742

16) LOCATION OF SYSTEM 7342 Apple Creek Dr. (STREET OR COUNTY ROAD)

17) SUBDIVISION Farmwood Lot No. 8 Block No. A

Map Book No 17 Page No. 366

18) DEED REFERENCE — DEED BOOK ___ AT PAGE ___

19) HAS A SOIL INVESTIGATION BEEN RUN? X YES ___ NO DATE RUN 6/22/77

20) PTR NUMBER (See Instructions) 12561

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

DATE OF APPLICATION 10/15/79

OWNER William H. Bofer

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

Serial No. 3615

Date Issued Oct. 16, 1979

LA No. 12561

T. C. No. po 135-361-01

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Bob McLemore and Company, Inc.
(LAST / FIRST / MIDDLE)

ADDRESS OF OWNER PO Box 25746, Charlotte, NC ZIP 28212

LOCATION OF LOT 7342 Apple Creek Drive
(STREET OR COUNTY ROAD)

SUBDIVISION Farmwood LOT NO #8 BLOCK NO. "A"

MAP BOOK NO. PAGE NO

The above specified lot is approved by the Mecklenburg County Department of Environmental Health for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the soil investigation, on an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 12561 This approval is subject to the following terms and conditions

1. That the nitrification field be installed, constructed, altered and/or repaired in the same area where the soil investigation was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit.

Steve Wood
Environmentalist

John R Adkisson
Environmental Health Director, or Authorized Section Head

EHD-5-76

Environmental Health Department's Copy

5