Date Received 6-29-84

MECK COUNTY DEPARTMENT OF ENVIRONMENTAL HEALTH RECEIVED

SIR No. 21196

T.R. No. 111-071-05

Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Caldwell, (LAST) Getcherl (FIRST) (MIDDLE)

2) ADDRESS OF OWNER 1009 Roosevelt Blvd. Philadelphia, Pa. ZIP 19116

3) PHONE NO. Home N/A Office Info. Only- 535-2558

4) LOCATION OF PROPERTY Harrisburg Road (Close to Reedy Creek Rd.)
(STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____ Tax Parcel-111-071-05

6) DEED REFERENCE DEED BOOK 2853 PAGE NO. 169

Send Copy to: J.H. Bruton, 11101 Harrisburg Rd. Charlotte, N.C. 28215

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge

SEE ATTACHED MAP

7) ACCURATELY DIAGRAM & DIMENSION LOT

Julia Caldwell
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 21196

T.C. NO. P.6 111-071-05

(Ground Absorption Sewage Disposal)

OWNER: GETCHERL CALDWELL PLAT NO:
ADDRESS: 1009 ROOSEVELT Blvd LOT SIZE: 1A
PHILADELPHIA PA 19116
LOCATION OF SITE: HARRISBURG Rd - Near Beaty Creek Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-4 U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS (U) Mid clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS (U) Weak Blocky	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS (U) 15-28"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) None U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S Slow PS (U)	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IV-a			
9. SITE CLASSIFICATION	Unsuitable			
10. SOIL SERIES	ENON			

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:

Described by: W. B. Ramsey
Title: Soil Scientist

Date: 7-23-84

24


X
Enter
2-4
200
200
Harrisburg Rd
Rocky Creek

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 21196
T.C. NO. PO 111-071-05
DATE: 7-24-84

Getcherl Caldwell
1009 Roosevelt Boulevard
Philadelphia, PA 19116

RE: Property located at Harrisburg Road

Dear Mr. Caldwell:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure