Date Received 5/21/84

SIR No. 21082

TAX No. 197-141-01

Map Date L

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER McDougle Arnold H.
(LAST, FIRST, MIDDLE)

2) ADDRESS OF OWNER 6250 Brookshire Rd ZIP 28209

3) PHONE NO Home 568-3320 Office 375-2411


4) LOCATION OF PROPERTY Indian Trail Rd
(STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO 7 BLOCK NO _____

MAP BOOK NO 112 PAGE NO 4 final 01

6) DEED REFERENCE DEED BOOK 1801 PAGE NO 178

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Pinson Realty Co. by
Charles H. Carson, Agent
OWNER
For Arnold H. McDougle

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT COPY

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. [illegible]

T.C. NO. [illegible]

(Ground Absorption Sewage Disposal)

OWNER: [illegible]
ADDRESS: [illegible]
LOCATION OF SITE: [illegible]

PLAT NO: [illegible]
LOT SIZE: [illegible]

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
3. SOIL STRUCTURE (12-36 inches)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
4. SOIL DEPTH (inches)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
7. OTHER (Specify)	S / PS / U	S / PS / U	S / PS / U	S / PS / U
8. SOIL GROUP				
9. SITE CLASSIFICATION				
10. SOIL SERIES				

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments: [illegible]

[illegible]

Described by: [illegible]
Title: [illegible]

Date: [illegible]

2#


150'
150'
Lagoon - Tarawa
Airport
2100

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 21082
T.C. NO. PO 197-141-01
DATE: 7-20-84

Anabel H. McDougle
2220 Iverness Road
Charlotte, NC 28209

RE: Property located at Indian Trail Road, Lot 7

Dear Ms. McDougle:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure