apt 14355

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: Kissiah, Robt
ADDRESS: 2826 Temple Dr
COUNTY:
LOCATION OF SITE: Comanche Rd

DATE REQUESTED:
PLAT NO.: 01-396.03
LOT SIZE: 9507 sq ft

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (Z)	(S) PS U 2%	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS (U) mod sandy 2:1 clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S PS (U) massive	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) PS 48" U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	(S) PS U 96" to Rock	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S < 24" PS to water (U)	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS 2ct (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	(S) adequate PS for U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable Unsuitable			
SOIL SERIES	Ingleside			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: Perched water table at 24"

Described By: J. M. Reynolds
Title: Environmental Specialist Date: 20 July 78

DHS Form 2601 (2/77)
Sanitation

2

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 14355
T.C. NO. 017-296-03
MAP DATE
DATE 7-21-78

NAME OF OWNER Kissiah, Robert

ADDRESS OF OWNER 2826 Temple Lane, Charlotte, N. C.

LOCATION OF LOT Comanche Road

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Soil structure massive

Soil permeability unsuitable

R. M. Reynolds, Environmentalist
On Premises Waste Disposal Section

RMR:jjk

EHD 398
7/77