

GREYLAND HILLS LOT 80

5/10/2007

duponbj

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

APPLICATION FOR SOIL INVESTIGATION

MECKLENBURG COUNTY · ENVIRONMENTAL HEALTH ·

1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

(OFFICE USE ONLY)

FILE: 3799A

TC: _____

☐ PC ☐ REPT

JOB LOCATION

① ADDRESS: Greyland Hills, Phase II, off Grey Road

② SUBDIVISION: Greyland Hills ③ LOT: 80 ④ BLOCK: _____
Part of 003-131-01

⑤ PARCEL REFERENCE: BOOK NO.: 03 PAGE NO.: 13 PARCEL NO.: 01

⑥ DEED REFERENCE: BOOK NO.: 3664 PAGE NO.: 949

OWNER


⑦ NAME: Bobby (FIRST) B (MIDDLE) Knox (LAST)

⑧ MAILING ADDRESS: PO Box 4

⑨ CITY: Davidson ⑩ STATE: NC ⑪ ZIP: 28036

⑫ PHONE: (WORK) 892-0196 (HOME) 892-0248

⑬ Accurately diagram and dimension lot.



⑭ The undersigned, owner of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY DEPARTMENT OF ENVIRONMENTAL HEALTH to enter onto the property for the purpose of processing this request.

MECK. COUNTY DEPARTMENT
RECEIVED
AUG 11 1987
ENVIRONMENTAL HEALTH

Signed: Bobby B Knox

Date: 3/26/87

WHITE - ENVIRONMENTAL HEALTH DEPARTMENT'S COPY ● CANARY - ENVIRONMENTALIST'S COPY ● PINK - OWNER'S COPY

MECKLENBURG COUNTY

Department of Environmental Health

December 8, 1987

Bobby B. Knox
P. O. Box 4
Davidson, NC 28036

Dear Mr. Knox:

File: 3799A - Greyland Hills, Lot 80
3800A - Greyland Hills, Lot 81
3491A - Greyland Hills, Lot 85
3492A - Greyland Hills, Lot 86
3493A - Greyland Hills, Lot 87

Our office has as application for a soil investigation dated March 26, 1987. The investigation was not made because of problems encountered in locating the lot, specifically, lines and corners. Should you desire us to complete the soils investigation, you contact us at 376-4603 by December 20, 1987 or your application will be placed under the "inactive" file. It will be necessary for the lot lines and corners to be plainly marked. Please contact us if you have any questions.

Sincerely,

W B. Ramsey

W. B. Ramsey
Soil Scientist

WBR/ir

MECKLENBURG COUNTY

Department of Environmental Health

February 25th, 1988

Bobby B. Knox
P.O. Box 4
Davidson, NC 28036

RE: Property located at Charden Road Extension 80
FILE: 3799A
PARCEL: 00313101PO

Dear Sir:

At your request, a field investigation was conducted on the property designated above for the purpose of determining site suitability for the installation of a ground absorption sewage disposal system. The property was found to contain a limited area of soils which were classified as provisionally suitable for such an installation. A copy of the Site Evaluation Report (Serial Number 14507) is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit an Application For An Improvement Permit with an ACCURATELY dimensioned plot plan detailing the location of current and/or proposed buildings, wells and sewage disposal systems to this office. The plan will be reviewed and if it is found that the area of provisionally suitable soils is adequate for the proposed construction, an Improvement Permit will be issued by this Department.

If I may be of assistance, please do not hesitate to contact me.

Sincerely,

Sylvia D. Daniel, R.S.
Environmental Health Supervisor
Environmental Resources Division

Enclosure

MECKLENBURG COUNTY ENVIRONMENTAL HEALTH
SITE EVALUATION REPORT
SERIAL NUMBER 14507

File: 3799A Action 1

Parcel: P000313101 ☐ PC

Location: Charden Road Extension

Subdivision:


Lot: 80 Block: Acres: Approx 1.4

Owner: Bobby B. Knox
Address: P.O. Box 4
Davidson, NC 28036

Comments: _____

Described by: William R. Marlin

Date: 2-23-98



***** EVALUATION KEY *****

S = Suitable U = Unsuitable
PS = Provisionally Suitable
The "Area Classification" below indicates the suitability of areas in the diagram.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4	AREA 5	AREA 6
Topography	(S) PS U 6-15%	S PS (U) complex slopes	S PS U	S PS U	S PS U	S PS U
Texture	S (PS) U clay	S PS U —	S PS U	S PS U	S PS U	S PS U
Structure	S (PS) U Blocky	S PS U —	S PS U	S PS U	S PS U	S PS U
Drainage	S (PS) U 736" to water	S PS U —	S PS U	S PS U	S PS U	S PS U
Depth	S (PS) U 736"	S PS U —	S PS U	S PS U	S PS U	S PS U
Restrictive Horizons	S (PS) U 736"	S PS U —	S PS U	S PS U	S PS U	S PS U
Available Space	S (PS) U very limited	S PS U	S PS U	S PS U	S PS U	S PS U
Other (specify)	S PS U	S PS U	S PS U	S PS U	S PS U	S PS U
Soil Group/Series	IvA Cecil-Like	complex slopes				
Area Classification	S (PS) U	S PS (U)	S PS U	S PS U	S PS U	S PS U