Date Received 9--29--83

RECEIVED
AUG 30 1983
ENVIRONMENTAL HEALTH

SIR No. 19992
T. C. No 193-134-03
Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Martin (LAST) Rachel (FIRST) Sasser (MIDDLE)

2) ADDRESS OF OWNER 2101 Lakeview. Cir. Matthews. N. C. ZIP 28105

3) PHONE NO. Home 847--9975 Office 535--5409


4) LOCATION OF PROPERTY Lakeview Cir. (STREET OR COUNTY ROAD)

5) SUBDIVISION Morning Star LOT NO. 12 BLOCK NO. A

MAP BOOK NO 8 PAGE NO. 353

6) DEED REFERENCE: DEED BOOK 2754 PAGE NO. 559

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Rachel S. Martin
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 19992
T.C. NO. 193-134-03
DATE: 9-12-83

Ms. Rachel S. Martin
2101 Lakeview Circle
Matthews, NC 28105

RE: Property located at Lakeview Circle, Lot 12, Blk. A

Dear Ms. Martin:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 14992

T.C. NO. 193-13403

(Ground Absorption Sewage Disposal)

OWNER: Rachel Jo Martin
ADDRESS: 9101 Lakeview Circle Matthews N.C. 28105
PLAT NO: Lot 12-A
LOT SIZE: 20,000
LOCATION OF SITE: Lakeview Circle

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10% U 10-20%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS Depth Variable (U) 12-36"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS 36" (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) 36" to ground water U	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IVA			
9. SITE CLASSIFICATION	unsuitable			
10. SOIL SERIES	Pacolet-L. Mu			

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments: _____

Described by: William A Martin
Title: Soil Scientist

Date: 1-13-93

EHD 539 (Revised: 6/82)

9H


100'
Parcel Line
10-2"
12-20"
201'
803'
Parcel Line
24-0"
24-30"
LAKE VIEW CR.
100'