Date Received 2/19/80

APT No. 16658

T. C. No. 211-273-03, 04

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Glendenning (LAST) Eula (FIRST) (MIDDLE)

2) ADDRESS OF OWNER 4718 Addison Drive ZIP

3) PHONE NO. Home 366-0909 Office


4) LOCATION OF PROPERTY Spring Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Providence Franklin LOT NO. 1 & 2 BLOCK NO. C

MAP BOOK NO 6 PAGE NO. 871

6) DEED REFERENCE DEED BOOK 1625 PAGE NO. 232

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and on on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of on individual septic tank wastewater treatment system with subsurface, soil absorption, effluent dischorge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Eula J. Glendenning
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

S.I.R. No. 1656
T.C. No. 211-223-0304

(Ground Absorption Sewage Disposal)

OWNER: Lula Hawkins
ADDRESS: 4218 Robbins Dr.
COUNTY: Charlotte, NC.
LOCATION OF SITE: Spring Terr Ct

DATE REQUESTED:
PLAT NO: Lots 1 & 2, Block C
LOT SIZE: 5-3 400

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U — 2 9%	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2:1 Clay)	S PS (U) — 2-1 clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS (U) — Massive	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S — 48" PS (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (inches) (Impervious strata, Rock)	(S) None PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S PS (U) — Seasonal perched water table	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (percolation rate)	S PS (U) — Very slow	S PS U	S PS U	S PS U
8. OTHER (specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	unsuitable			
10. SOIL SERIES	Iredell			

S - Suitable PS - Provisionally Suitable U - Unsuitable


** See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope)

Recommendations/Comments:

Described By: William R. Marlin
Title: Soil Scientist
Date: 2-26-80

DHS Form 2601
Sanitation
EHD 539 (2/80)

R


100'
100'
267'
Irregular
267'
Lot 3
Lot 4
Spring Circle
100'
100'

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. # 16658

T.C. # 211-273-03.04

DATE February 27, 1980

NAME OF OWNER Glendenning, Eula

ADDRESS OF OWNER 4718 Addison Drive, Charlotte, NC

LOCATION OF LOT Spring Circle Lots 1 and 2, Block C

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system, due to the following reason:

Soil Structure Massive

Soil Permeability Unsuitable

John R. Adkisson

John R. Adkisson, Environmentalist