Date Received_____

APT No. 12307
P.O.
T. C. No. 231-101-01

Map Date_____

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER BOB McLEMORE & CO, INC
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER P.O. Box 25746 CHAR ZIP 28212

3) PHONE NO. Home_____ Office 545-6111


4) LOCATION OF PROPERTY BUCKBOARD LANE
(STREET OR COUNTY ROAD)

5) SUBDIVISION PROVIDENCE RIDGE LOT NO. 12 BLOCK NO. A

MAP BOOK NO._____ PAGE NO._____

6) DEED REFERENCE: DEED BOOK_____ PAGE NO._____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Peter L Bordel
OWNER

FORM NO. E1-11-3M-6-75

HEALTH DEPARTMENT'S COPY

SOIL INVESTIGATION REPORT

Date of Investigation May 5, 1977 APT NO. 12327

Owner Bob McLemore & Co., Inc.

Location of Property Beckboard Lane Lot No. 12 Block A

Soil Suitability Ratings Tax Code No. PL 231-101-01


Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Ceci	Heland	Chewacla	
2. Soil Slope	Suitable 2-6%	Suitable 2-6%	—	
3. Soil Depth	Suitable >48"	Unsuitable >48"	—	
4. Soil Texture	provisionally suitable Clay	Unsuitable 2.16 expansive Clay	—	
5. Soil Structure	provisionally suitable blocky	Unsuitable Massive	—	
6. Restrictive Horizons	—	—	—	
7. Soil Drainage	Suitable with subsoil drainage	Unsuitable poorly high water table	Unsuitable poorly drained	
8. Soil Permeability (Percolation Rate)	Provisionally suitable moderate	Unsuitable very slow >120 min/in	Unsuitable 30 second	high water table 6-18" from surface
9. Other	loamy fine	—	Unsuitable poorly drained	
10. Overall Rating	provisionally Suitable	Unsuitable	Unsuitable	

Remarks Recommendations Based on this investigation the lot was found to have provisionally suitable soils capable of installation of a septic tank system. System design should be based on a percolation rate of 60 min/in and should be placed in the area of Ceci soils.

Soil Engineer

3/30/75

DIAGRAM OF PROPERTY



3/18/75
EHD 539

Serial No. 0744

PTR No. 12387

Date Issued May 12, 1977

T C No P.O.231-101-01

Map Date


MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
SOIL INVESTIGATION REPORT

NAME OF OWNER Bob McLemore & Company, Inc.
LAST FIRST MIDDLE

ADDRESS OF OWNER P.O. Box 25746, Charlotte, NC ZIP 28212

LOCATION OF PROPERTY Buckboard Lane
STREET OR COUNTY ROAD

SUBDIVISION LOT NO 12 BLOCK NO A



PLOT PLAN

...Provisionally Suitable... 60 min/in. ...

1. ...
2. ...
3. ...
4. ...

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina Department of Human Resources, Division of Health Services and the Mecklenburg County Health Commission which were in effect on the date of issuance and is void if at any time in the future prior to completion of the system, these laws, rules and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

Soil Scientist

Environmental Health Director or Authorized Section Head

EHD-5-76

Environmental Health Department's Copy

SEE INSTRUCTIONS ON BACK

Date Received DEPARTMENT OF [illegible]

RECEIVED
SEP 30 1976
ENVIRONMENTAL HEALTH

ICAR (S) Application No. 1232 1

T. C. No 231-101-01


Map Date _____

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to:

1) X Install or Construct 2) ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface, soil absorption, effluent discharge.



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No of Bedrooms 3

5) Business Use — Max No Employees ___

6) Washing Machine X Yes ___ No

7) Garbage Disposal ___ Yes X No

8) Dishwasher X Yes ___ No

9) Water Supply:
- A) Individual Well ___
- B) Governmental System ___
- C) Community System:
  - 1. Well source X
  - 2. Governmental source ___

10) Sewage System:
House located within 200 feet of public sewer ___ Yes X No
House located within 200 feet of community sewer ___ Yes X No

11) FHA Case No -

12) VA Case No. -

13) NAME OF OWNER Lawrence J. Pilkowski, c/o Jesse L. Ibelel, Contractor
(LAST FIRST MIDDLE)

14) ADDRESS OF OWNER 9201 Indian Trail Rd. Charlotte, 28212

15) PHONE NO Home ___ Office 545-4206

16) LOCATION OF SYSTEM 10344 Stonemead Lane
(STREET OR COUNTY ROAD)

17) SUBDIVISION Providence Plaza Lot No. 12 Block No. A

Map Book No 15 Page No. 120

18) DEED REFERENCE — DEED BOOK ___ AT PAGE ___

19) HAS A PERCOLATION TEST BEEN RUN? X YES ___ NO DATE RUN 5-12-77

20) PTR NUMBER (See Instructions) 12327

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

9-12-77
DATE OF APPLICATION

Jesse L Ibelel
OWNER Contractor for Lawrence J. Pilkowski

FORM NO E-4-4-1-71

HEALTH DEPARTMENT'S COPY

Serial No. 2237

LA No. 12327

Date Issued September 20, 1978

T. C. No. P.0.231-101-01

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

TO THE BUILDING INSPECTION DEPARTMENT

IMPROVEMENT PERMIT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Pelkowski (LAST) Lawrence (FIRST) J. (MIDDLE)

ADDRESS OF OWNER c/oPete Goebel, 8200 Indian Trail Rd., Charlotte NC ZIP 28212

LOCATION OF LOT 10311 Stonemede Lane (STREET OR COUNTY ROAD)

SUBDIVISION Providence Ridge LOT NO. 12 BLOCK NO. A

MAP BOOK NO. 18 PAGE NO. 120

The above specified lot is approved by the Mecklenburg County Department of Environmental Health for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the soil investigation, on an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 12327. This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered and/or repaired in the same area where the soil investigation was run.

2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit

Steve Wood
Environmentalist

Environmental Health Director, or Authorized Section Head

EHD-5-76

Environmental Health Department's Copy


Date Issued 20 Nov 75 **Serial No. 2184** ICAR(S) Permit No. 12327

T C No. 231-101-18

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
INSTALLATION, CONSTUCTION, ALTERATION, AND/OR REPAIR PERMIT
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Permission is hereby given to ✓ Install or Construct, ___ Alter or Repair the individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in application 12327, dated 9/20/75 and the permit shall be void and of no effect if the information provided in the application is misrepresented in any way. All work shall be completed on or before 20 Dec. , after which date this permit shall be null and void.



PLOT OF SYSTEM

Permeability Rate 6 S

Liquid Capacity of Tank 1500 gal

Tank Construction P.C. Conc.

Absorption and or Nitrification Lines

Total Line Length 495' & 125'

Number of Lines 5 & 3

Distance from House 10'

Distance from Property Line 10'

Distance from Well Community

NAME OF OWNER Laurence J. Pelkowski

LOCATION OF PROPERTY 10311 Stonnedale Ln

This system is approved subject to construction requirements as set forth in the Regulations of the Mecklenburg County Health Ordinance in effect on the date of the granting of this permit. A certificate of approval must be issued by the Environmental Health Director before any system can be covered up or otherwise rendered inoperable. **The issuance of this permit does not in any way guarantee that the system anticipated to be constructed will operate properly, or relieve any person now or hereafter owning, controlling or using such system from any liability resulting from the failure of the system to operate properly.**

Comments: (9' x 42' x 17" Stone)

Comments: (15' x 99' x 17" Stone)

Division or Section Head

Environmentalist* Stephen J. Wood

* If this permit is for the installation or construction of a new system, it must be signed by the division or a section head of the Department of Environmental Health in order to be valid. Only the signature of the Environmentalist is required where an existing system is being altered or repaired.

EHD-5-76

Environmental Health Department's Copy

Date Issued 21 Dec. 78 Serial No. 2220 C of A (s) No. 12327

T. C. No. 231401-18

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

ENVIRONMENTAL HEALTH DIVISION

DEPARTMENT OF CONSTRUCTION

CERTIFICATE OF APPROVAL

(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

Name of Owner Pelkowski (LAST) Lawrence (FIRST) J. (MIDDLE)

Location of Property 10311 Stonemeade LN

Application Number 12327 Permit Number 12327

Inspection Data:

Liquid Capacity of Tank 1500 gal Tank Material P.C. Concrete

Total Length of Drain Tile 495' & 125' Number of Lines 5 & 4

Depth of Filter Material 17" Cover Depth 18"

Water Supply Source Community Distance from Water Source 100'

Excavation Inspected — (DATE) Tank Inspected 14 Dec. (DATE)

Nitrification Field Inspected 14, 15, 18, 21 Dec. (DATE)

Washing Machine Line Inspected If Applicable 14, 15, 18, 21 Dec. (DATE)

The undersigned has inspected the Individual Septic Tank System with subsurface, soil absorption, effluent discharge as described above and it has been ✓ installed or constructed, ~~altered~~ altered or repaired in accordance with the permit issued and the regulations of the Mecklenburg County Health Commission in effect on the date of issuance of the permit. The issuance of this Certificate of Approval does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling or using such system from any liability resulting from the failure of the system to operate properly. This Certificate of Approval is issued subject to those restrictions and conditions shown on the permit in addition to those listed below under comments. This Certificate of Approval shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

Comments Shared Gutter

Environmentalist

EHD-S-76

Environmental Health Department's Copy