Date Received 5·10·73

APT No 6R15

T. C No.

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER SOUTHMINISTER CO. INC. (LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER P. O. Box 23057 ZIP 28212

3) PHONE NO. Home 545-5107 Office 545-5900


4) LOCATION OF PROPERTY CARILLON WAY (STREET OR COUNTY ROAD)

5) SUBDIVISION CAMELOT LOT NO. 6 BLOCK NO. 95

MAP BOOK NO. 227 PAGE NO. 09

6) DEED REFERENCE: DEED BOOK PAGE NO.

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Southminster Co.
OWNER
John K Moore

FORM NO E-1-9-1-72

HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
Department of Public Health
1200 Blythe Boulevard
Charlotte, North Carolina 28203

Telephone 374-2113

Date Issued
1. _____
2. _____
3. _____

SDR No. _____
T.C. No. _____

SITE DISAPPROVAL REPORT
INDIVIDUAL SEPTIC TANK SYSTEM WITH SUBSURFACE,
SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER _____

ADDRESS OF OWNER _____ ZIP _____

LOCATION OF LOT _____

The lot described above has been disapproved for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

FAILURE TO PASS PERCOLATION TEST (60 minutes per inch or less)

	Test No.	Date of Test	Percolation Rate
____	1.	_____	_____ min/in
____	2.	_____	_____ min/in
____	3.	_____	_____ min/in

____ ON SITE INSPECTION REVEALED LOT TO BE UNSUITABLE FOR THE FOLLOWING REASON(S) Test holes [illegible] deep enough - [illegible] must be 36 inches deep.

John R Atkisson
Environmentalist

(Stencil No.)
MMD 398
F/70

FORM NO.
E-19-B-14-70

Serial No. 3125

PTR No. 6215

Date Issued May 24, 1973

T. C No. 227-095-06

Map Date 2-14-73

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER Southminister Company, Inc.
(LAST, FIRST, MIDDLE)

ADDRESS OF OWNER Post Office Box 23057 ZIP

LOCATION OF PROPERTY Carillon Way
(STREET OR COUNTY ROAD)

SUBDIVISION Camelot LOT NO. 6 BLOCK NO.



PLOT PLAN

This is to certify that a percolation test has been run and an on-site inspection made by the Mecklenburg County Health Department on the lot described above. The said test was conducted on that portion of the lot as indicated on above plot.

The percolation rate determined by the test was 58 min/in The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install, construct, alter, or repair the specific system shall be obtained from the Mecklenburg County Health Department prior to the beginning of any construction of buildings, or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater treatment system which must be installed will be determined by the Health Department prior to installation based on the percolation rate obtained above, and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area where the percolation test was run.
4. This approval is void if any grading, filling, or construction (including the drilling of a well) is performed on the lot which, in the opinion of the Health Department, renders the area where the percolation test was run unsuitable for the installation, construction, alteration, and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina State Board of Health and the Mecklenburg County Board of Health which were in effect on the date of issuance and is void if at any time in the future, prior to the completion of the system, these laws, rules, and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

John R Atkisson

Director, Environmental Health Division or
Authorized Section Head

FORM NO E-2-4-1-71

HEALTH DEPARTMENT'S COPY

SEE INSTRUCTIONS ON BACK

Date Received 7-21-73

ICAR(S) Application No 6215

T C No 227-095-06

Map Date 2-1-73


MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to:

1) ✓ Install or Construct 2) ___ Alter or Repair an individual septic tank wastewater treatment system with a subsurface soil absorption, effluent discharge



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No. of Bedrooms 4

5) Bathroom Use Max No Employees

6) Washing Machine ✓ Yes ___ No

7) Garbage Disposal ___ Yes ✓ No

8) Dishwasher ✓ Yes ___ No

9) Water Supply
A) Individual Well ✓
B) Governmental System
C) Community System
1) Well source
2) Governmental source

10) Sewage System
House located within 200 feet of public sewer ___ Yes ✓ No
House located within 200 feet of community sewer ___ Yes ✓ No

11) FHA Case No

12) VA Case No

13) NAME OF OWNER Southminster Co. (LAST / FIRST / MIDDLE)

14) ADDRESS OF OWNER P.O. Box 23052 Charlotte NC 28212

15) PHONE NO Home 372-3885 Office 545-5900

16) LOCATION OF SYSTEM Carlton Way (STREET OR COUNTY ROAD)

17) SUBDIVISION Camelot Lot No 6 Block No. 95

Map Book No 227 Page No. 09

18) DEED REFERENCE — DEED BOOK _____ AT PAGE _____ PR 758

19) HAS A PERCOLATION TEST BEEN RUN? ✓ YES ___ NO DATE RUN 5-24-73

20) PTR NUMBER (See Instructions) _____

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

DATE OF APPLICATION

OWNER Southminster Co. by John R Boone

FORM NO E-4-9-1-72

HEALTH DEPARTMENT'S COPY

Serial No. 3241

LA No. 6215

Date Issued July 30, 1973

T C. No. 227-095-06

Map Date 2-14-73

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Southminister Company
(LAST / FIRST / MIDDLE)

ADDRESS OF OWNER P.O. Box 23057 ZIP 28212

LOCATION OF LOT Carillon Way
(STREET OR COUNTY ROAD)

SUBDIVISION Camelot LOT NO 6 BLOCK NO. 95

MAP BOOK NO. _____ PAGE NO. _____

The above specified lot is approved by the Mecklenburg County Health Department for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the percolation test results which yielded a percolation rate of 58 min/in on an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 6215. This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered, and/or repaired in the same area where the percolation test was run.

2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit (s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit.

Thomas R. Ward
Environmentalist

John R. Atkisson
Director, Environmental Health Division or Authorized Section Head

FORM NO. E-3-4-1-71

HEALTH DEPARTMENT'S COPY