Date Received _____ Provided 30 yr 7/95 APT No. 1514

T. C. No. _____

Map Date _____

MECK COUNTY DEPARTMENT OF
RECEIVED
MAY 31 19/9
ENVIRONMENTAL HEALTH

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER _____ (LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER _____ ZIP _____

3) PHONE NO. Home _____ Office _____


4) LOCATION OF PROPERTY _____ (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

6) DEED REFERENCE: DEED BOOK 4160 PAGE NO. 0208

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Melanie McKee Abl
OWNER

EHD-5-76

15714
033-072-02

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

(Ground Absorption Sewage Disposal)

OWNER: ABLE Melanie McGee DATE REQUESTED: 4-26-79
ADDRESS: R-4 Box 414A PLAT NO.:
COUNTY: Wake LOT SIZE: 7.9A
LOCATION OF SITE: At the West END of Simpson Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10 U	S PS U	S PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S PS Clayey (U)	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S PS Massive (U)	S PS U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS 10 (U)	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	S PS Clay & Rock (U)	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S PS slow (U)	S PS U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS slow (U)	S PS U	S PS U	S PS U
8. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable			
SOIL SERIES	Wilkes (shallow-10")			

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)

Recommendations/Comments: Soils Are Very Shallow TO (10-15") Firm Saprolite.

Described By: W.B. Ramsey
Title: Soil Scientist Date: 6-7-79

DHS Form 2604 (2/77)
Sanitation

3

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15714
T.C. NO. 033-072-02
MAP DATE
DATE 6/11/79

NAME OF OWNER Melanie McGee Able

ADDRESS OF OWNER Route 9 Box 411A Charlotte, NC 28208

LOCATION OF LOT Simpson Road Pawcreek Township

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site cannot be approved for a septic tank system due to the following reason:


Soil Structure Unsuitable

Soil Permeability Unsuitable

John R. Adkisson, Environmentalist

EHD 398
7/77

R


200
Wilkes
2-10
200
1078 200 feet
Old Rd
End of Rd
Simpson Rd