

13131 SADDLETREE CT

21516234

6/5/08

marliwr

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

SERVICE REQUEST/WORK ORDER Retain as part of File # 8541

Log No.: File 8541 Section: INWS Hazard? [ ] Yes [ ] No

Date: 3/19/97 Parcel: <60 Days? [ ] Yes [ ] No

REQUESTING PERSON: Ralph Getz Phone 847-5619

Address _____ City _____ Zip _____


PROPERTY CONCERNED: Facility Name _____

Address 13131 Saddletree Court City Matt Zip 93105

SERVICE REQUESTED: malfunction. Surfacing near S.T.

ASSIGNED TO: Lisa Mialik TAKEN BY: Lisa Mialik

DATE	ACTIVITY REPORT
3/25/97	OBV. Mrs Ralph Getz present. Problem appears to be between S.T. & D-Box. Advised repair approved not needed, however, at her request I will contact David Jordan ~~to do~~ wish to be on-site when replacement/reconnection made.
3/26/97	PC w/ ~~Ralph Getz~~ David Jordan - Scheduled appt. for 3/27 ~11:30 am to check correction.
3/27/97	OBV. Mr. & Mrs Getz present. David Jordan, S.T. contractor present. D-Box + lines off D-Box clogged w/roots (+ sludge) New PVC pipe installed at D-Box - pipe discharge point in gravel bed. (Existing Bed was dry) Effluent being taken by existing gravel bed.



Closing S.R.

NOTIFICATION TO REQUESTING PERSON: ( ) Written (✓) Verbal ( ) Not Applicable

COMPLETED BY: Lisa B. Mialik, RS, 3/27/97

REVIEWED BY: _____, 3-31-97