Date Received 5/24/77

APT No 12491

T. C No 025 153 01p

Map Date

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER _____ (LAST) _____ (FIRST) _____ (MIDDLE)

2) ADDRESS OF OWNER _____ ZIP _____

3) PHONE NO Home _____ Office _____


4) LOCATION OF PROPERTY _____ (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO 5 BLOCK NO A

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot here nabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

_____
OWNER

FORM NO E-1-8-1-72

HEALTH DEPARTMENT S COPY

SOIL INVESTIGATION REPORT

Date of Investigation June 9, 1977 APT NO. 12491

Owner D. A. Harris & Carolina Development T.C. 025-193-00

Location of Property Williamsburg Circle LOT # 5

Soil Suitability Ratings


Soil Properties	Soil 1	Soil 2	Soil 3	Soil 4
1. Soil Series	Helena			
2. Soil Slope	Sl. rolling 2-6%			
3. Soil Depth	Sl. deep 4+'			
4. Soil Texture	Sandy loam & sandy clay			
5. Soil Structure	[illegible]			
6. Restrictive Horizons				
7. Soil Drainage	[illegible]			
8. Soil Permeability (Percolation Rate)	Mod. rapid 5/64 72 min/in			
9. Other				
10. Overall Rating	Acceptable			

Recommendations Based on this information, this site will be considered to be suitable for the installation of a septic tank system ~~[illegible]~~

~~[illegible]~~ William C. Marlin
SOIL SCIENTIST

3/15/75
FHD 509

DIAGRAM OF PROPERTY



3/18/75
EHD 539

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

DATE ISSUED
1. 6-13-77
2. _____
3. _____

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIP NO. 12491
T.C. NO. 025-153-06
M.P. DATE _____

NAME OF OWNER **Harris, W. W. & C. D.**

ADDRESS OF OWNER **1713 North Tryon St., Charlotte, NC 28206**

LOCATION OF LOT **Williamsburg Circle, Lot 6, Block A**

The lot described above is not recommended for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge due to the following:

Soil Structure Unsuitable.

Soil Permeability Unsuitable.

John R. Adkisson, Environmentalist
On Premises Waste Disposal Section

JRA: glr

(Stencil No.)
EHD 399
8/74

FORM NO.
E-19-8-21-74

Date Received _____

APT No. 12491

T. C. No. 035-[illegible]

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER [illegible] (LAST) [illegible] (FIRST) [illegible] (MIDDLE)

2) ADDRESS OF OWNER 1213 [illegible] St. ZIP 282[illegible]

3) PHONE NO Home 364 3[illegible] Office 333 4[illegible]

4) LOCATION OF PROPERTY Williamsburg Circle (STREET OR COUNTY ROAD)

5) SUBDIVISION Westminster Park LOT NO 5 BLOCK NO A

MAP BOOK NO 11 PAGE NO [illegible]

6) DEED REFERENCE DEED BOOK 2495 PAGE NO 128

Application is hereby made to the Mecklenburg County Department of Environmental Health for the purpose of a soil investigation on the property described in the lot herein as described for the purpose of determining the soil's suitability for an individual septic tank wastewater treatment system with subsurface soil absorption effluent disposal.

7) ACCURATELY DIAGRAM & DIMENSION LOT

[illegible]
OWNER

[illegible]

EHD-5-76

Environmental Health Department's Copy