Date Received 11-7-83

MECK[illegible]Y DEPARTMENT OF
RECEIVED
NOV 7 1983
ENVIRONMENTAL HEALTH

SIR No. 20257
T. C. No. 053-092-19
Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER ROBIE (LAST) RICHARD (FIRST) E. (MIDDLE)

2) ADDRESS OF OWNER RTD 5 Box 1019-M ZIP 28205

3) PHONE NO. Home 399-6550 Office 399-4444 C-21 WESTSIDE


4) LOCATION OF PROPERTY ~~Hartford Rd~~ Clarke Wood Rd
(STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. 10 BLOCK NO. _____

MAP BOOK NO 053-092-19 PAGE NO. _____

6) DEED REFERENCE DEED BOOK 4485 PAGE NO. 581

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

GO Richard E. Robie
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 20257
T.C. NO. PO 053-092-19
DATE: November 30, 1983

Richard E. Rorie
Rt. 5, Box 1019-M
Charlotte, NC 28208

RE: Property located at Hawfield Road, Plat #10

Dear Mr. Rorie:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20757

T.C. NO. PO 053-8274

(Ground Absorption Sewage Disposal)

OWNER: Richard E. Rossi
ADDRESS: Rt. 5, Box 1019-M Pineville, NC. 28134

PLAT NO: #10
LOT SIZE: 1 Acre

LOCATION OF SITE: Brayfield Road

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 8-8%	(S) PS 2-8% U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) 2:1 clay U	S PS — U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) Blocky U	S PS — U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS 30-36" U	S PS — U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS ∠36" U	S PS — U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) >36" U groundwater	S Depression PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	1UB	—		
9. SITE CLASSIFICATION	unsuitable	unsuitable		
10. SOIL SERIES	Mecklenburg-Lilac	Depression		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments: _____

Described by: [signature] Title: Soil Scientist

Date: 12-26-83

EHD 539 (Revised: 6/82)

2H


60'
Hew Field Rd
Markleeburg
300'
300'
60'

Date Received 11-7-83

RECEIVED
NOV 7 1983
ENVIRONMENTAL HEALTH

SR No. 20258

T. C. No. 053-09219

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Poole (LAST) Richard (FIRST) E (MIDDLE)

2) ADDRESS OF OWNER 8713 Ballantyne Ridge Dr. ZIP 28210

3) PHONE NO. Home 349-6556 Office 374-4454 (Charlotte)


4) LOCATION OF PROPERTY Ballantyne Ridge Dr. (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. 9 BLOCK NO. _____

MAP BOOK NO 053-092-19 PAGE NO. _____

6) DEED REFERENCE: DEED BOOK 4445 PAGE NO. 581

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Richard E. Poole
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 20258
T.C. NO. PO 053-092-19
DATE: November 30, 1983

Richard E. Rorie
Rt. 5, Box 1019-M
Charlotte, NC 28208

RE: Property located at Hawfield Road, Plat #9

Dear Mr. Rorie:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20258

T.C. NO. P065-092-19

(Ground Absorption Sewage Disposal)

OWNER: Richard E Rose
ADDRESS: Rt 5, Box 1019-19 Charlotte N.C. 28216
LOCATION OF SITE: Hampton Rd

PLAT NO: #9
LOT SIZE: 14,000

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) PS U 2-8%	(S) PS U 2-8%	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) U 2-1 clay	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U Blocky	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS (U) 30-36"	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS (U) +36"	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S (PS) U 36" to gravel water	S PS (U) Depression	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	10B	-		
9. SITE CLASSIFICATION	unsuitable	unsuitable		
10. SOIL SERIES	Alor Altenburg like	Depression		

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:


William R Rankin

Described by: William R Rankin
Title: Soil Scientist

Date: 11-25-73

EHD 539 (Revised: 6/82)

28


60'
Hawfield Rd
Marlboro - Like
Depression
300'
300'
60'