Date Received 5-15-76 App. No. (S) RECEIVED MAY 19 1976 ENVIRONMENTAL HEALTH Application No. (W) 7146

T. C. No. 139-112-02

Map Date 9-5-73

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR WELL WATER SUPPLY PERMIT

NAME OF OWNER Vanderburg (LAST) Michael (FIRST) Lane (MIDDLE)

ADDRESS OF OWNER 6910 B Baraway Drive ZIP 28212

PHONE NO. Home 537-3651 Office 376-7420 / Mrs 333-0157

LOCATION OF PROPERTY 11, 117 Valmere Drive, Ridgewood Est. (STREET or COUNTY ROAD)


SUBDIVISION Ridgewood Estates LOT NO. 14 BLOCK NO.

MAP BOOK NO. 17 PAGE NO. 232 & 233 FHA LOAN no

DEED REFERENCE: DEED BOOK (Last owner) 3678 / (Present owner) 3843 PAGE NO. 667 / 419 VA LOAN no

WELL CONTRACTOR LICENSE NO.

Application is hereby made to the Mecklenburg County Health Department for a permit to drill a water well on the hereinabove described lot to be used as a source of ✓ individual, _____ semi public, or _____ public water supply:



ACCURATELY DIAGRAM & DIMENSION LOT

5-17-76
DATE OF APPLICATION

Michael L. Vanderburg
OWNER

Application approved and permit hereby granted

Permit No: 7146

L R Brigman
ENVIRONMENTALIST

FORM NO. E-20-5-1-73

HEALTH DEPARTMENT'S COPY

Date Received 10-22-23

APT No. 7146
P.O.
T. C. No. 131-112-02
Map Date 4-5-13

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

APPLICATION FOR PERCOLATION TEST

1) NAME OF OWNER Investment Land Sales
(LAST / FIRST / MIDDLE)

2) ADDRESS OF OWNER 1740 E. Independence Blvd. ZIP 28205

3) PHONE NO. Home _____ Office 333-5492


4) LOCATION OF PROPERTY Lot 64 - Valmere Drive
(STREET OR COUNTY ROAD)

5) SUBDIVISION Eastside Estates - Addition LOT NO. 64 BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

6) DEED REFERENCE: DEED BOOK _____ PAGE NO. _____

Application is hereby made to the Mecklenburg County Health Department for the conduct of a percolation test and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

October 19, 1973

Investment Land Sales

OWNER Vice President

FORM NO. E-1-B-1-72

HEALTH DEPARTMENT'S COPY

Serial No. 3742

PTR No. 7146

P.O.

T. C. No. 139-112-02

Date Issued October 25, 1973

Map Date 9-5-73

Do Not Issue A Building Permit Based On This Form

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION


PERCOLATION TEST REPORT

NAME OF OWNER Investment Land Sales
(LAST) (FIRST) (MIDDLE)

ADDRESS OF OWNER 1740 East Independence Blvd. ZIP 28205

LOCATION OF PROPERTY Valmere Drive
(STREET OR COUNTY ROAD)

SUBDIVISION Eastside Estates LOT NO. 64 BLOCK NO.



PLOT PLAN

This is to certify that a percolation test has been run and an on-site inspection made by the Mecklenburg County Health Department on the lot described above. The said test was conducted on that portion of the lot as indicated on above plot.

The percolation rate determined by the test was 60 min/in* The said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install, construct, alter, or repair the specific system shall be obtained from the Mecklenburg County Health Department prior to the beginning of any construction of buildings, or of the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater teratment system which must be installed will be determined by the Health Department prior to installation based on the percolation rate obtained above, and on the size and type of building constructed thereon.
3. This approval is valid only if the system is installed in the immediate area where the percolation test was run.
4. This approval is void if any grading, filling, or construction (including the drilling of a well) is performed on the lot which, in the opinion of the Health Department, renders the area where the percolation test was run unsuitable for the installation, construction, alteration, and/or repair of such a system.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina State Board of Health and the Mecklenburg County Board of Health which were in effect on the date of issuance and is void if at any time in the future, prior to the completion of the system, these laws, rules, and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

*Results determined by soil analysis.

John R. Atkinson
Director, Environmental Health Division or Authorized Section Head

W. Everette Lyons, Jr. Soil Scientist

FORM NO. E-2-4-1-71

HEALTH DEPARTMENT'S COPY

Date Received 5-15-76

RECEIVED
MAY 19 1976
ENVIRONMENTAL HEALTH


ICAR (S) Application No. 7146
T. C. No. 139-116-42
Map Date 9-5-73

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

Application for an
Installation, Construction, Alteration, and/or Repair Permit
(Individual Septic Tank System with Subsurface, Soil Absorption, Effluent Discharge)

The owner of that property described hereinafter hereby applies to the Mecklenburg County Health Department for a permit to:

1) ✓ Install or Construct 2) ____ Alter or Repair an individual septic tank wastewater treatment system with a subsurface, soil absorption, effluent discharge.



3) PLOT PLAN (ACCURATELY DIMENSIONED)

4) No. of Bedrooms 3
5) Business Use (Max No Employees) none
6) Washing Machine ✓ Yes ____ No
7) Garbage Disposal ____ Yes ✓ No
8) Dishwasher ✓ Yes ____ No
9) Water Supply:
A) Individual Well ✓
B) Governmental System ____
C) Community System:
1. Well source ____
2 Governmental source ____
10) Sewage System:
House located within 200 feet of public sewer ____ Yes ✓ No
House located within 200 feet of community sewer ____ Yes ✓ No
11) FHA Case No. na
12) VA Case No. na

13) NAME OF OWNER Vanderburg (LAST) Michael (FIRST) Lane (MIDDLE)
14) ADDRESS OF OWNER 6910 B Baraway Drive, Charlotte 28212
15) PHONE NO. Home 537-3651 Office 376-7420 / Mrs. 333-0157
16) LOCATION OF SYSTEM 11,117 Valmere Drive (STREET OR COUNTY ROAD) Ridgewood Est., Meck. County
17) SUBDIVISION Ridgewood Estates Lot No. 14 Block No. ____
Map Book No. 17 Page No. 232 + 233
(18) Present owner Deed Book 3843 / Page 419
18) DEED REFERENCE — (as conveyed by original owner) DEED BOOK 2530 AT PAGE 340 + 159
(Last owner) 3678 667
PR → 40
19) HAS A PERCOLATION TEST BEEN RUN? ✓ YES ____ NO DATE RUN 10-23-73
20) PTR NUMBER (See Instructions) 7146

The undersigned person hereby agrees that he has read the foregoing application and that the contents of same are true. It is understood that any permit applied for herein shall be void and of no effect if any of the above facts are not true.

5-17-76
DATE OF APPLICATION

Michael L. Vanderburg
OWNER

FORM NO. E-4-4-2M-6-785

HEALTH DEPARTMENT'S COPY

Date Issued 5/21/76

Serial No. 5939

IMPROVEMENTS PERMIT

LA No. 7146

T. C. No. 139-116-13

Map Date 9-5-73

MECKLENBURG COUNTY HEALTH DEPARTMENT

ENVIRONMENTAL HEALTH DIVISION

TO THE BUILDING INSPECTION DEPARTMENT

APPROVAL OF LOT FOR INSTALLATION OF AN INDIVIDUAL SEPTIC TANK WITH SUBSURFACE, SOIL ABSORPTION, EFFLUENT DISCHARGE

NAME OF OWNER Vanderburg (LAST) Michael (FIRST) Lane (MIDDLE)

ADDRESS OF OWNER 6910 B Baraway Drive, Charlotte, N. C. ZIP 28212

LOCATION OF LOT 11117 Valmere Drive (STREET OR COUNTY ROAD)

SUBDIVISION Ridgewood Estates LOT NO 14 BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

The above specified lot is approved by the Mecklenburg County Health Department for the installation of an individual septic tank system with subsurface, soil absorption, effluent discharge based on the percolation test results which yielded a percolation rate of _____, on an on-site inspection of the said lot; and upon the information supplied in the "Application for an Installation, Construction, Alteration, and/or Repair Permit", number 7146. This approval is subject to the following terms and conditions:

1. That the nitrification field be installed, constructed, altered, and/or repaired in the same area where the percolation test was run.
2. That an "Installation, Construction, Alteration, and/or Repair Permit" be issued and in full force and effect when the system is installed, constructed, altred, and/or repaired and that the system be installed in accordance with same.

This approval may be revoked and the building inspection department requested to revoke any building permit(s) which have been issued to authorize construction on the said lot if at any time it is determined that any information contained in the "Application for an Installation, Construction, Alteration, and/or Repair Permit" is not correct or is untrue or that the septic-tank system is not being installed, constructed, altered and/or repaired in accordance with a valid Installation, Construction, Alteration, and/or Repair Permit.

Environmentalist

Director, Environmental Health Division or Authorized Section Head

FORM NO. E-3-9-2M-6-75

HEALTH DEPARTMENT COPY