


10631 FAIRVIEW RD

19722103

12/31/2007

duponbj

Groundwater and Wastewater Services File Imaging Project
May 2007
*Barcode Font = IDAutomationHC39M*

# CERTIFICATE OF COMPLETION/OPERATION PERMIT

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
700 NORTH TRYON ST., SUITE 211
CHARLOTTE, NC 28202
PHONE (704) 336-5102

FILE: 2542B DATE: 6/12/98

TC: 197 111 20 ☒ L ☐ CRT

SERIAL Nº 17326

Name of Owner Virginia H. Mullis Juris.: _____

Address of Property 10631 Fairview Rd

**Inspection Data:**

Tank Material Existing

Total Length of Drainfield ~~180'~~

Number of Lines ~~3~~ 3 @ 60'

Cover Depth 18"

Water Supply Source Well


Distance to Water Source >100'

Excavation Inspected 6/12/98

Tank(s) Inspected NA

Wash Line Inspected NA

High Water Alarm Inspected NA




Design 1998 Repair, S40SFB, 18"stone cecil CTR# Curt Bradley

The undersigned has inspected the Septic Tank System described above, and certifies it has been

☐ installed or constructed ☒ altered or repaired

☐ in accordance with the permit issued ☒ as detailed in the plot above

and meets the provisions of I5A NCAC 18A. 1900, "Laws And Rules For Sewage Treatment and Disposal Systems" in effect on the date of issuance of the permit. This issuance of this

☐ Certificate of Completion ☒ Operation Permit

does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling, or using such system from any liability resulting from the failure of the system to operate properly. This document is issued subject to those restrictions and conditions shown on the permit(s) and the provisions of I5A NCAC 18A. 1990 in addition to those listed below under "COMMENTS." This document shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

**Notice:** Disturbance of the designated repair area may result in the suspension/revocation of this permit.

COMMENTS: Repair to Existing system. Existing drainfield cut off because of property encroachment. Built 1956

Phila A. Walker R.S.
Environmental Health Specialist

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

FEE: NA

DATE: _____

# APPLICATION FOR IMPROVEMENT PERMIT FOR RESIDENTIAL SITE INDIVIDUAL WATER AND WASTEWATER SYSTEMS PROGRAM

REPAIR

[ ] CRT

TYPE APPLICATION: __ NEW SYSTEM __ EXPANSION/ ALTERATION OF EXISTING SYSTEM X REPAIR OF EXISTING SYSTEM

NORTH CAROLINA
DEPARTMENT OF ENVIRONMENT,
HEALTH, AND NATURAL RESOURCES
DIVISION OF ENVIRONMENTAL HEALTH
ON-SITE WASTEWATER SECTION

FILE #: 25488

PROPERTY INFORMATION (FROM ENGINEERING FORM) FOR JOB LOCATION:

TAX/PARCEL NUMBER: 197-111-20.

STREET ADDRESS: 10631 Fairview Rd.

SUBDIVISION OR MOBILE HOME PARK NAME:

LOT NUMBER:

TYPE OF BUILDING (CHECK ONE):

__ SINGLE MOBILE HOME(S)
__ DOUBLE WIDE (D)
__ HOUSE (H)
__ MODULAR HOME (M)
__ MULTIPLE FAMILY (U)
__ OTHER (O)

TOWNSHIP (CHECK ONE):

__ 0 MECKLENBURG
__ 1 CHARLOTTE
__ 2 DAVIDSON
__ 3 CORNELIUS
__ 4 PINEVILLE
__ 5 MATTHEWS
__ 6 HUNTERSVILLE
__ 7 MINT HILL

HEATED SQUARE FOOTAGE:

NUMBER OF BEDROOMS: 3

NUMBER OF OCCUPANTS: 2

CLOSING DATE _____

FOUNDATION FOR RESIDENCE:

__ WITHOUT BASEMENT
__ ON SLAB
__ CRAWL SPACE
__ WITH BASEMENT /PLUMBING
__ WITH BASEMENT /NO PLUMBING

IF EXPANSION/ALTERATION OF EXISTING SYSTEM, DESCRIBE THE PROPOSED BUILDING ADDITION:

WILL THERE BE A HOME BUSINESS IN THE RESIDENCE: __ YES __ NO TYPE: _____

WATER SUPPLY (CHECK ONE):

__ COMMUNITY (C)
__ MUNICIPAL (M)
__ PRIVATE WELL (P)
✓ SHARED WELL (S)
__ OTHER 'SPRINGS' (O)

IF ANY OF THE FOLLOWING ARE LOCATED ON THE PROPERTY, PLEASE SHOW LOCATION ON PLAT:

| | | | |
|---|---|---|---|
| BURIED CABLES, LANDFILLS, STUMPHOLES | __ YES __ NO | WELL, SPRINGS OR WATERLINES | __ YES __ NO |
| EXISTING WASTEWATER SYSTEMS | __ YES __ NO | DESIGNATED WETLANDS | __ YES __ NO |
| EASTMENTS OR RIGHT-OF-WAYS | __ YES __ NO | | |

| PROPERTY OWNER: Virginia H. Mullis | LEGAL AGENT FOR PROPERTY OWNER, IF APPLICABLE: |
|---|---|
| NAME: (LAST) Mullis (FIRST) Virginia (MI) H. | NAME: (LAST) Mullis (FIRST) Virginia (MI) H. |
| ADDRESS: 10631 Fairview Rd | DAYTIME PHONE: ( ) 545-4692 |
| CITY: Charlotte STATE: N.C ZIP: 28227 | |
| DAYTIME PHONE: (704) 545-4692 | |

WHAT DATE WAS THE PROPERTY ORIGINALLY DEEDED AND RECORDED? _____

An Improvement Permit is subject to suspension or revocation if site plans or the intended use change or if information submitted in this application is falsified or changed. The undersigned, owner, or legal agent for the owner, of the property described above as the "Job Location" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the Mecklenburg County Health Department to enter onto the property for the purpose of processing this request.

SIGNED: Virginia H. Mullis DATE: 6/2/98

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
c/o HAL MARSHALL CTR., SUITE 211, 700 N. TRYON ST., CHARLOTTE, N.C. 28202., (704) 336-5102

# INSTALLATION, CONSTRUCTION, ALTERATION, AND/OR REPAIR APPROVAL


HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
700 NORTH TRYON ST., SUITE 211
CHARLOTTE, NC 28202
PHONE (704) 336-5102

FILE: 25488 DATE: 6/2/98

TC: 197 111 20 ☑ L

SERIAL No 17227

Permission is hereby given to _____ Install or Construct, ✓ Alter or Repair the individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in the application dated 6/2/98. All work shall be completed on or before 7/2/98, after which date this permit shall be null and void. The system shall meet all of the construction requirements of I5A NCAC 18A. 1900 which are in effect on the date of the granting of this permit. A Certificate of Completion or an Operation Permit must be obtained from the Mecklenburg County Health Department before any system can be covered up or placed into service. The issuance of this permit does not in any way guarantee that the system anticipated to be constructed will operate properly, or relieve any person now or hereafter owning, controlling or using such system from any liability resulting from the failure of the system to operate properly.




PLOT OF SYSTEM
10631 Fairview Rd

Liquid Capacity of Septic Tank Existing gallons

Liquid Capacity of Dosing Tank – gallons

Tank Construction –

Trench Depth 36"

Absorption and/or Nitrification Lines:

Trench Width 9' feet

Trench Walls Scored and Porous Yes

Total Line Length Bed 210 feet

Number of Lines Bed 3 (70')

Depth of Stone 18" inches

Distance from House 5' feet

Distance from Property Line 10' feet

Distance from Well > 100' feet

NOTICE: This system shall not be installed while soils are in a wet condition.

NAME OF OWNER Virginia H. Mullis

LOCATION OF PROPERTY 10631 Fairview Rd

Comments: Repair to Existing system, Bed system 9'wd x 70'long x 18" stone cut off existing system (may encroach on recently divided property line)

Philo S. Walker R.S.
Environmental Health Specialist

WHITE - HEALTH DEPARTMENT's COPY • CANARY - E.H.S. COPY • PINK - OWNER OR AGENT's COPY