RECEIVED
Date Received 10-19-83
OCT 19 1983
ENVIRONMENTAL HEALTH

SR No. 20152

T. C. No PO 031-132-11

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Renfro (LAST) C. Elliott (FIRST) G. (MIDDLE)

2) ADDRESS OF OWNER RT 1, Box 355 Indian Trail, N.C. ZIP 28079

3) PHONE NO. Home 753-4465 Office —


4) LOCATION OF PROPERTY Caving Rd (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO. _____

6) DEED REFERENCE: DEED BOOK 031 PAGE NO. 13

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

C. G. Renfro
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SIR. NO. 20157
T.C. NO. PO 031-132-11
DATE: 12-12-83

Colbert G. Renfroe
% Mike Iachettu
Route 1, Box 356
Indian Trail, NC 28079

RE: Property located at Lawing Road

Dear Mr. Renfroe:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20157

T.C. NO. PO 031-132-11

(Ground Absorption Sewage Disposal)

OWNER: Robert D Rinehart
ADDRESS: Rt 1 Box 253 Huntersville
LOCATION OF SITE: Antioch Church Rd & Lawyers Road

PLAT NO: Lot 11
LOT SIZE: 1.35 ac

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 2-12 U	S complex PS slopes U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS 2-1 Clay U	S PS — U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Blocky U	S PS — U	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS 36-40" U	S PS — U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S PS >36" U	S PS — U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S Normal PS water Table U 40"	S Drainage way Area PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	II B	—		
9. SITE CLASSIFICATION	Unsuitable	Unsuitable		
10. SOIL SERIES	Helena-Urban	Drainageway		

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments: _____

Described by: William P. Mannix
Title: Soil Scientist

Date: 12-7-83

EHD 539 (Revised: 6/82)


Drainage
85'
310'
310'
Existing
House
Existing Rd.
85'

MECK COUNTY DEPARTMENT OF
Date Received [illegible]
OCT 1 9 1983
ENVIRONMENTAL HEALTH

SIR No. 20158

T. C. No. 031-132-11

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Rexford C. Cloer G
LAST FIRST MIDDLE

2) ADDRESS OF OWNER RT 1, Box 355 Indian Trail, N.C. ZIP 28079

3) PHONE NO. Home 753-4465 Office _____


4) LOCATION OF PROPERTY Lanning Rd
STREET OR COUNTY ROAD

5) SUBDIVISION _____ LOT NO. _____ BLOCK NO. _____

MAP BOOK NO. _____ PAGE NO. _____

6) DEED REFERENCE: DEED BOOK 031 PAGE NO. 13

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

C S Cloer
OWNER

EHD-5-76

ENVIRONMENTAL HEALTH DEPARTMENT'S COPY

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BL[illegible] THE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SIR. NO. 20158
T.C. NO. PO 031-132-11
DATE: 12-12-83

Colbert G. Renfroe
% Mike Iachettu
Route 1, Box 356
Indian Trail, NC 28079

RE: Property located at Lawing Road

Dear Mr. Renfroe:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can.be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure

DEPARTMENT OF
ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY,
NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 20158

T.C. NO. PO 21-122-11

(Ground Absorption Sewage Disposal)

OWNER: [illegible]
ADDRESS: Rt. 1, Box 355 Statesville, N.C. 28677

PLAT NO:
LOT SIZE: 25,500

LOCATION OF SITE: Sunny Road

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U 2-8%	S (PS) U 2-8%	S (PS) U 2-8%	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) U clay	S PS U 2-1 Clay	S PS U 2-1 Clay	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U Blocky	S (PS) U Blocky	S (PS) U Blocky	S PS U
4. SOIL DEPTH (inches)	S (PS) U 30-40"	S (PS) U 30-40"	S PS U (10-30"	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) U >30"	S (PS) U >30"	S PS U <30"	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S ~~PS~~ U >30"	S Perched water table 20-30" U	S (PS) U >35" to ground water	S PS U
7. OTHER (Specify)	S Acceptable Area PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IVA	IVB	IVB	
9. SITE CLASSIFICATION	unsuitable	unsuitable	unsuitable	
10. SOIL SERIES	Enon Like	Helena Like	Enon Like	

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:

Described by: [illegible]
Title: Soil Scientist

Date: 2-9-83

EHD 539 (Revised: 6/82)


110'
325'
60'