Date Received 6/1/79

APT No. 15670

T. C. No. 031-162-17

Map Date (6/16/21)

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Combs (LAST) Eugene (FIRST) (MIDDLE)

2) ADDRESS OF OWNER P.O. Box 7375 Charlotte, N.C. ZIP 28208

3) PHONE NO Home 394-6565 Office


4) LOCATION OF PROPERTY Forrest Drive (STREET OR COUNTY ROAD)

5) SUBDIVISION LOT NO 15, 16, 17 BLOCK NO

MAP BOOK NO PAGE NO

6) DEED REFERENCE DEED BOOK PAGE NO

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge.



7) ACCURATELY DIAGRAM & DIMENSION LOT

Eugene Combs
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

15470
031-162-47

(Ground Absorption Sewage Disposal)

OWNER: EUGENE COMBS DATE REQUESTED: 6-1-79
ADDRESS: R-6 Box 737 J PLAT NO.:
COUNTY: Meck. 28208 LOT SIZE: 15000
LOCATION OF SITE: RIVERSIDE DRIVE

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-10 U	S (PS) 2-10 U	S PS U	S PS U
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S (PS) Loamy U	S (PS) Loamy U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S (PS) Weak Blocky U	S (PS) Weak Blocky U	S PS U	S PS U
4. SOIL DEPTH (In.)	S PS > 48 (U)	S (PS) 48 U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Impervious Strata, Rock)	S PS Clay layer (U)	S (PS) None U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	S PS High water Table (U)	S (PS) Adequate U	S PS U	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S PS Slow (U)	S (PS) Moderate U	S PS U	S PS U
8. OTHER (Specify) *	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable	PROVISIONALLY Suitable		
SOIL SERIES	MONOCAN	Altavista		

S - Suitable PS - Provisionally Suitable U - Unsuitable


* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns.

Recommendations/Comments: * Note limitation of size of lot

Described By: William B. Ramsey
Title: Soil Scientist Date: 6-25-79

DHS Form 2604 (2/77)
Sanitation

2


A
B
C
ALTAVISTA
2-10
MONACAN
2-10
RIVER VIEW DRIVE

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15670
T.C. NO. 031-182-17
MAP DATE
DATE July 3, 1979

NAME OF OWNER Eugene Combs

ADDRESS OF OWNER Route 6, Box 737 J

LOCATION OF LOT Riverside Drive, Lot 17

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This is for the following reason:

Inadequate area available for installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

John R. Adkisson
John R. Adkisson, Environmentalist

EHD 39a
7/77

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR.NO. 15670
T.C. NO. 031-182-17
MAP DATE
DATE July 3, 1979

NAME OF OWNER Eugene Combs

ADDRESS OF OWNER Route 6, Box 737 J

LOCATION OF LOT Riverside Drive, Lot 17

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank-soil absorption system. This site [illegible]:

Inadequate area available for installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

John R. Adkisson

John R. Adkisson, Environmentalist

EHD 398
7/77

R