Date Received 1-5-84

RECEIVED
JAN 5 1984
MECKLENBURG COUNTY HEALTH

APT No. 20481

T. C. No. 053-015-02

Map Date _____

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER BAREFOOT (LAST) JERRY (FIRST) C. (MIDDLE)

2) ADDRESS OF OWNER 10041 MOORES CHAPEL RD ZIP 28208

3) PHONE NO Home 394-2259 Office 399-7765


4) LOCATION OF PROPERTY 833 WOODLAND LN. (STREET OR COUNTY ROAD)

5) SUBDIVISION WOODLAND PARK LOT NO 9 BLOCK NO. "A"

MAP BOOK NO 12 PAGE NO 61

6) DEED REFERENCE DEED BOOK 4665 PAGE NO 0007

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Jerry C. Barefoot
OWNER

EHD-5-76

Environmental Health Department's Copy

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO 20481

T.C. NO. 053-015-12

(Ground Absorption Sewage Disposal)

OWNER: Jerry C. Bousfield
ADDRESS: 7809 Monroe Expwy Rd Charlotte, NC. 28212

PLAT NO: Lot 9-A
LOT SIZE: Approx. 12,424

LOCATION OF SITE: 833 Wilmallard

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S PS 2-10% U	S PS U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S PS 2-1 clay U	S PS U	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS Blocky U	S PS U	S PS U	S PS U
4. SOIL DEPTH (inches)	S 30-36" PS U	S PS U	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S +36" PS U	S PS U	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S +36" PS To Ground water U	S PS U	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U

8. SOIL GROUP IC B

9. SITE CLASSIFICATION Unsuitable

10. SOIL SERIES Iredell

S - Suitable PS - Provisionally Suitable U - Unsuitable

**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)


Recommendations/Comments:

Described by: William A. Martin
Title: Soil Scientist

Date: 1-13-84

EHD 539 (Revised: 6/82)

2c


100'
Emm
2-10'0
167'
105'
105'
Woodland Lane

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE NORTH CAROLINA 28203

SIR. NO. 20481
T.C. NO. 053-015-02
DATE: 1-18-84

Jerry C. Barefoot
10041 Moores Chapel Road
Charlotte, NC 28208

RE: Property located at 833 Woodland Lane

Dear Mr. Barefoot:

At your request, a field investigation was conducted on the property designated above and was classified unsuitable for the installation of a ground absorption sewage disposal system. A copy of the site evaluation report is enclosed for your information.

Sites classified as unsuitable may be utilized for soil absorption disposal systems provided engineering, hydrogeologic, soil and environmental studies indicate that a suitable septic tank system or a suitable alternate system can-be reasonably expected to function satisfactorily.

Should you desire to file for permission to install an alternate system, plans and specifications prepared by a person with a demonstrated knowledge of ground absorption sewage treatment disposal systems, soil and rock characteristics, groundwater hydrology and drainage systems should be submitted to this office. They will be reviewed and if it is found that the system may be reasonably expected to function satisfactorily, approval will be given upon the execution by you of "Septic Tank Agreemnt Form" provided by this office.

If I may be of assistance, please feel free to call.

Sincerely,

Bill D. Hardister

Bill D. Hardister, Jr.
Environmental Health Supervisor

BDH/kbg

Enclosure