Date Received 2/20/80

APT No. 16662

T. C. No. 00.013-062-05

Map Date

BRADSHAW REALTY CO.
4126 TRIANGLE DRIVE
CL... N. C. 28208
TEL... (704) 399-2273

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Loving J. L. Estate
(LAST FIRST MIDDLE)

2) ADDRESS OF OWNER 4126 Triangle Drive ZIP 28208

3) PHONE NO. Home 399-2275 Office 399-2275

4) LOCATION OF PROPERTY Jim Kidd Road
(STREET OR COUNTY ROAD)


5) SUBDIVISION _____ LOT NO _____ BLOCK NO. _____

MAP BOOK NO _____ PAGE NO _____

6) DEED REFERENCE DEED BOOK _____ PAGE NO. _____

Tax 013-062-05

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

James A. Bradshaw Jr.
OWNER Agent for Estate

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX II
SITE EVALUATION

S.I.R. No. 16662
T.C. No. 20 013-062-00

(Ground Absorption Sewage Disposal)

OWNER: J. L. LAWING ESTATE DATE REQUESTED: 2-20-80
ADDRESS: 4126 TRIANGLE DRIVE PLAT NO:
COUNTY: Meck 28208 LOT SIZE: 10AC (100,000 Sq Ft. Checked
LOCATION OF SITE: Jim Kidd Rd

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) 2-5 U	S (PS) 2-10 U	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2:1 Clay)	S PS (U) 2-1 Clay	S mostly PS (U) 2-1 Clay	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S PS (U) massive	S PS (U) Massive	S PS U	S PS U
4. SOIL DEPTH (inches)	S PS (U) 48	S PS (U) 48	S PS U	S PS U
5. RESTRICTIVE HORIZONS (inches) (Impervious strata, Rock)	S PS (U) Clays	S PS (U) Clays	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S PS (U) slow	S PS (U) slow	S PS U	S PS U
7. SOIL PERMEABILITY (percolation rate)	S (PS) slow U	S PS (U) slow	S PS U	S PS U
8. OTHER (specify)	S PS U	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	✓ Unsuitable	Unsuitable		
10. SOIL SERIES	Iredell	ENON		

S - Suitable PS - Provisionally Suitable U - Unsuitable


** See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope)

Recommendations/Comments: I Would RATE This LOT VERY Severe.

Described By: W. B. Rawley
Title: Soil Scientist
Date: 2-25-80

DHS Form 2601
Sanitation
EHD 539 (2/80)

2


Check only To 500 feet
From Rd.
I
IREDELL
2-5
HOUSE
SITE
500
II
ENON
2-10
200
JIM KIDD RD

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
1200 BLYTHE BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

S.I.R. No. 16662

T.C. No. po 013-062-05

DATE March 5, 1980

NAME OF OWNER J.L. Laving Estate

ADDRESS OF OWNER 4126 Triangle Drive, Charlotte, NC 28208

LOCATION OF PROPERTY Jim Kidd Road (100,000 Square Feet Investigated)

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank, soil absorption system, due to the following reason:

Site Classification Unsuitable
(Soil Structure Massive, Soil Depth Unsuitable, Soil Permeability Unsuitable)

John R. Adkisson, Environmentalist