BM

FILE NUMBER: 7534B

Revised On: January 3, 2007

APPLICATION NUMBER: 3078

SEPTIC FEE: 200.00
DATE: 12-7-07
CK# 2180

MECKLENBURG COUNTY GROUNDWATER & WASTEWATER SERVICES
APPLICATION FOR A RESIDENTIAL SITE IMPROVEMENT PERMIT/ CONSTRUCTION AUTHORIZATION FOR AN ON-SITE WASTEWATER SYSTEM, NEW WELL INSTALLATION, OR REPAIR OF EXISTING WELL

WELL FEE: _____
DATE: _____

1. **SEPTIC / TYPE APPLICATION:** ☐ NONE ☒ NEW SYSTEM ☐ ALTERATION ☐ REPAIR ☐ MODIFIED PLOT PLAN

2. **WELL / TYPE APPLICATION:** ☐ NONE ☐ NEW WELL ☐ MAJOR REPAIR ☐ ABANDONMENT

3. **JOB LOCATION INFORMATION:**

TAX PARCEL NUMBER: 01124111
STREET ADDRESS: 14301 BLACK FARMS RD
CITY: HUNTERSVILLE
STATE: NC ZIP: 28078
SUBDIVISION NAME: SADDLEBROOK ESTATES
LOT #: 4 LOT SIZE (acres): 1.538
TOWNSHIP:

☐ 0-MECKLENBURG ☐ 3-CORNELIUS ☒ 6-HUNTERSVILLE
☐ 1-CHARLOTTE ☐ 4-PINEVILLE ☐ 7-MINT HILL
☐ 2-DAVIDSON ☐ 5-MATTHEWS

4. **BUILDING INFORMATION:**

BUILDING TYPE:
☐ SINGLE MOBILE HOME ☐ MODULAR HOME
☐ DOUBLE WIDE ☐ MULTIPLE FAMILY
☒ HOUSE ☐ OTHER _____
HEATED SQUARE FOOTAGE:
NUMBER OF BEDROOMS: 5
NUMBER OF OCCUPANTS:
FOUNDATION TYPE:
☐ CONCRETE SLAB ☐ BASEMENT WITH PLUMBING
☐ CRAWL SPACE ☐ BASMENT WITH NO PLUMBING

5. **IF PLANNING TO EXPAND OR ALTER THE EXISTING SYSTEM PLEASE COMPLETE THE FOLLOWING SECTION:** ☒ N/A

NUMBER OF BEDROOMS TO BE ADDED: _____ NUMBER OF ADDITIONAL OCCUPANTS IN THE RESIDENCE: _____

6. **WATER SUPPLY:** ☒ MUNICIPAL ☐ PUBLIC WELL ☐ PRIVATE WELL ☐ SHARED WELL ☐ SPRING

7. **PROPOSED USE OF WELL:** ☒ N/A ☐ IRRIGATION ☐ POTABLE ☐ GEOTHERMAL ☐ OTHER

8. **PLEASE INDICATE AND RANK DESIRED SEPTIC SYSTEM TYPE(S) IN ORDER OF PREFERENCE** *(1-MOST DESIRED 5-LEAST DESIRED):*

☐ ANY TYPE ☒ CONVENTIONAL ☒ ACCEPTED ☒ INNOVATIVE ☒ ALTERNATIVE ☐ OTHER _____

8A. **RANK:** 1 2 3 4 ___

9. **DO ANY OF THE FOLLOWING APPLY TO THE PROPERTY IN QUESTION? IF "YES" PLEASE ATTACH SUPPORTING DOCUMENTATION.**

BURIED CABLES, LANDFILLS, STUMPHOLES	☐ YES	☒ NO	GRADING/SOIL REMOVAL PERFORMED	☐ YES	☒ NO
EXISTING WASTEWATER SYSTEMS	☐ YES	☒ NO	JURISDICTIONAL WETLANDS	☐ YES	☒ NO
WELLS, SPRINGS, OR WATER LINES	☒ YES	☐ NO	APPROVAL REQUIRED BY ANY OTHER PUBLIC AGENCY	☐ YES	☒ NO
EASEMENTS OR RIGHT-OF-WAYS	☐ YES	☒ NO	WASTEWATER OTHER THAN DOMESTIC SEWAGE	☐ YES	☒ NO

10. **PROPERTY OWNER:**

NAME: DAVID DEQUICK
ADDRESS: 390 TEMPLETON RD
CITY: MOORESVILLE
STATE: NC ZIP: 28117
HOME PHONE: 704-664-7702 WORK PHONE:
MOBILE PHONE: FAX:

11. **OWNER'S LEGAL REPRESENTATIVE, IF APPLICABLE:**

NAME:
ADDRESS:
CITY:
STATE: ZIP:
HOME PHONE: WORK PHONE:
MOBILE PHONE: FAX:

12. **WHAT DATE WAS THE PROPERTY ORIGINALLY DEEDED AND RECORDED?** _____

13 **WHAT IS THE ANTICIPATED CLOSING DATE FOR THIS PROPERTY?** _____

14. **SEPTIC SYSTEM PERMIT APPLICATION SIGNATURE SECTION:**
If the information in this application is falsified, changed, or the site is altered, then the Improvement Permit and Authorization to Construct shall become invalid. I have read this application and certify that the information provided herein is true, complete and correct. Authorized county and state officials are granted right of entry to conduct necessary inspections to determine compliance with applicable laws and rules. I understand that I am solely responsible for the proper identification and labeling of all property lines and corners and making the site accessible so that a complete site evaluation can be performed. The permit is valid for either 60 months or is non-expiring depending upon the documentation submitted: complete site plan = 60 months, complete plat = non-expiring.

David J. DeQuick 9/13/07
Property Owner's or Owner's Legal Representative Signature Date

15. **WELL PERMIT APPLICATION SIGNATURE SECTION:**
If the information in this application is falsified, changed, or the site is altered, then the Well Permit shall become invalid. I have read this application and certify that the information provided herein is true, complete and correct. Authorized county and state officials are granted right of entry to conduct necessary inspections to determine compliance with applicable laws and rules. I understand that I am solely responsible for the proper identification and labeling of all property lines and corners and making the site accessible so that a complete site evaluation can be performed. The permit is valid for a period of 12 months from the date of issuance.

_____
Property Owner's or Owner's Legal Representative Signature Date

☐ SURVEY PLAT TO SCALE SUBMITTED ☒ SCALED SITE PLAN SUBMITTED ☐ UN-SCALED SITE PLAN SUBMITTED

MECKLENBURG COUNTY-GROUNDWATER & WASTEWATER SERVICES
700 N. TRYON ST., SUITE 211, CHARLOTTE, NC 28202 PHONE: (704) 336-5103 FAX: (704) 336-6894

MECKLENBURG COUNTY
LAND USE AND ENVIRONMENTAL SERVICES
Payment Receipt

Receipt Information

Date:	12/07/07	**Amount:**	4,000.00
Receipt #:	54027	**Tendered:**	4,000.00
Check / Auth #:	CHECK 2180	**Returned:**	4,000.00
Received By:	GLADNAG		


Account Information

Account #:	200000
Contractor:	DEQUICK DAVID & FREDA A
Attn:	
Address:	390 TEMPLETON RD
Address:	
City/State/Zip:	MOORESVILLE, NC 28117

Item	Description	Permit#	Quantity	Unit Price	Total Price
0701	Improvment Permit App-Residen 20 LOTS(1-20)BLACK FARMS RD		1	4,000.00	4,000.00

----------Outstanding Balances----------

Month-To-Date	Prior Month	30 Days	60 Days	90 Days	Balance


BEFORE YOU DIG !
CALL 1-800-632-4949
N.C. ONE-CALL CENTER
IT'S THE LAW !
Hind's Feet Farm, Inc.
Parcel# 011-241-13
Deed Book 11821, Page 465
Zoning - R
0.65 ACRES OPEN SPACE
GAZEBO AND WATER WHEEL
BUFFER TO SERVE AS ACCESS TO EXISTING POND
1.49 ACRES OPEN SPACE INCLUDING POND ACCESS & BUFFER
James O. McConnell
Parcel# 011-241-12
Deed Book 4677, Page 195
Zoning - R
ADD SIDEWALK BEHIND EX. DITCH ALONG FRONTAGE
Darlene O. Amberge
Parcel# 011-151-15
Deed Book 12631, Page 057
Deed Book 9238, Page 681
Zoning - R
DETENTION
BMP
0.85 ACRES OPEN SPACE IN POND
EXISTING POND
FIELD SURVEYED TOP OF BANK
60 FT BUFFER
BLACK FARM ROAD (SR 2228) MAINTAINENCE RIGHT-OF-WAY
S.W.I.M. BUFFER 30' UPLAND ZONE
TREE SAVE AREAS
AMENITY ACCESS EASEMENT
25' RADIUS TYP
ENTRANCE MEDIAN W/ LANDSCAPING
0.93 ACRES OPEN SPACE
WETLANDS
1.30 ACRES OPEN SPACE IN BUFFER
30' R/W FROM C/L
Renee White Cope
Parcel# 011-151-02
Deed Book 19907, Page 286
Deed Book 07805, Page 458
Zoning - R
Joshua Sarett and Gail Sarett
Parcel# 011-151-20
Deed Book 20142, Page 548
Deed Book 19907, Page 290
Deed Book 10527, Page 657
Zoning - R
REMAINDER OF ORIGINAL PLAT
Philip L. Black
Parcel# 011-151-03
Deed Book 5062, Page 986
0.244 ACRES
KBR Properties
Parcel# 011-151-04
Deed Book 19975, Page 809
Deed Book 01702, Page 110
Zoning - R
Russell W. Wallace and Judith G. Wallace
Parcel# 011-151-22
Deed Book 10537, Page 562
Zoning - R
Lander H. Bustle, Jr. and wife Judith C. Bustle
Parcel# 011-241-05
Deed Book 3044, Page 290
Zoning - TR
Lander H. Bustle, Jr. and wife Judith C. Bustle
Parcel# 011-241-06
Deed Book 4898, Page 694
Zoning - TR
Joseph Wyatt Henry
Parcel# 011-241-10
Deed Book 4854, Page 144
Zoning - TR
Guy W. and wife Nina W. Johnson
Parcel# 011-241-07
Deed Book 4947, Page 256
Zoning - TR
SADDLEBROOK ESTATES
(ZONED R)
SADDLEBROOK FARMS
(ZONED TR)
1 1.09 ACRES
2 1.16 ACRES
3 1.08 ACRES
4 0.98 ACRES
5 1.00 ACRES
6 0.99 ACRES
7 0.96 ACRES
8 1.01 ACRES
9 ACRES
10 0.92 ACRES
11 0.91 ACRES
12 0.89 ACRES
13 1.09 ACRES
14 0.80 ACRES
15 0.85 ACRES
16 0.81 ACRES
17 0.94 ACRES
18 0.90 ACRES
19 1.12 ACRES
20 1.57 ACRES
500'

Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 of 2
Property ID: PO 011-241-11
Lot #: 4
File #: 7534B
AppID: 3078

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: David DeQuick
Applicant:
Address: 390 Templeton Road, Mooresville, N. C. 28117
Date Evaluated: 12/19/07
Proposed Facility: Residence
Design Flow (.1949): 600gpd
Property Size: .98a
Location of Site: Off Black Farms Road
Property Recorded:
Water Supply: [x] Public [ ] Individual [ ] Well [ ] Spring [ ] Other
Evaluation Method: [ ] Auger Boring [x] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	LS, 6	0-6	GR/SCL	FR/SEXP/SS/SP	>48" TO SOIL WETNESS	48	N/A	NONE	PS, IV
	✔	6-20	SBK/ABK/C	FI/SEXP/S/P					.25GPD/FT^2
		20-48	SBK/C/W CINC	FR/SEXP/SS/SP					
2	"	0-3	GR/SCL	"	>44" TO SOIL WETNESS	44	"	"	"
	✔	3-29	SBK/ABK/C	FI/SEXP/S/P					
		29-44	SBK/CL	FR/SEXP/SS/SP					
3	LS, 10	0-5	GR/SCL	"	>48" TO SOIL WETNESS	48	"	"	"
	✔	5-21	SBK/C	FI/SEXP/S/P					
		21-48	SBK/CL	FR/SEXP/SS/SP					
4	"	0-6	GR/SCL	"	>47" TO SOIL WETNESS	27	US	"	US
	✔	6-27	ABK/SBK/C	VFI/EXP/VP/S					
		27-47	M/SCL	FR/SEXP/SS/SP					
					SITE LTAR .25GPD/FT^2				

Description	Initial System	Repair System
Available Space (.1945)		
System Type(s)		
Site LTAR		


Other Factors (.1946):
Soil Evaluation By: W. R. Marlin, LSS, 1/3/2007, W. R. Marlin
Others Present: J. Seagle
Site Classification (.1948):
Site Evaluation By:
Others Present:

COMMENTS:
100% repair

Landscape Position	Group	Texture	.1955 LTAR	Structure
R-Ridge	I	S-Sand	1.2 - 0.8	SG-Single Grain
SS-Shoulder Slope		LS-Loamy Sand		M-Massive
LS-Linear Slope				CR-Crumb
FS-Foot Slope	II	SL-Sandy Loam	0.8 - 0.6	GR-Granular
NS-Nose Slope		L-Loam		SBK-Subangular Blocky
HS-Head Slope				ABK-Angular Blocky
CC-Concave Slope	III	SI-Silt	0.6 - 0.3	PL-Platy
CV-Convex Slope		SICL-Silty Clay Loam		PR-Prismatic
T-Terrace				
FP-Flood Plain		CL-Clay Loam		
		SCL-Sandy Clay Loam		
	IV	SC-Sandy Clay	0.4 - 0.1	
		SIC-Silty Clay		
		C-Clay		

Consistence Moist	Consistence Wet	Mineralogy
VFR-Very Friable	NS-Non-Sticky	SEXP-Slightly Expansive
FR-Friable	SS-Slightly Sticky	EXP-Expansive
FI-Firm	S-Sticky	
VFI-Very Firm	VS-Very Sticky	
EFI-Extremely Firm	NP-Non-Plastic	
	SP-Slightly Plastic	
	P-Plastic	
	VP-Very Plastic	

Sketch of Soil Evaluation Locations



Department of Environment, Health, and Natural Resources
Division of Environmental Health
On-site Wastewater Section

Sheet: 1 of 2
Property ID: 011-241-11
Lot #: 4
File #: 7534B
AppID: 3078

SOIL/SITE EVALUATION for ON-SITE WASTEWATER SYSTEM

Owner: DAVID DEQUICK
Applicant: DAVID DEQUICK
Address: 390 TEMPLETON RD Mooresville NC 28117
Date Evaluated: 10/27/2009
Proposed Facility: Residence
Design Flow (.1949): 600gpd
Property Size:
Location of Site: 14301 BLACK FARMS RD Huntersville NC
Property Recorded:
Water Supply: [ ] Public [ ] Individual [x] Well [ ] Spring [ ] Other
Evaluation Method: [ ] Auger Boring [x] Pit [ ] Cut
Type of Wastewater: [x] Sewage [ ] Industrial Process [ ] Mixed

PROFILE #	.1940 Landscape Position/ Slope%	Horizon Depth (IN.)	SOIL MORPHOLOGY .1941 .1941 Structure/ Texture	.1941 Consistence Mineralogy	b PROFILE FACTORS .1942 Soil Wetness/ Color	.1943 Soil Depth (IN.)	.1956 Sapro Class	.1944 Restr Horiz	Profile Class & LTAR
1	15%	0-10	GR/SL	FR,SS,SP,SXP	MOTTLES @ 20"	50	N/A	NONE	U.S III
	L.S	10-20	GR-SBK/SCL	FR-FI,SS,SP,SXP	2.5YR 5/1				
Repair		20-50	M/SCL	VFI,SAPROLITE					
				Sampled at 35" depth					
2	"	0-4	GR/SCL	FR,SS,SP,SXP	>48" TO SOIL WETNESS	60	"	"	U.S IV
Initial		4-22	PR/C	FI,S,P,EXP					
		22-60	M/SCL	VFI,SAPROLITE					
				NEED KSAT RESULTS					

Description	Initial System	Repair System
Available Space (.1945)		
System Type(s)		
Site LTAR		

Other Factors (.1946):
Soil Evaluation By: Jason Jackson
Others Present: Jeremy Michelone, Bill Marlin
Site Classification (.1948): Unsuitable
Site Evaluation By:
Others Present:

Sheet: 2 of 2

COMMENTS: 100% REPAIR AREA REQUIRED. FILE #: 7534B

SAMPLES COLLECTED FOR PARTICLE ANALYSIS


LOT EVALUATION DIAGRAM ATTACHED

SAMPLE#4

Landscape Position	Group	Texture	.1955 LTAR	Structure
R-Ridge	I	S-Sand	1.2 - 0.8	SG-Single Grain
SS-Shoulder Slope		LS-Loamy Sand		M-Massive
LS-Linear Slope				CR-Crumb
FS-Foot Slope	II	SL-Sandy Loam	0.8 - 0.6	GR-Granular
NS-Nose Slope		L-Loam		SBK-Subangular Blocky
HS-Head Slope				ABK-Angular Blocky
CC-Concave Slope	III	SI-Silt	0.6 - 0.3	PL-Platy
CV-Convex Slope		SICL-Silty Clay Loam		PR-Prismatic
T-Terrace				
FP-Flood Plain		CL-Clay Loam		
		SCL-Sandy Clay Loam		
	IV	SC-Sandy Clay	0.4 - 0.1	
		SIC-Silty Clay		
		C-Clay		

Consistence Moist	Consistence Wet	Mineralogy
VFR-Very Friable	NS-Non-Sticky	SEXP-Slightly Expansive
FR-Friable	SS-Slightly Sticky	EXP-Expansive
FI-Firm	S-Sticky	
VFI-Very Firm	VS-Very Sticky	
EFI-Extremely Firm	NP-Non-Plastic	
	SP-Slightly Plastic	
	P-Plastic	
	VP-Very Plastic	

Sketch of Soil Evaluation Locations



A&L Eastern Laboratories, Inc.

7621 Whitepine Road Richmond, Virginia 23237 (804) 743-9401 Fax (804) 271-6446

www.allabs.com

TEXTURE ANALYSIS

Client :
Mecklenburg County Government
700 N Tryon St - Ste 211
Finance Department 11th floor
Charlotte , NC 28202

Grower :
MECKLENBURG COUNTY GOVERNMENT

Date Received : 11/04/2009

Report No : 09-308-0563
Cust No : 46867
Date Printed : 11/06/2009
Page : 1 of 1
Submitted By: JASON JACKSON

Lab No	Sample Identification	Percent Sand	Percent Silt	Percent Clay	Textural Classification
00919	1	84.4	10.4	5.2	Loamy Sand
00920	2	80.4	10.4	9.2	Loamy Sand
00921	3	76.4	16.4	7.2	Sandy Loam
00922	4	72.4	20.4	7.2	Sandy Loam

Analysis prepared by: A&L Eastern Laboratories, Inc.

MEADE GUNNELL
engineering & surveying, p.c.

19810-A West Catawba Avenue
Cornelius, NC 28031
704.655.7290 704.655.7291 (fax)

Additional Septic Application Information

Saddlebrook Estates Subdivision
14301 Black Farms Rd
Huntersville, NC 28078

Lot Number 4

1. See site plan for location of existing well in 80 ft buffer off of lot.