Date Received 6-15-83

RECEIVED
JUN 15 1983
ENVIRONMENTAL HEALTH

SIR No. 19776

T. C. No 163-141-04

Map Date

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Mullis (LAST) Roy (FIRST) P. (MIDDLE)

2) ADDRESS OF OWNER RFD 3, Box 682, Monroe, N.C. ZIP 28110

3) PHONE NO. Home _____ Office _____


4) LOCATION OF PROPERTY 2540 Valleyview Drive, Charlotte, N.C. 28215 (STREET OR COUNTY ROAD)

5) SUBDIVISION _____ LOT NO 42 BLOCK NO 141

MAP BOOK NO 103 PAGE NO 10

6) DEED REFERENCE DEED BOOK 1998 PAGE NO 464

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinabove described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

Carrie J. Mullis
OWNER

EHD-5-74

Environmental Health Department's Copy

Serial No. 5078

SIR No. 19776

T C No. 103-141-04

Date Issued 6-22-83

Map Date


MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
SOIL INVESTIGATION REPORT

NAME OF OWNER Mullis, (LAST) Roy (FIRST) P. (MIDDLE)

ADDRESS OF OWNER RFD 3, Box 682, Monroe, NC ZIP 28110

LOCATION OF PROPERTY 2540 Valleyview Drive, (STREET OR COUNTY ROAD) Charlotte, NC 28215

SUBDIVISION LOT NO 2 BLOCK NO 141



PLOT PLAN

This is to certify that a soil investigation and percolation test was made by the Mecklenburg County Department of Environmental Health on the lot described above. The said investigation was conducted on that portion of the lot as indicated on the above plot.

The permeability rate determined by the investigation was **Provisionally Suitable** said lot is approved for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption effluent discharge subject to the following terms and conditions:

1. A permit to install or construct, alter or repair a sewage system must be obtained from the Mecklenburg County Department of Environmental Health prior to the location and construction of buildings and the wastewater treatment system on the said lot.
2. The size of the septic tank wastewater treatment system and the method of installation will be determined by the Mecklenburg County Department of Environmental Health at the time of application for a permit and is based on the permeability rate obtained above and on the size and type of building to be constructed thereon.
3. This approval is valid only for the system as indicated on the above plot plan and is granted as acceptable for system installation on the above plot.
4. This approval is void at any time if alterations of the character existing at the time of the soil investigation are made, or if the Mecklenburg County Department of Environmental Health renders the area indicated as acceptable for system installation unsuitable for use as the result of construction activity on and improvements to the lot.

This approval is granted based on the laws of the State of North Carolina and the rules and regulations of the North Carolina Department of Human Resources, Division of Health Services and the Mecklenburg County Health Commission which were in effect on the date of issuance and is void if at any time in the future, prior to completion of the system these laws, rules and regulations are changed such that this approval would not have been granted had the new or revised laws, rules, and regulations been in effect on the issue date.

Soil Scientist

Environmental Health Director or
Authorized Section Head

Environmental Health Form No. 3 (Rev. 5/82)

DEPARTMENT OF ENVIRONMENTAL HEALTH
MECKLENBURG COUNTY, NORTH CAROLINA

SITE EVALUATION

S.I.R. NO. 19776

T.C. NO. 103-141-04

(Ground Absorption Sewage Disposal)

OWNER: Roy Mullis
ADDRESS: R-3 Box 682 Monroe 28110
PLAT NO:
LOT SIZE: 14,890
LOCATION OF SITE: 2540 Valley View Drive

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	S (PS) U — 2-4	S (PS) U — 2-4	S PS U	S PS U
2. SOIL TEXTURE (12-36 inches) Sandy, Loamy, Clayey (Note 2-1 Clay)	S (PS) U — Clayey	S (PS) U — Clayey	S PS U	S PS U
3. SOIL STRUCTURE (12-36 inches)	S (PS) U — Blocky	S (PS) U — Blocky	S PS U	S PS U
4. SOIL DEPTH (inches)	S (PS) U — 40-45	S PS (U) — 20"	S PS U	S PS U
5. RESTRICTIVE HORIZONS (Inches) (Impervious strata, Rock)	S (PS) U — None	S PS (U) — Saprolite	S PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (external and internal)	S Adequate U	S PS (U) — Saturated At 20"	S PS U	S PS U
7. OTHER (Specify)	S PS U	S PS U	S PS U	S PS U
8. SOIL GROUP	IIa	IIa		
9. SITE CLASSIFICATION	Acceptable	Unsuitable		
10. SOIL SERIES	Cecil	Cecil in Low Area		

S - Suitable PS - Provisionally Suitable U - Unsuitable


**See Diagram on Back (includes: soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slopes)

Recommendations/Comments:

Described by: W. B. Ramsey
Title: Sanitarian

Date: 6-20-83

EHD 539 (Revised: 6/82)


117
Ponded Area
in Cecil
Unsuitable
78
168
178
100
Cecil
2-4
Psuitable
117
Valley View Drive