Date Received 7/[illegible]

MECK COUNTY DEPARTMENT OF
RECEIVED
JUL 9 1979
ENVIRONMENTAL HEALTH

APT No. 15892
T. C. No. [illegible]
Map Date [illegible]

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH

APPLICATION FOR SOIL INVESTIGATION

1) NAME OF OWNER Lawson (LAST) F. (FIRST) Wyatt (MIDDLE)

2) ADDRESS OF OWNER 3733 Solana Road, Coconut Grove, Miami Fla. ZIP 33133

3) PHONE NO Home (305) 445-3209 Office N/A


4) LOCATION OF PROPERTY Westside of Valley Road (STREET OR COUNTY ROAD)

5) SUBDIVISION Lakeside Acres LOT NO 43 BLOCK NO. Section 1

MAP BOOK NO 7 PAGE NO 69 & 71

6) DEED REFERENCE DEED BOOK 1723 PAGE NO 155

Application is hereby made to the Mecklenburg County Department of Environmental Health for the conduct of a soil investigation and an on site inspection of the lot hereinafter described for the purpose of determining if the lot is suitable for the installation of an individual septic tank wastewater treatment system with subsurface soil absorption, effluent discharge



7) ACCURATELY DIAGRAM & DIMENSION LOT

R. V. Hedrick, Agent
OWNER

EHD-5-76

Environmental Health Department's Copy

NORTH CAROLINA
DEPARTMENT OF HUMAN RESOURCES
DIVISION OF HEALTH SERVICES
RALEIGH, NORTH CAROLINA

APPENDIX H
SITE EVALUATION

APT 15842

(Ground Absorption Sewage Disposal)

OWNER: F. Wyatt Lawson
ADDRESS: 3733 - Riviera Acres
COUNTY: Coconut Grove, Miami, Fla.
LOCATION OF SITE: Valley Rd.

DATE REQUESTED:
PLAT NO.: 227-023-16 Lot 43
LOT SIZE: 34,327

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4
1. SLOPE (%)	(S) 2-15% PS U	S Complex PS Slopes (U)	(S) 2-6% PS U	S PS U +
2. SOIL TEXTURE (12-36 in.) (Sandy, loamy, clayey, Note 2:1, Clay)	S (PS) Clay U	S (PS) Clay U	S PS U	S PS U
3. SOIL STRUCTURE (12.36 in.) (Clayey Soils)	S (PS) Blocky U	S (PS) Blocky U	S PS U	S PS U
4. SOIL DEPTH (In.)	(S) 48" PS U	S Depth PS Variable (U)	S PS U	S PS U
5. RESTRICTIVE HORIZONS (In.) (Imprevious Strata, Rock)	(S) None PS U	(S) None PS U	(S) None PS U	S PS U
6. SOIL DRAINAGE/GROUNDWATER (External & Internal)	(S) 36" to PS ground U water	S Eroded PS Areas (U) Channel Water	S Driveway PS way (U)	S PS U
7. SOIL PERMEABILITY (Percolation Rate)	S (PS) Moderate U	S (PS) Moderate U	S PS Slow U	S PS U
8. OTHER (Specify)	S Road cut PS Area of (U) Acceptable Soils	S PS U	S PS U	S PS U
9. SITE CLASSIFICATION	Unsuitable	Unsuitable	Unsuitable	
SOIL SERIES	Cecil	Eroded Area	Dry Retention Area	

S - Suitable PS - Provisionally Suitable U - Unsuitable

* See Diagram on Back (Include: Soil areas, property lines, roads, streams, gullies, wet areas, fill areas, wells, water bodies, slope patterns, etc)


Recommendations/Comments:

Described By: William F. Marlin

Title: Jr C Sanitarian Date: 7-23-79

DHS Form 2601 (2/77)
Sanitation

3


Drainage Way
Existing Areas
163'
Valley Rd
Cont. 6-15-6
280'
Cont. 3-15-6

MECKLENBURG COUNTY
DEPARTMENT OF ENVIRONMENTAL HEALTH
[illegible] BOULEVARD
CHARLOTTE, NORTH CAROLINA 28203

SITE INVESTIGATION REPORT
INDIVIDUAL SEPTIC TANK SYSTEM
WITH SUBSURFACE,
SOIL ABSORPTION,
EFFLUENT DISCHARGE

SIR. NO. 15892
T.C. NO. 227-093-16
MAP DATE
DATE July 24, 1979

NAME OF OWNER F. Wyatt Lawson

ADDRESS OF OWNER 3738 3733 Solana Road, Coconut Grove, Miami Fla. 33133

LOCATION OF LOT Westside of Valley Road, Lot 43, Section 1

As determined under the Rules and Regulations promulgated by the Commission for Health Services, Division of Health Services, North Carolina Department of Human Resources, Raleigh, North Carolina, the soils on the lot described above were found to be unsuitable for the installation of an individual septic tank - soil absorption system. This site cannot be approved for a septic tank system due to the following reason:

Complex Slopes
Drainageway
Inadequate area of acceptable soils for the installation of ground absorption sewage disposal system in accordance with North Carolina Department of Human Resources specifications.

John R. Adkisson

John R. Adkisson, Environmentalist

R