

15314 MILLVIEW TRACE LN

13915241

6/21/2007

duponbj

Groundwater and Wastewater Services File Imaging Project
May 2007
Barcode Font = IDAutomationHC39M

MECKLENBURG COUNTY HEALTH DEPARTMENT
Environmental Health Division
Groundwater & Wastewater Services

July 14, 2005

Timothy Brooks
15314 Millview Trace Lane
Charlotte, NC 28227

Dear Mr. Brooks:

Re: Bacteriological Well Sample Results / Septic Inspection Report

Enclosed you should find a copy of the laboratory analysis of the well water sample that was collected at 15314 Millview Trace Lane on July 6, 2005. The laboratory analysis of the well water sample was reported to be NEGATIVE for total coliform bacteria.

Enclosed you should also find a copy of the report for the septic system inspection that was conducted on July 6, 2005.

Please contact me at (704) 336-5568 if you have any questions.

Sincerely,

Trevor Thomason, R.S.I.
Managed Systems Program Coordinator
Groundwater & Wastewater Services

Enclosures: (4)

CHARLOTTE.

Laboratory Analysis Report

Report Date: 7/8/2005 02:03 PM

LABORATORY SERVICES DIVISION

LOCATION: 6745A
LOC ID: G-GWS
SAMPLE DATE-TIME: 7/6/2005 15:00
SAMPLE DESCRIPTION: Grab

SAMPLE ID: AB41620
CHAIN OF CUSTODY #: 05070060

	Parameter	Result	Units	RL	Method	Start Date/ Time	Analyst
AB41620	**E. COLI-PA**	**absent**	**P/A**		SM 9223B	7/7/2005 8:00	KEK
AB41620	**Total Coliform**	**absent**	**P/A**		SM 9223B	7/7/2005 8:00	KEK

Comment:

Laboratory Supervisor: _____

Laboratory Certifications: McAlpine NC DENR No.148; Brookshire NC DENR No.162; Hal Marshall N.C. DENR No. 192, N.C. DHHS Laboratory No. 37527

CHARLOTTE-MECKLENBURG UTILITIES - LABORATORY SERVICES DIVISION

Hal Marshall Laboratory, 700 North Tryon St., Charlotte, NC 28202, 704/336-5460

CHAIN OF CUSTODY RECORD

PAGE 1 OF 1

CLIENT: MECKLENBURG COUNTY, LUESA - GROUNDWATER AND WASTEWATER SERVICES

FACILITY: GROUNDWATER (Potable Water) - Brooks Residence

LOCATION / ADDRESS: 15314 Millview Trace Ln., Charlotte, NC 28227

LAB CODE (circle one): REAL PRIV NEW TNC MPL (PME) OTHER

Send Report To: Trevor Thomason, 700N Tryon St. Ste. 205, Charlotte, NC 28202

COC#: 0567006D

Sampled By (Print Name): Trevor Thomason

SAMPLE ID	Sample Collector's Initials	Sample Collection: Begin Date and Time	Sample Collection: End Date and Time	Chlorinated System	Sample Temperature: Collection Temp	Sample Temperature: Receipt Temp	Sample Type: Depth Composite	Sample Type: Auto Composite	Sample Type: Hand Comp	Sample Type: Grab	Sample Containers: Plastic	Sample Containers: Glass	Sample Containers: # Containers	Chemical Preservative: None	HNO3	H2SO4	NaOH	HCl	Na2S2O3	pH Correct	Analyses Requested: Total Coliform	Nitrate	Nitrite	Nitrate + Nitrite	Fluoride	Hardness	Metals	Fecal Coliform	Fecal Strep	Pest/PCB, EPA 608	Herb, EPA 8151	VOA, EPA 8260	Semis, EPA 8270
4162D GWS-6745A	TCT	7/6/2005 15:00		N						X	100 ml		1						X		X											

NOTES: Complete yellow shaded sections; each "X" needs to be circled.

Itemize requested Metals here:

COMMENTS: ****3-DAY TAT REQUESTED****

Relinquished By: (Signature)	Received By: (Signature)	Date	Time
[signature]	[signature]	07-07-05	0743
Relinquished By: (Signature)	Received By: (Signature)	Date	Time
Relinquished By: (Signature)	Received By: (Signature)	Date	Time
Relinquished By: (Signature)	Received By: (Signature)	Date	Time

Form Revision 05; effective 03/15/2005

CODES: **REAL**=REAL ESTATE TRANSACTION **PRIV**=PRIVATE WELL SAMPLING BY REQUEST OR FOR REPAIR **NEW**=NEW WELL (PERMIT)

N.C. Department of Environment and Natural Resources
Division of Environmental Health

Inspection of Engineered Subsurface Wastewater System

Mecklenburg County **Health Department**	Brooks Residence **Name of Establishment**	6745A **Permit/Project No.**
15314 Millview Trace Ln., 28227 **Location**	3-Bedroom House **Type of Establishment**	360 GPD **Design Flow**
Timothy Brooks **Owner/Agent**	Same as location address **Address**	(704) 573-9278 **Phone**
N/A **Operator**	N/A **Address**	N/A **Phone**
IIIb **System Type**	7/6/2005 **Date of Inspection**	July 2010 **Next Inspection Due**

	Yes	No	N/A	Comments:
1. ESTABLISHMENT:				
a. Type, size, and sewage flow in accordance with permit?	☒	☐	☐	1.a. Small trickle of water entering pump tank. Check for leaking toilet.
2. COLLECTION SYSTEM:				
a. No evidence of leaks into or out from sewer lines/manholes?	☒	☐	☐	
b. Free of blockages/solids buildup in lines or manholes?	☒	☐	☐	
3. TANKAGE: (Grease Traps/Lift Stations/Septic/Dosing Tanks)				
a. Tank risers accessible and surface water diverted?	☒	☐	☐	
b. Tanks and access manholes structurally sound, watertight?	☒	☐	☐	
c. Sanitary tee(s) in good working condition?.....	☐	☐	☒	3.c. Sanitary tee was not inspected.
d. Tanks pumped, cleaned out as needed?.....	☐	☐	☐	*See comment in maintenance section.
4. RAW SEWAGE LIFT STATION (if present):				
a. Required pumps present, operating, and cycling properly	☐	☐	☒	
b. High-water alarm present and operating properly?	☐	☐	☒	
c. Floats/pipe/valves/disconnects in good condition?	☐	☐	☒	
5. EFFLUENT DOSING SYSTEM:				
a. Effluent appears clear, free of excess solids?	☐	☒	☐	5.a. Measured an average of 5" of solids in the pump tank.
A. PUMP SYSTEMS:				
a. Required pumps present, operating, and cycling properly?	☐	☒	☐	5.A.a. Improper pump used for replacement.
b. High-water alarm present and operating properly?	☒	☐	☐	
c. Floats/pipe/valves/disconnects in good working condition?	☐	☒	☐	5.A.c. Install proper pump control float and set at correct level.
d. Control panel enclosure/components in good condition?	☒	☐	☐	
e. Elapsed time readings: _____ _____ _____ _____				
B. SIPHON SYSTEMS:				
a. No evidence of overflow or siphon leakage?	☐	☐	☒	
b. Siphon(s) appear to be working/alternating properly?	☐	☐	☒	
c. Bells and vents free of debris and in good condition?	☐	☐	☒	

6. GROUND ABSORPTION FIELDS:

a. No evidence of effluent surfacing/reaching surface waters?	☒	☐	☐	6. No problems detected with drain field.
b. Minimal ponding in subsurface trenches?	☒	☐	☐	
c. Surface water being effectively diverted away?	☒	☐	☐	
d. Diversions/ditches/swales/tiles drains properly maintained?	☒	☐	☐	
e. Line cover/vegetation adequate/maintained as needed?	☒	☐	☐	
f. Protected from traffic, destructive uses?	☒	☐	☐	
g. Distribution devices in good condition, working properly?	☒	☐	☐	
h. Repair area properly reserved, maintained?	☒	☐	☐	

A. LOW PRESSURE PIPE DRAIN FIELDS:

a. Turnups/cleanouts/valves intact and accessible?	☐	☐	☒
b. No effluent standing in lower laterals?	☐	☐	☒
c. Laterals free of excess solids, cleaned out as needed?	☐	☐	☒
d. Pressure head is properly adjusted?	☐	☐	☒

OVERALL CONDITION AND OPERATION OF SYSTEM:

No sewage observed on ground surface at the time of inspection.

Effluent pump has been replaced with an improper sump pump.

SUMMARY OF REPAIRS REQUIRED AT THIS TIME:

1. Install approved effluent pump and reconnect pump control float inside pump tank.
2. Contol float should be set to maintain a minimum of 12" of efflent in the pump tank at all times.
3. Properly wire pump in control panel to allow for manual operation of the pump.
4. Rework electrical wiring inside tank to remove all wiring splices.
5. Install a rope/chain on new pump to aid in pump removal.

***REPAIR WITHIN N/A DAYS.**

SYSTEM MAINTENANCE/IMPROVEMENTS REQUIRED:

*The MCHD recommends having the tanks (septic & dosing) pumped out every 3 to 5 years to remove excess solids.

1. Check for leaking toilet/(s) inside the house. Repair as needed.

DATE: 7/7/2005

SIGNED: _____ RSI AGENT

Division of Environmental Health

MECKLENBURG COUNTY
LAND USE AND ENVIRONMENTAL SERVICES
Payment Receipt

Receipt Information

Date:	06/24/05	**Amount:**	85.00
Receipt #:	35377	**Tendered:**	85.00
Check / Auth #:	CHECK 1944	**Returned:**	0.00
Received By:	WALKEVA		

Account Information

Account #: 200000
Contractor: BROOKS TIMOTHY
Attn:
Address: 1108 MEADOWBROOK LANE
Address:
City/State/Zip: CONCORD, NC 28027

Item	Description	Permit#	Quantity	Unit Price	Total Price
0743	Hmeownr Maint Inspec-Type IIIB FILE #6745A 704-573-9278		1	85.00	85.00

7/13/04

----------Outstanding Balances----------

Month-To-Date	Prior Month	30 Days	60 Days	90 Days	Balance

Mecklenburg County Public Health Laboratory

Environmental Health Section

249 Billingsley Road • Charlotte, North Carolina 28211

ATb

Microbiological Analyses

Owner, System or Establishment: Thomas Hildreth

Address: 15314 Millview Trace Ln

Charlotte Zip: 28227

Collected By: L. Thompson

Date Collected: 7-13-99 Time: 1:00 AM (PM)

Sample Source: Outside tap

Date Delvd. to Lab: 7-13-99 Time: 3:25 AM (PM)

Delivered By: LBT ☑ Received on Ice Initials LBT

Type of Sample

Potable Water

- ☑ Individual Well
- ☐ Non-Community
- ☐ Community
- ☐ City
- ☐ Other (specify)

Treatment ☐ chlorinated ☑ nonchlorinated

- ☑ Initial Sample
- ☐ Recheck (chlorinated)
- ☐ Recheck (nonchlorinated)
- ☐ Other (specify) _____

Nonpotable Water

- ☐ Surface
- ☐ Storm
- ☐ Other (specify) _____

Analysis Requested: ☑ Total Coliform ☐ Fecal Coliform ☐ Fecal Strep ☐ Enterococcus

☐ Sulfate Reducing Bacteria ☐ Pseudomonas aeruginosa

☐ Other (specify) _____

☐ Food Analysis (specify) _____

Comments: _____

Laboratory Analysis Report

Method: ✓ Membrane Filter _____ Colilert _____ Multiple Tube Fermentation

Total Coliform	Present /100 ml.	Non-Coliform	_____ /100 ml.
Fecal Coliform	Absent /100 ml.	Plate Count	_____ /gm. or ml.
Fecal Strep	_____ /100 ml.	Coliform Count	_____ /gm. or ml.
Enterococcus	_____ /100 ml.	*Pseudomonas aeruginosa*	_____ /100 ml.

Laboratory Comments:

Date Received: 7-13-99 Date Reported: 7-14-99

Received By: JW Analyst: JW Lab #: 720

Laboratory Identification #: 37518 DEHNR Division of Laboratory Services
#: 449 DEM

L 1.14 1/92
Rev. 10/96
4319

White - Lab Report Copy Yellow - Lab File copy

Mecklenburg County
Health Department

June 20, 1999

Thomas Hildreth
15314 Millview Trace Lane
Charlotte, NC 28227

Dear Mr. Hildreth:

During a recent investigation of the property located at 15314 Millview Trace Lane, Charlotte, North Carolina, a well water sample was collected. The laboratory analysis of the well water was reported to be positive for coliform bacteria. The presence of bacteria indicates a source of contamination. It is recommended that the well be chlorinated. The procedure for chlorination of a well is enclosed.

If you have any questions concerning this report, please contact me at 336-5568.

Sincerely,

Larry B. Thompson, Jr., R.S., Coordinator
Managed Systems Program
Individual Water and Wastewater Systems

Enclosure

N. C. Department of Environment and Natural Resources
Division of Environmental Health

INSPECTION OF ENGINEERED SUBSURFACE WASTEWATER SYSTEM

Mecklenburg — Health Department
6745 A — Permit/Project No.
Name of Establishment
15314 Millview Trace Lane — residence — 360gpd
Location — Type of Establishment — Design Flow
Thomas Hildreth 15314 Millview Trace Lane, Charlotte 28227
Owner/Agent — Address — Phone
N/A III b
Operator — Address — Phone
Remarks

	Yes	No	REMARKS
1. ESTABLISHMENT:			
Type, size, and sewage flow in accordance with permit?	☑	☐	
2. COLLECTION SYSTEM:			
No evidence of leaks into or out from sewer lines/manholes?	☐	☐	
Free of blockages/solids buildup in lines or manholes?	☐	☐	
3. TANKAGE (Grease Traps/Lift Stations/Septic/Dosing Tanks):			
Tank risers accessible and surface water diverted?	☑	☐	
Tanks and access manholes structurally sound, watertight?	☑	☐	
Sanitary tee(s) in good working condition?	☐	☐	
Tanks pumped, cleaned out as needed?	☐	☐	We recommend pumping septic tank at 3-5 year intervals
4. RAW SEWAGE LIFT STATION (if present):			
Required pumps present, operating, and cycling properly?	☐	☐	
High-water alarm present and operating properly?	☐	☐	
Floats/pipe/valves/disconnects in good working condition?	☐	☐	
Control panel enclosure/components in good condition?	☐	☐	
5. EFFLUENT DOSING SYSTEM:			
Effluent appears clear, free of excess solids?	☐	☐	
PUMP SYSTEMS:			
Required pumps present, operating, and cycling properly?	☑	☐	
High-water alarm present and operating properly?	☐	☑	Alarm is not working
Floats/pipe/valves/disconnects in good working condition?	☑	☐	
Control panel enclosure/components in good condition?	☑	☐	
Elapsed time readings: _____ _____ _____			
SIPHON SYSTEMS:			
No evidence of overflow or siphon leakage?	☐	☐	
Siphon(s) appear to be working/alternating properly?	☐	☐	
Bells and vents free of debris and in good condition?	☐	☐	
6. GROUND ABSORPTION FIELDS:			
No evidence of effluent surfacing/reaching surface waters?	☑	☐	
Minimal ponding in subsurface trenches?	☑	☐	
Surface water being effectively diverted away?	☑	☐	
Diversions/ditches/swales/tile drains properly maintained?	☑	☐	
Line cover/vegetation adequate/maintained as needed?	☑	☐	
Protected from traffic, destructive uses?	☑	☐	
Distribution devices in good condition, working properly?	☑	☐	
Repair area properly reserved, maintained?	☑	☐	
LOW-PRESSURE PIPE DRAIN FIELDS:			
Turnups/cleanouts/valves intact and accessible?	☐	☐	
No effluent standing in lower laterals?	☐	☐	
Laterals free of excess solids, cleaned out as needed?	☐	☐	
Pressure head is properly adjusted?	☐	☐	

OVERALL CONDITION AND OPERATION OF SYSTEM: Overall - system looks good

SUMMARY OF IMPROVEMENTS NEEDED:

Improvement	Repair Within (Days)
Repair High Water Alarm	45

DATE: 7-15-99 SIGNED: Larry B. Thompson, J. L.S. AGENT
Division of Environmental Health

DENR 3702 (Revised 3/98)
On-Site Wastewater Section (Review 12/98)

– over –

SUMMARY OF IMPROVEMENTS NEEDED (cont.)

Improvement	Repair Within (Days)

INTENT TO SUSPEND OR REVOKE PERMIT

This is to notify you of intent to suspend/revoke your operation permit/certificate of completion 60 days from this date for the following
(circle one) *(circle one)*

violations: _____
[Law or Rule(s)]

If suspended, the operation permit or certificate of completion remains suspended until violations are corrected. A hearing will be held prior to suspension or revocation if you file a petition for a hearing with the Office of Administrative Hearings, P. O. Drawer 27447, Raleigh, NC 27611-7447, in writing within the number of days specified above of your intent to attend the hearing. If you do not petition the Office of Administrative Hearings, the operation permit or certificate of completion will be suspended or revoked.

IMMEDIATE SUSPENSION OR REVOCATION OF PERMIT

This is to notify you of immediate suspension/revocation of your operation permit/certificate of completion for the following violations:
(circle one) *(circle one)*

_____
[Law or Rule(s)]

If suspended, the permit or certificate remains suspended until the violations are corrected. You will be notified of the day and location of a hearing on this suspension or revocation by a hearing officer from the Office of Administrative Hearings.

This the _____ day of _____, 19 _____.

_____ Agent
DIVISION OF ENVIRONMENTAL HEALTH

INSTRUCTIONS

Purpose: Article 11 of Chapter 130A requires the Commission for Health Services to adopt rules governing the design, construction, and operation of on-site wastewater systems. 15A NCAC 18A .1937 specifies that the local health department shall determine whether systems with an Operation Permit are operating properly at a frequency specified in Rule .1961, Table V(a), and that systems which exceed 3,000 gallons per day and other systems which are required to be designed by a professional engineer shall be reinspected annually. This form is developed to be used in making inspections of engineered subsurface wastewater systems.

Preparation: Local environmental health specialists shall complete the form every time they conduct an inspection. Prepare an original and two copies for:

1. Original to be left with the responsible person.
2. Copy for the local health department.
3. Copy for the On-Site Wastewater Section, Division of Environmental Health.

In the event the permit is suspended or revoked, complete the portion above.

Disposition: This form may be destroyed in accordance with Standard 7, Inspection Records, of the *Records Disposition Schedule* published by the N.C. Division of Archives and History.

Additional forms may be ordered from: On-Site Wastewater Section
Division of Environmental Health
P. O. Box 29594
Raleigh, NC 27626-0594
(Courier 52-01-00)

MAINTENANCE INSPECTION STATEMENT

MECKLENBURG COUNTY HEALTH DEPARTMENT

PAST DUE NOTICE

Thomas & Kimberly Hildreth
15314 Millview Trace Lane
Charlotte, NC 28227

Please Make Check Payable To:

Mecklenburg County Health Department
700 N. Tryon Street, Ste 211
Charlotte, NC 28202

Note: THIS COMPLETED FORM MUST ACCOMPANY PAYMENT!

DESCRIPTION OF PROPERTY

Name	Site Address	Tax Parcel	File Number	# of Bedrooms	System Type
Thomas & Kimberly Hildreth	15314 Millview Trace Ln	139-152-41	6745A	3	IIIB

Total Amount Due: $85.00

Please use the space below, to make any corrections to property information.

Name _____

Site Address _____

_____

# of Bedrooms _____

RECEIVED 2-16-99

2/9/99

BILL INFORMATION

Billing Date	Payment Due Date
2/16/99	3/16/99 *PAST DUE*

7-13-99 SC
OSV - H2O 1:00pm

Direct Questions Concerning This Bill To ..... (704) 336-5102

☑ *Please check if you have a well.*

Make Check Payable To Mecklenburg County Health Department
Your Canceled Check Is Your Receipt

DO NOT SEND CASH

MAINTENANCE INSPECTION STATEMENT

MECKLENBURG COUNTY HEALTH DEPARTMENT

PAST DUE NOTICE

Thomas & Kimberly Hildreth
15314 Millview Trace Lane
Charlotte, NC 28227

Please Make Check Payable To:

Mecklenburg County Health Department
700 N. Tryon Street, Ste 211
Charlotte, NC 28202

Note: THIS COMPLETED FORM MUST ACCOMPANY PAYMENT!

DESCRIPTION OF PROPERTY

Name	Site Address	Tax Parcel	File Number	# of Bedrooms	System Type
Thomas & Kimberly Hildreth	15314 Millview Trace Ln	139-152-41	6745A	3	IIIB

Total Amount Due: $85.00

Please use the space below, to make any corrections to property information.

Name _____

Site Address _____

_____

# of Bedrooms _____

BILL INFORMATION

Billing Date	Payment Due Date
2/16/99	3/16/99 *PAST DUE*

Direct Questions Concerning This Bill To ..... (704) 336-5102

☐ *Please check if you have a well.*

Make Check Payable To Mecklenburg County Health Department
Your Canceled Check Is Your Receipt

DO NOT SEND CASH

Mecklenburg County
Health Department

February 16, 1999

Thomas Gregory and Kimberly Dawn Hildreth
15314 Millview Trace Lane
Charlotte, NC 28227

Dear Mr. and Mrs. Hildreth:

This letter is being sent to all home/business owners in Mecklenburg County with septic tank systems that utilize pumps. In 1992 the North Carolina Administrative Code governing septic tank systems was amended to require routine maintenance and inspection of certain septic tank systems. Research conducted on septic tank systems has shown that properly maintained systems perform better and protect the home/business owner's investment. These State rule changes required local health departments to perform additional inspections without additional resources. During the 1998-99 budget hearings, the Mecklenburg County Board of County Commissioners (BOCC) approved user fees to offset costs and to allow the local health department to comply with mandatory enforcement requirements in the State regulations.

Since you have a pump system, these new rules and fee requirements affect you. The fee is $85.00 and is due upon receipt of this notice. We will visit your property and make assessments and recommendations for the continued efficient operation of your septic tank system. In addition, if you have a well, a bacterial sample will be collected to help assess the quality of your water supply source. The process, including fee assessment, will be repeated every five (5) years. The fee amount may change in the future.

We are excited about the interest and support demonstrated by the BOCC. Past performance in this area was more enforcement oriented rather than supportive. One of our goals is to establish our department as a resource to you to aid and assist you with this and related public health concerns. The inspection program and the water analysis are important to the health of you and your family. This is a very important initiative intended to protect the public's health while improving and preserving our groundwater resources.

Your prompt fee payment will activate our inspection process. Your comments and questions regarding this matter are encouraged and welcomed.

Sincerely,

Larry B. Thompson, Jr., R.S.

Larry B. Thompson, Jr., R.S.
Environmental Health Specialist
Individual Water and Wastewater Systems

Enclosure

cc: Fiscal Services Manager, HMHCS

6745A 400 ☑ INDIVIDUAL WATER AND WASTEWATER SYSTEMS PROGRAM
APPLICATION FOR SERVICES

Pd. # 200 6/24/94 # 1223 CRT

Mecklenburg County Health Dept.
Environmental Health Division
c/o Hal Marshall Ctr., Suite 211
700 N. Tryon St.
Charlotte, NC 28202

(704)336-5102

PERSON FILING APPLICATION:
NAME: PEREZ (last) MICHAEL (first) E (mi)
ADDRESS: 7808-103 CAUSEWAY DR. PHONE: (704) 536-7879
CITY: CHARLOTTE STATE: N.C. ZIPCODE: 28227

Date:

PROPERTY INFORMATION (FROM ENGINEERING FORM):
TAX/PARCEL NUMBER: 139-152-41
STREET ADDRESS: 15314 Millview Trace LN
ZONING:

PROPERTY OWNER:
NAME: SAME (last) (first) (mi)
ADDRESS: PHONE: (___) ___
CITY: STATE: ZIPCODE:

SUBDIVISION OR MOBILE HOME PARK NAME:

Township (check one):
[] 0 Mecklenburg County [] 2 Davidson [] 4 Pineville [] 6 Huntersville
[] 1 Charlotte [] 3 Cornelius [] 5 Matthews [] 7 Mint Hill

TYPE APPLICATION (check one):

LOT NUMBER: LOT SIZE (in acres):

[] SOIL TEST - INDIVIDUAL LOT (D)
[X] NEW CONSTRUCTION ON VACANT LOT - 4 BEDROOMS OR LESS (N)
[] EXCHANGE MOBILE HOME - SAME # BEDROOMS (Y)
[] ADDITION - INCREASE ROOMS/OCCUPANCY/MOBILE HOME SIZE (A or M)
[] COMMERCIAL OR INDUSTRIAL (N)
[] SOIL TEST DEVELOPMENT (P)
[] ADDITION - GARAGE OR RENOVATION/NO MAJOR CHANGES (X)
[] MODIFIED /ALTERNATIVE/ OR RESIDENCE > 4 BEDROOMS (Z)
[] REPAIR TO SYSTEM (R)

RESIDENTIAL PROPERTY (Type Building, check one):
[X] SINGLE MOBILE HOME (S) [X] HOUSE (H) [] MULTIPLE FAMILY (U)
[] DOUBLE WIDE (D) [] MODULAR HOME (M) [] OTHER _____ (O)

NUMBER BEDROOMS: 3 NUMBER OCCUPANTS: 3

SYSTEM CLASSIFICATION:

COMMERCIAL/INDUSTRIAL PROPERTY:
Type Business _____ # Employees ___ Per Shift ___ ___ ___
Industrial Wastes (Y/N) ___
Underground Storage Tanks On Property (Y/N) ___ Type _____

WATER SUPPLY (check one):
[] Community (C) [] Shared Well (S)
[] Municipal (M) [] Other 'spring' (O)
[X] Private Well (P)

FUTURE ADDITIONS - ALL PLANNED ADDITIONS MUST BE ENTERED (check all that apply):
[] Swimming Pool [] Jacuzzi [] Stable/Barn [] Workshop [] None
[] Garage [] Storage Building [] Deck/Patio [] Bedrooms [] Other

The undersigned, owner, or legal agent for the owner, of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY HEALTH DEPARTMENT to enter onto the property for the purpose of processing this request.

Signed: Michael E. Perez Date: JUNE 24, 1994

NOTICE:

The undersigned, an authorized agent of the MECKLENBURG COUNTY HEALTH DEPARTMENT, certifies that the Department has approved the Request for the Job Location contained in this document. This approval is granted in accordance with the provisions of Laws And Rules For Sanitary Sewage Collection, Treatment And Disposal in effect at the time of issuance of the permit and is subject to the following provisions:

...No work shall be conducted on the septic tank system until an installation, Construction, Alteration and/or Repair approval is granted by this Department.

...This permit is not transferable.

... left station required

[X] IMPROVEMENT PERMIT - VALID 60 MONTHS FROM ISSUANCE
[] MOBILE HOME EXCHANGE APPROVAL - VALID 6 MONTHS FROM ISSUANCE
[] ADDITION/RENOVATION APPROVAL - VALID 1 YEAR FROM ISSUANCE

Susan Gatewood 7/5/94
Environmentalist Date

J. Walker for A. Powell 7/20/94
Director or Authorized Section Head Date

WATER : 122791

CERTIFICATE OF COMPLETION/OPERATION PERMIT

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

FILE: 6745 A DATE: 1/12/95

TC: 139 152 41 ☐ L ☐ CRT

SERIAL № 14371

Name of Owner Michael Perez Juris.:

Address of Property 15314 Millview Trace Ln

Inspection Data:

Tank Material PCC

Total Length of Drainfield 400'

Number of Lines 3 @ 133'

Cover Depth 12" - 16"

Water Supply Source well (existing)

Distance to Water Source 80'

Excavation Inspected 1/12/95

Tank(s) Inspected 1/12/95

Wash Line Inspected -

High Water Alarm Inspected 1/12/95

PLOT

Design: 1995, 1500ST, 1000PT, PI, 1200SFT, 12" stone cec.l CTR# N. Osborne

The undersigned has inspected the Septic Tank System described above, and certifies it has been

☒ installed or constructed ☐ altered or repaired

☒ in accordance with the permit issued ☐ as detailed in the plot above

and meets the provisions of 10 NCAC 10A .1900, "Laws And Rules For Sanitary Sewage Collection, Treatment, And Disposal" in effect on the date of issuance of the permit. The issuance of this

☐ Certificate of Completion ☒ Operation Permit

does not in any way guarantee that the system will operate properly or relieve any person now or hereafter owning, controlling, or using such system from any liability resulting from the failure of the system to operate properly. This document is issued subject to those restrictions and conditions shown on the permit(s) and the provisions of 10 NCAC 10A .1900 in addition to those listed below under "COMMENTS." This document shall be null and void if any information contained in the application is untrue or if any additions are made to the property which would increase the requirements for said system.

COMMENTS: Septic system designed for 3 bedroom residence. Type ~~III~~ IIIb

HB for S Daniel

Thilo S. Walker R.S.
Environmentalist

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

INSTALLATION, CONSTRUCTION, ALTERATION, AND/OR REPAIR APPROVAL


HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
700 NORTH TRYON ST., SUITE 211
CHARLOTTE, NC 28202
PHONE (704) 336-5102

FILE: 6745A DATE: 1/9/95

TC: 139 152 41 ☐ L

SERIAL Nº 16023

Permission is hereby given to ✓ Install or Construct, _____ Alter or Repair the individual septic tank wastewater treatment system with subsurface, soil absorption, effluent discharge as specified herein at the described location. This permit is granted based upon the information supplied in the application dated 7/7/94. All work shall be completed on or before 2/9/95, after which date this permit shall be null and void. The system shall meet all of the construction requirements of 15A NCAC 18A. 1900 which are in effect on the date of the granting of this permit. A Certificate of Completion or an Operation Permit must be obtained from the Mecklenburg County Health Department before any system can be covered up or placed into service. The issuance of this permit does not in any way guarantee that the system anticipated to be constructed will operate properly, or relieve any person now or hereafter owning, controlling or using such system from any liability resulting from the failure of the system to operate properly.



PLOT OF SYSTEM

Liquid Capacity of Septic Tank 1500 gallons

Liquid Capacity of Dosing Tank 1000 gallons

Tank Construction PCC

Trench Depth ≤3'

Absorption and/or Nitrification Lines:

Trench Width 3 feet

Trench Walls Scored and Porous –

Total Line Length 400' feet

Number of Lines 3 (133')

Depth of Stone 12 inches

Distance from House 5 feet

Distance from Property Line 10 feet

Distance from Well ≥ 50' feet

NOTICE: This system shall not be installed while soils are in a wet condition.

NAME OF OWNER Michael Perez

LOCATION OF PROPERTY 15314 Milview Trace Ln

Comments: 1500ST, 1000DT, 3 lines x 133'long x 3'wd x 12"stone
Keep septic system ≥50' from any wells / Keep septic lines
on contour of land

Phelo A. Walker R.S.
Environmental Health Specialist

COPY


PROPOSED PLOT PLAN

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
700 NORTH TRYON STREET
CHARLOTTE, NC 28202
PHONE (704) 336-5102

FILE: 6745A

TC: 139-152-41

Draw in and name all roads adjoining the property. Draw in and accurately dimension the lot concerned. Accurately indicate property boundaries, proposed and/or existing structures and driveways, underground utilities, and wells and springs within 100 feet of the proposed building or drainfield.



APPROVAL DATE _____

White - Health Department's Copy Canary - Environmentalist's Copy Pink - Owner's Copy

DATE 6/21/94

TO: CHARLOTTE-MECKLENBURG BUILDING STANDARDS
PERMIT ISSUING SECTION

FROM: MECKLENBURG COUNTY ENGINEERING

JURISDICTION Mick

139-152-41
PARCEL NUMBER

15314 Millwin Trace Ln
ASSIGNED STREET ADDRESS (ADDRESS OF RECORD)

Lot 2
EXISTING STREET ADDRESS (IF DIFFERENT FROM ASSIGNED)

Connell Mill
PROJECT NAME (IF APPLICABLE)

THE ABOVE DESCRIBED LOCATION HAS BEEN CHECKED CONCERNING:

1. SUBDIVISION REGULATIONS	APPROVED	NOT APPROVED
2. FLOODWAY REGULATIONS	APPROVED	NOT APPROVED
3. WATERSHED PROTECTION	APPROVED	NOT APPROVED
4. COMMERCIAL DRAINAGE PLAN	APPROVED	NOT APPROVED
5. PUBLIC UTILITY EASEMENT	PRESENT	NOT PRESENT
6. PROPERTY FRONTS ON THOROUGHFARE	YES	NO
7. DRIVEWAY PERMIT REQUIRED	YES	NO
8. DOES PROJECT CONFLICT WITH ROAD PROJECT?	YES	NO

REMARKS: S. Alone a Deck

NOTE: THIS FORM MUST BE TURNED IN AT THE CASHIERS OFFICE WHEN PAYING PERMIT FEE. CERTIFICATE OF OCCUPANCY WILL NOT BE GRANTED UNTIL TRANSPORTATION DIVISION GRANTS FINAL APPROVAL ON DRIVEWAY(S).

ALL OTHER FORMS OBSOLETE

☐ NEW ADDRESS

SIGNED: [signature]

REVISED 1/91


PROPOSED PLOT PLAN

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
700 NORTH TRYON STREET
CHARLOTTE, NC 28202
PHONE (704) 336-5102

FILE: 6745A

TC: 139-152-41

Draw in and name all roads adjoining the property. Draw in and accurately dimension the lot concerned. Accurately indicate property boundaries, proposed and/or existing structures and driveways, underground utilities, and wells and springs within 100 feet of the proposed building or drainfield.



3 bedroom design

1500 g. septic tank
1000 g. pump tank
1200 sq ft drainfield
Supply line may be located at opposite end of drainfield from as shown in drawing.
Keep well min 100' from any part of septic tank system and it's repair area.
Pump, pump controls & alarm to be installed according to current N.C. State Regulations.
Install large box such as waster type box to then feed into equal distribution box.

Melodie B. Reny
property owner sign + date
7/15/94

APPROVAL DATE 7-7-94

White - Health Department's Copy Canary - Environmentalist's Copy Pink - Owner's Copy

Mecklenburg County
Health Department

June 1st, 1990

Connell Mill Partners
3933 Bon Rea Drive
Charlotte, NC 28226

RE: Property located at Cabarrus road
FILE: 6745A
PARCEL: 13915103

Dear Sir:

At your request, a field investigation was conducted on the property designated above for the purpose of determining site suitability for the installation of a ground absorption sewage disposal system. The property was found to contain a limited area of soils which were classified as PROVISIONALLY SUITABLE for such an installation. A copy of the Site Evaluation Report (Serial Number 17929) is enclosed for your information.

Should you desire to file for permission to install a ground absorption sewage disposal system, please submit an Application For An Improvement Permit with an ACCURATELY dimensioned plot plan detailing the location of current and/or proposed buildings, wells and sewage disposal systems to this office. The plan will be reviewed and if it is found that the area of provisionally suitable soils is adequate for the proposed construction, an Improvement Permit will be issued by this Department.

If I may be of assistance, please do not hesitate to contact me.

Very truly yours,

Gene Vaughan, R.S., Supervisor
On Premises Waste Disposal & Water Supply

Enclosure

Environmental Health Division
1200 Blythe Boulevard • Charlotte, North Carolina 28203 • (704) 376-4603

MECKLENBURG COUNTY HEALTH DEPARTMENT
SITE EVALUATION REPORT
SERIAL NUMBER 17929

File: 6745A Action 1

Parcel: P0139-151-03 PC

Location: Cabarrus Road

Subdivision:


Lot: 2 Block: 2 Acres: .81

Owner: Connell Mill Partners
Address: 3933 Bon Rea Drive
Charlotte, NC 28226

Comments: 100% Repair

Described by: William B. Marlin

Date: 6-1-90



***** EVALUATION KEY *****

S = Suitable U = Unsuitable
PS = Provisionally Suitable
The "Area Classification" below indicates the suitability of areas in the diagram.

FACTORS	AREA 1	AREA 2	AREA 3	AREA 4	AREA 5	AREA 6
Topography	(S) PS U 2-6%	S PS (U) Ditch	S PS U	S PS U	S PS U	S PS U
Texture	S (PS) U clay	S PS U —	S PS U	S PS U	S PS U	S PS U
Structure	S (PS) U Blocky	S PS U —	S PS U	S PS U	S PS U	S PS U
Drainage	S (PS) U 736" Water	S PS U —	S PS U	S PS U	S PS U	S PS U
Depth	S (PS) U 736"	S PS U —	S PS U	S PS U	S PS U	S PS U
Restrictive Horizons	S (PS) U 736"	S PS U —	S PS U	S PS U	S PS U	S PS U
Available Space	S (PS) U	S PS U —	S PS U	S PS U	S PS U	S PS U
Other (specify)	S PS U	S PS U	S PS U	S PS U	S PS U	S PS U
Soil Group/Series	IV Cecil-Lloyd	Ditch				
Area Classification	S (PS) U	S PS (U)	S PS U	S PS U	S PS U	S PS U

APPLICATION FOR SOIL INVESTIGATION

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

(OFFICE USE ONLY)

FILE: 6745-A

TC: _____

☐ PC ☐ REPT

JOB LOCATION

① ADDRESS: Cabarrus Road

② SUBDIVISION: Connell Mill ③ LOT: 2 ④ BLOCK: 2

⑤ PARCEL REFERENCE: BOOK NO.: 139 PAGE NO.: 151 PARCEL NO.: 03

⑥ DEED REFERENCE: BOOK NO.: _____ PAGE NO.: _____

OWNER


⑦ NAME: Connell Mill Partners
(FIRST) (MIDDLE) (LAST)

⑧ MAILING ADDRESS: 5933 Bonna Ridge Drive

⑨ CITY: Charlotte ⑩ STATE: NC ⑪ ZIP: 28226

⑫ PHONE: (WORK) 541-2580 (HOME) 542-0126

⑬ Accurately diagram and dimension lot.



Shallow ditch

49
50
91
190

⑭ The undersigned, owner of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY HEALTH DEPARTMENT to enter onto the property for the purpose of processing this request.

Signed: Vera E Connell

Date: May 16, 1990

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

WHITE - HEALTH DEPARTMENT'S COPY • CANARY - ENVIRONMENTALIST'S COPY • PINK - OWNER'S COPY

APPLICATION FOR SOIL INVESTIGATION

HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
1200 BLYTHE BOULEVARD
CHARLOTTE, NC 28203
PHONE (704) 376-4603

(OFFICE USE ONLY)

FILE: 6745-A

TC: _____

☐ PC ☐ REPT

JOB LOCATION

① ADDRESS: Cabarrus Road

② SUBDIVISION: Connell Mill ③ LOT: 2 ④ BLOCK: 2

⑤ PARCEL REFERENCE: BOOK NO.: 139 PAGE NO.: 151 PARCEL NO.: 03

⑥ DEED REFERENCE: BOOK NO.: _____ PAGE NO.: _____

OWNER


⑦ NAME: Connell Mill Partners
(FIRST) (MIDDLE) (LAST)

⑧ MAILING ADDRESS: 3933 Ben Rea Drive

⑨ CITY: Charlotte, ⑩ STATE: NC ⑪ ZIP: 28226

⑫ PHONE: (WORK) 541-2580 (HOME) 542-0126

⑬ Accurately diagram and dimension lot.



⑭ The undersigned, owner of the property described above as the "JOB LOCATION" has read the foregoing application, acknowledges that the contents of same are true, and authorizes agents of the MECKLENBURG COUNTY HEALTH DEPARTMENT to enter onto the property for the purpose of processing this request.

Signed: Dana E Connelly

Date: May 16, 1990

Mecklenburg County services are available without regard to ethnic origin, sex, or disability.

WHITE - HEALTH DEPARTMENT'S COPY • CANARY - ENVIRONMENTALIST'S COPY • PINK - OWNER'S COPY

MECKLENBURG COUNTY HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION

CHARGE SLIP

Date: 5-16-90

Name/Company: ~~George P. Lassiter & Associates~~
Vance E. & Nina E. Sorrenberg

Sanitation _____

Vector Control _____

O.P.W.D. ✓

Service: S/T - 1 Ac each
Connell Mill Subdivision

MECK. HEALTH DEPARTMENT
ENVIRONMENTAL HEALTH DIVISION
PAID
MAY 16 1990

Lots # 6744A – 6760A
all off Cabarrus Road

Fee: $ 680.00 CK# 0922 11680

NOTICE:

A processing fee of $15.00 will be charged for all returned checks in accordance with N.C. General Statute 25-3-512.

Jackie Abernethy
Completed by

Collected by